

## Maintenance Log: MLOG-013

**Machine:** Conveyor C301

**Date:** 2026-06-10

**Engineer:** Karthik Raj

### Issue: Conveyor jam

**Symptoms:** Operator reported abnormal behavior during shift.

**Root Cause:** Wear and tear on internal components.

**Corrective Action:** Replaced affected parts and recalibrated.

**Downtime:** 3 hours

**Remarks:** Resolved. References SOP-005 and Machine Manual.