

Maintenance Log: MLOG-016

Machine: Heat Exchanger HX01

Date: 2026-06-24

Engineer: Karthik Raj

Issue: Generator shutdown

Symptoms: Operator reported abnormal behavior during shift.

Root Cause: Wear and tear on internal components.

Corrective Action: Replaced affected parts and recalibrated.

Downtime: 8 hours

Remarks: Resolved. References SOP-005 and Machine Manual.