

Incident Report: IR-004

Machine: Motor M101

Date: 2026-06-21

Description: Safety limit triggered causing automatic shutdown.

Timeline: Incident occurred at 14:30. Response initiated at 14:35.

Root Cause: Conveyor jam

Impact: Production halted temporarily.

Corrective Action: Re-engaged safety protocols and cleared fault.

Preventive Action: Update inspection checklist.

Status: Closed