

Incident Report: IR-019

Machine: Conveyor C301

Date: 2026-06-07

Description: Safety limit triggered causing automatic shutdown.

Timeline: Incident occurred at 14:30. Response initiated at 14:35.

Root Cause: Bearing failure

Impact: Production halted temporarily.

Corrective Action: Re-engaged safety protocols and cleared fault.

Preventive Action: Update inspection checklist.

Status: Closed