
carbon leaves the lattice as SiC
precipitation more favourable with Ge
carbon prefers Si-rich shells
SiC attracts Ge in the first shell
covering no better than random
one factor at a time worse than random
+0.94 → +1.6 eV
+0.24 → +0.35 eV
+0.21 → +0.24 eV
+0.10 → −0.00042 eV
+0.032 → +0.032 (ln κ)
+0.022 → +0.021 (ln κ)
MACE-MP-0
MACE-MPA-0
0
1
2
3
4
5
margin to the deciding threshold, in units of the plausible shift