LINEAR SYSTEMS CONTROL

Solutions to Problems

Problem 2.6

a. For the volume flows one has:

$$q_{1} = A_{c}\dot{x} + \frac{V_{1}}{\beta}\dot{p}_{1} + C_{l}(p_{1} - p_{2})$$

$$q_{2} = A_{c}\dot{x} - \frac{V_{1}}{\beta}\dot{p}_{2} + C_{l}(p_{1} - p_{2})$$

$$\Rightarrow \begin{array}{c} \dot{p}_1 = \frac{\beta}{V_1} (q_1 - A_c \dot{x} - C_l (p_1 - p_2)) \\ \\ \dot{p}_2 = \frac{\beta}{V_2} (-q_2 + A_c \dot{x} + C_l (p_1 - p_2)) \end{array} \right\}.$$

The flow are controlled by the input relation:

$$q_1 = q_2 = ku.$$

Newton's second law applied to M gives:

$$\begin{split} M\ddot{x} &= f + A_c(p_1 - p_2) - C_f \ \dot{x} \\ \Rightarrow \dot{x} &= \frac{1}{M} (f + A_c(p_1 - p_2) - C_f \ \dot{x}). \end{split}$$

b. The state vector for the system is (see the block diagram below):


$$\mathbf{x} = \begin{bmatrix} x \\ \dot{x} \\ p_1 \\ p_2 \end{bmatrix} = \begin{bmatrix} x \\ v \\ p_1 \\ p_2 \end{bmatrix} = \begin{bmatrix} x_1 \\ x_2 \\ x_3 \\ x_4 \end{bmatrix}$$

LINEAR SYSTEMS CONTROL

Solutions to Problems

Problem 2.6 (continued)

Blockdiagram:



The state equations for the system can be written in two different ways:

$$\begin{split} \dot{x} &= v & \dot{x}_1 &= x_2 \\ \dot{v} &= \frac{1}{M} (-C_f v + A_c (p_1 - p_2) + f) & \dot{x}_2 &= \frac{1}{M} (-C_f x_2 + A_c (x_3 - x_4) + f) \\ \dot{p}_1 &= \frac{\beta}{V_1} (ku - A_c v - C_l (p_1 - p_2)) & \text{or} \quad \dot{x}_3 &= \frac{\beta}{V_1} (ku - A_c x_2 - C_l (x_3 - x_4)) \\ \dot{p}_2 &= \frac{\beta}{V_2} (-ku + A_c v + C_l (p_1 - p_2)) & \dot{x}_4 &= \frac{\beta}{V_2} (-ku + A_c x_2 + C_l (x_3 - x_4)) \end{split}$$

This leads to:

LINEAR SYSTEMS CONTROL

Solutions to Problems

Problem 2.6 (continued)

$$\Rightarrow \mathbf{A} = \begin{bmatrix} 0 & 1 & 0 & 0 \\ 0 & -\frac{C_f}{M} & \frac{A_c}{M} & -\frac{A_c}{M} \\ 0 & -\frac{A_c\beta}{V_1} & -\frac{C_l\beta}{V_1} & \frac{C_l\beta}{V_1} \\ 0 & \frac{A_c\beta}{V_2} & \frac{C_l\beta}{V_2} & -\frac{C_l\beta}{V_2} \end{bmatrix}, \quad \mathbf{B} = \begin{bmatrix} 0 \\ 0 \\ \frac{k\beta}{V_1} \\ \frac{k\beta}{V_2} \end{bmatrix}$$

$$\mathbf{B}_{v} = \begin{bmatrix} 0 \\ \frac{1}{M} \\ 0 \\ 0 \end{bmatrix}, \quad \mathbf{C} = \begin{bmatrix} 1 & 0 & 0 & 0 \end{bmatrix}$$