

## **Motors Pins:**

1	2	3	4	5	6	7	8
GPIO 12	GPIO 14	GPIO 27	GPIO 26	GPIO 25	GPIO 33	GPIO 32	GPIO 4

Cam servo pin – GPIO 13

Leds Port - GPIO 23

## Baro I2c pins:

GPIO 22 (scl)

GPIO 21 (Sda)

GND(by gpio21)

3.3V

## Ftdi (PC-esp comm):

Vin (5v from pc)

GPIO 17 – tx

GPIO 16 - rx

GND