SIMPLWINDUS QUICK REFERENCE CARD

DISPLAY MANIPULATION

APPLICATION Closes Detail ViewCTRL+F4 Closes SIMPL WindowsALT+F4 Display context-sensitive helpF1 Hide/view both Symbol Library and Program ViewALT+B Hide/view Program ViewALT+P Hide/view Symbol LibraryALT+Y Refresh windowF5 **DIALOG BOXES** Displays startup dialog boxCTRL+T Displays Zoom Percentage dialog boxALT+Z NODE Collapses current nodeCTRL+SHIFT+E Expands current nodeCTRL+E Display next paneF8 Display previous paneSHIFT+F8

PROGRAM

Create new programCTR	L+N
Create new user macro	_+N
Opens program or macroCTR	L+C
Saves program or macroCTR	L+S
Prints programCTR	L+F
Opens Port Settings dialog boxAL	T+0
2,2,1,1	

SIGNAL

NAME Add a new signal name FNT FNT
Add a new signal nameENT, ENT
Add a signal suffix from promptALT+6
Add the signal suffix
set in PreferencesALT1 thru ALT5
Add inputs and/or outputs
one at a timeALT+=
Add inputs or outputs in
specified multiples
Assign sequential names to highlighted
signals (based on first signal)SHIFT+F4
Assign sequential names to highlighted
signals (based on last signal)F4

NAME continued

Copy selected input signal to its output
(or vice-versa)F6
Cursor remains with current signal after
signal assignmentCTRL+ENT
Delete a signalDEL
Delete a signal and highlight the input or
output below itCTRL+DEL
Removes inputs and/or outputs
one at a timeALT+

one at a time minimum transfer at the second
GETTING AROUND Moves cursor between inputs and outputs (in a top to bottom, left to right direction)
Moves cursor (in any direction)ARROW KEYS Select a variable range of inputs or
outputsSHIFT+CLICK
Select inputs or outputs in a downward direction (from present cursor position to last input or output)SHIFT+END
Select inputs or outputs in an upward direction (from present cursor position to first input or output)SHIFT+HOME
Signal routing (show)F2
Signal routing (highlight)F3

SYMBOL

Edit symbol comment	.CTRL+R
Find symbol	.CTRL+F
Find next symbol	F3
Move symbol or enter a new symbol placing it inside a subsystem	
SHI	
Remove a symbol	DEL
Resize a symbol (in Detail View)	F7

GENERAL EDIT

	ESC
Copy	CTRL+C
Cut	CTRL+X
Paste	CTRL+\
Undo	CTRL+Z

