
How to Change SpiRely to High Resolution Mode

- Connect SpiRely to computer through TTL-USB tool.
 Red to VCC, Black to GND, Green to Rx, and White to Tx.
- Open YD14. Select and open COM port.
 Download at https://files.secureserver.net/0sSvU5kVOWASIH



3. Click on the tab of Ultrasonic Meter and click on Calibrate Total to go to High Resolution mode.

