


2.7 System Flow Chart - ROS2 Robotic Arm Harvesting System
Overall process integrating inputs, processing, outputs, and feedback loops



Data flow summary:
1. Input: camera detection or manual target point.
2. Processing: YOLO tracking, target selection, inverse kinematics.
3. Output: joint angles and STM32 motor commands.
4. Feedback: UI status, detection count, reachability warnings, repeated loop.