
## Valentin Taifun 17E Motorglider



The 17 meter Taifun motorglider is one of the few that have a fully retractable landing gear. This sleek ship has a Limbach L2400EB 90 hp 4-stroke engine with an infinitely variable pitch Muehlbaur propeller. It has a U.S. Standard Airworthiness Type Certificate. Current engine TBO is 450 hrs. Fiberglass/foam sandwich construction is used throughout. The wings are foldable allowing the craft to be stowed in a 32' X 11' space. Wing area is 189.4 sq. ft. with a max wing loading of 9.5 lbs/sq. ft. at 1,874 lbs. Max. T.O. weight. Empty weight is 1,345 lbs. Fuel capacity is 23.8 gallons (143 lbs). Range is 700+mi. at 127mph cruise. Takeoff distance is 754' at S.L./Standard conditions. Rate of climb is over 600 fpm. Best glide ratio is 30.1. Hydraulic actuated disc brakes are standard and the nose wheel is steerable. Flaps and ailerons are interconnected at -8, 0, +8 and +15 degree positions. The landing flap position of +30 degrees returns the ailerons to zero degrees. The instrument panel is ample in size for full IFR instrumentation. Used cost of a Taifun is in the vicinity of \$100,000.

# Self-Launching Sailplane Pilot's Assn. NEWSLETTER

### March ~ April 1995

Published Bi-Monthly by SLSPA, Inc • Stan Nelson, President • Bruce Templeton, Vice President • Issue #43 Vol. VII

#### New officers Selected at 1995 SSA Convention

At the SLSPA Membership and Board of Director's Meeting on 2 March, 1995 several organizational changes were approved. Please note that these new procedures affect all existing and new members.

President ...... Stan Nelson

Checks for memberships, donations and publications should be made out to SLSPA, Inc. and sent as required to either the Membership Chairman (memberships and donations) or Newsletter Editor for publications or For Sale ads.

Addresses as follows:

Stan Nelson, President SLSPA, Inc.

P.O. Box 254245 Patrick AFB, FL 32925

407-254-1241

Brian G. Utley, Membership Chairman/SLSPA, Inc.

1930 SW 8th St.

Boca Raton, FL 33486

407-750-6876

Pete Williams, SLSPA Newsletter/Publications

1033 Dresslerville Rd.

Gardnerville, NV 89410

702-265-3877

# Time to Renew Your Membership for 95-96!

If this newsletter (Mar/April 95) has a *red* slip in it, this is your *last* newsletter and you need to send your annual dues for \$20 U.S. (or \$25 International) to continue SLSPA Membership. Please send funds to SLSPA, Inc. c/o Brian Utley, 1930 S.W. 8th St., Boca Raton, FL 33486 USA. If you have questions, please call Brian at 407-750-6876

## German Gliding Championship 1995 will have mixed types...

The German Aero Club and Gliding Commission has scheduled a championship for the following classes:

Class I: Open Class with retractable engine and span of over 18M. Class II: 18M-Class Gliders with and without retractable engine with wing spans of 15-18 Meters.

Class III: Standard Class gliders with retractable of foldable engine/propeller which meet Standard Class Definition.

The purpose is to select a German gliding champion in all three classes and to test the capability of integration of gliders with retractable engines and pure gliders.

This is a 13-day contest (4-16 June, 1995) with no handicap scoring. Eighty pilots will be accepted including foreign pilots. The site is Sonderlandeplatz Paderborn-Haxterberg.

Interested pilots contact:

DAec-Segelflugkommission

-Geschaftsstelle-

Postfach 1361

D-63141 Heusenstamm


**GERMANY** 


The registration fee is DM350. Closing date is 31 March/95.

Ed. note: The emergence of the 18 meter sailplane over the past 5 years has created a new competition category. The German Aero Club is to be commended for its leadership in hosting the world's first national competition with both motorized and pure ships with wing spans of 15-18 meters in a single class. The rules say that if a motorized ship does use its engine, points will be awarded to last turnpoint. Scoring is per DAec-Gliding Championships - copy not furnished to SLSPA. Starts will be by time cameras and finishes controlled from the ground, Radio Nav permitted (GPS).

## Rollanden-Schneider Self-launcher Progress Report...

Mike Adams advises the 18 meter prototype LS-9 self-launcher is now flying. It has the Rotax 535 liquid cooled engine (hp unknown but most likely 45-48). Empty weight- 782.6 lbs. Max weight- 1157.4 lbs. The engine is buried in the fuselage. No details yet available for expected delivery or price. Interested pilots contact LS U.S. Dealer Mike Adams at 310-376-4590.





#### SLSPA Breakfast at Reno 95 SSA Convention...

Reno 95 had to be one of the best SSA Conventions on record. Attendance was high... over 600 delegates, twenty sailplanes were on display and 45 exhibitors were present.

SLSPA member Steele Lipe gave a talk on the use of oxygen. Stan Nelson, SLSPA's new President gave a talk on flying self-launch sailplanes safely. At the SLSPA Breakfast over 77 people were present, including 40 SLSPA members. At this breakfast, Stan presented Pete Williams with a plaque of appreciation for his tenure as founder and president of SLSPA over the past seven years.

John Schmidt, Stan Nelson and Pete Williams met with Gene Hammond, SSA's Soaring Safety Foundation chairman to review the FAA A.C. 61-94 covering the recommended training procedures for transition to self-launching sailplanes. John Schmidt, SLSPA's Safety Chairman will be reviewing this A.C. with input from Williams, Nelson and Tom Knauff. The objective being to assist FAA in updating this document with SSA input to preserve the intent of the A.C. to not establish a powered glider rating.

## No Handicap Factors for Open Class MG at Minden/95...

Bud Shurmeier has advised that if three or more Open Class ships enter the Motorglider Nationals at Minden, an Open MG Class will exist with no-handicap scoring.

Questions? Bud Schurmeier 619-941-3703

#### Pilot Wanted for MG Nationals

Bob Smith wants a qualified contest pilot to checkout in his Stenume S10 and fly as PIC in the Minden MG Nationals 11-22 June. Bob will act as co-pilot and gain insights into contest flying. This is a great opportunity for some pilot to: 1. Check out in the Stemme S10 and 2. Fly the nationals with no handicap!

Interested? Call or write Bob Smith, Box 672, Ketchum, ID 83340, 208-726-4730

#### South Region 5 Accepts Motorgliders Class...

Brian Utley advises the South Region 5 contest to be held at Cordele, GA May 8-12 will accept MG entries as a Class to be scored using Aux-Pwrd Rules.


For more info contact the Contest Manager:

Clyde Taylor 3911 Forest Dawn Ct. Lithonia, GA 30058 404-985-2732 PM, 404-715-7227 Days

#### New Safety Publication Available from SLSPA

Stan Nelson has produced a 13-page booklet describing JAR 22 minimum airworthiness standards for powered sailplanes including takeoff and climb performance standards. The booklet describes procedures for Flight Planning, takeoff, aborted takeoff, loss of power and inflight starts. Copies are available from The SLSPA Publications Library for \$1. Send to Newsletter Editor Pete Williams.

Mar-Apr 95 Page 2



DG-500M Cockpit Instrumentation...

Seen above is a shot of Tupper Robinson's DG-500M front cockpit controls and instruments. The long LCD readout in the center is the DEI (Digital Engine Instrumentation).

The LCD readout displays: Fuel Quantity, RPMs, Battery Volts,

Colored LEDs indicate: Ignition ON/OFF; Engine Extension/ Retraction; Engine Door Position; Start Warning Light; Propeller Position Warning Light.

Switches select: Ignition ON/OFF; Ignition Test Circuits 1 & 2; Batt/CHT; Total Electric system or soaring instruments only; T.E. or Static pressure for variometer.

#### A Special Thanks...

I would like to take this opportunity to thank all of the members of SLSPA past and present for their support of this organization. The charter upon which SLSPA was founded is to assist pilots who fly or desire to fly motorized sailplanes. I also want to express my gratitude to the new management of SLSPA for their willingness to become involved and make a contribution to this movement. A special thanks also to Stan Nelson for crafting the beautiful plaque.



#### SLSPA Administrative Operations for 1994...

The newsletter master files contain 42 Newsletters published since May 1988. Each newsletter initial printing is 350 with 100 reprints made from time to time. Each new member gets 6 newsletters and can order back copies at 85 cents each.

In addition to sales of newsletter reprints, SLSPA has available copies of all Rotax Engine Repair and Parts Manuals plus Tech Notes and Bulletins. Also available are copies of the Safety Survey conducted in 1990; a 12-page booklet titled 'FAA Advisory Circular AC-61-94 Pilot Transition Course for Self-Launching or Powered Sailplanes (Motorgliders)". A Newsletter Index is published about two times per year. A 24-page booklet is also available titled "The DG-400, A Pilot's Introduction and Orientation".

A Pitney Bowes postal meter is used for mailing. Average time required to publish and mail one newsletter issue is 20-25 man hours.

Subject data for the newsletter is gleaned form the airframe and engine factories, submitted by individual members and compiled from other sources such as Sailplane and Gliding, (England), Volo a Vela (Italy), AOPA Pilot, Air Sports International (FAI), West Wind (PASCO), etc.

SLSPA always needs input from its membership. If you have had an interesting flight, maintenance problem, or have a safety note to pass on, please let us know. Photos are particularly welcome.

In 1994, 84 new members joined SLSPA. Total paid membership is 306. Total circulation is 329.

#### SLSPA, Inc. 1994 Financial Statement

(12/31/94)

**Income**: From Dues, Publications Sales & Donations ......\$6,414.10

Expenses:	
Office Supplies/Telephone/FAX/Bank Charges	\$501.69
Fees/Dues/Subscriptions	155.00
Postage	1,228.25
Printing	2,304.11
Travel (1994 SSA Convention)	1,166.26
SLSPA Decals and Patches	737.12
Total Expenses	\$6,029.43
<b>Assets</b> (cash in bank as of 12-31-94)	\$2,838.05
Liabilities	

#### SLSPA Sailplane Fleet...

DG-400 33	1 1K20L/30 10	ASTF20E4
DG-600M 2	Nimbus3DM4	ASH-24E 2
DG-8008	Nimbus4DM 1	ASW-22BE 1
DG-500M 1	Nimbus4M 1	Taifun 3
Grob 103SL3	Ventus CM6	Misc 21
Grob 10914	Ventus BT 5	
	Ventus CT2	TOTAL 134

ACH 26E


DIK 20E/20

#### For Sale

VENTUS CM 17.6m. Immmaculate. NDH. TTA-95hr, TTE-14hr; Peschages VP6E large screen LCD; O<sub>2</sub> Dittle FSG71, Baro' Camera; Tinted Canopy; Cobra Trailer; one man rigging. \$90,000 US. Fritz Bortenlanger, Calgary Alberta. Tel. days: 403-236-8262 (Canada)

NIMBUS 3DM. Perfect. Low engine and airframe hours. Cobra trailer with rigging aids and tow-out gear. Two full panels with S Nav and 760 ch. radio. Parachutes and barograph. New C of A. Contact Phil Lever. Corbridge, Northumberland, UK NE45 5PZ. Tel./Fax 0434 672236.


PIK-20E, 125 hrs TTA, 45 hrs. TTE. Excellent condition. Automatic prop. stop. Full instuments with Winter mechanical vario. Ball electric vario. Edo 720, Oxygen. Minden trailer w/one man rigging. \$45,000. 206-868-2025 (WA).



VALENTIN TAIFUN 17E. N9MA, S/N 1090; always hangared; 225 total hrs. 94hp Limbach with variable pitch and full feathering electric prop; Full IFR panel (Loran and intercom). One person ground handling equipment; 30:1 L/D; retractable tricycle gear; side-by-side dual controls. \$97,000. Call Dr. John at work 503-234-1531 or home 503-775-5004. Portland, OR.

Mar-Apr 95

## Principal Motorgliders in use today (not to scale)



#### SLSPA NEWSLETTER INDEX

May/June '88 thru Jan/Feb '95 (42 Issues)	May/Jone	188	thru	Jan/Feh	95	(42	(Seuze)
---	----------	-----	------	---------	----	-----	---------

Back issues available to members at \$1.00 each or all issues for \$35. Prices include postage. \$1.50/lssue-Nommembers.

Aileron connection/DG-400	June 88
Aileron gel coat cracks/DG-400	May/June 89
Aileron throw checks/DG-400	Nov/Dec 88
Alcohol in Fuel test system	Sep/Oct 91
Airstarts/DG-400 May/June 8	8 July/Aug 88
Anti-rust maintenence	July/Aug 89
ARIA sailplane	Jan/Feb90
Automatic engine extension/retraction DG-400	May/Jun 90

Batteries DG-400 July/Aug88 Mar/Apr89 Mar/Apr90 May/June90
Batteries PIK-20E/30 May/June 89
Battery Upkeep Jul/aug 93
Brake linings DG-400 Jan/Feb 89 Mar/Apr 89
BEA (DG400 Auto Engine Ext/Ret System) Problems May/June91

-	Jan/Feb	91
	Jul/Aug	89
.**	Ju1/Aug	89
	May/June	92
	July/Aug	90
Nov/Dec	92 Jan/Feb	92
	May/June	90
	May/June	88
	,7°	Jul/Aug Jul/Aug May/June July/Aug Nov/Dec 92 Jan/Feb May/June

DE1 Circuit Diagram/	400 May/June	92
DG 400/800 Custom In:	ument Console May/June	94
DG-400 Specs	May/June	93
D8-400 Climb Performa	e May/June	94
00m500 Specs	Jan/Feb 93 Jul/Aug	92
DG-500 Engine failure	May/June	91
DG-600M Nov/Dect	Jan/Feb 90 Mar/Apr 90 May/June	90
Man/Ann	Inn/Eah02	

Mar/Apr91 Jan/Feb92		
DG-600M Disc Brake Installation	Jan/Feb	94
DG-800M Jul/Aug92Jan/Feb92	Nov/Dec	90
9G-800B Nou/Dec94	Jul/Aug	94
DG-800B Specs	Sep/Oct	94
Discus M Flight Report	Mar/Apr	93
Discus BT	Mar/Apr	94
Ducati Ignition/Rotax Engines Jan/Feb 93	Jul/Aug	92
	Nov/Dec	91

Electrical Sys. troubleshooting DG-400	Mar/Apr 98
Elevator push/pull tube guides PIK-20E	Jan/Feb 89
Elevator trim problems/06-400	Sep/Oct90
Emerg. Extension of engine DG-400	June 88
Emerg. Extract/Retract Switch Caution DG400/800	May/Jun 94

Engine bay doors P1K-20E	May/June 89
Engine bay fuel value DG-400	May/June 89
Engine extraction relay D6-400	May/June 90
Engine extraction blocked DG-400	May/June 91
Engine retraction blocked DG-400	Sep/Oct 92
Engine failure Rotax	July/Aug 88
Engine/Prop doors DG-400	Mar/Apr 89
Exhaust Manifold Cracks-DG-600M	May/June 92
Flight training program	Nov/Dec 88
Fournier RF58	Mar/Apr 92
Fuel hoses DG-400	Jul/Aug 89 Jan/Feb 90
Fuel gauge calibration DG-400/500M/8	
	May/June91 Sep/Oct 90
	May/June92 Jul/Aug 88
Fuel/oil mixture SOLD	May/June92
Fuel octane specs./Rotax Mar/Apr9	
	Sep/Oct 92
Fuel Tank Drain Valve/DG-400	Jul/Aug92 Sep/Oct91
Belcoat cracks near spoilers/DG-400	May/June92
Glaser-Dirks Sailplanes Prices-1995	Jan/Feb95
Glasflugel Mosquito Self-Launcher	Sep/Oct93
Grob 1098 Specs	Sep/Oct92
High Alt.Jets/Rotax May/June88 June	
Hotellier Quick Disconnects for Cont	
water at security 101 point	Jan/Feb90
Ignition/Rotax May/Jun88 Nov/Dec8	88 Jan/Feb89 May/JuneB9
Mar/Ap93 Sep/Octs	
Insurance	Jul/Aug92 May/June88
IS-28M2 Motorglider	Sep/Oct92
Landing gear retraction DG-400 June8	
Liquid measures chart	Jul/Aug92
LS-6 Motorglider	May/June93
Mikuni Carbs/Rotax	Sep/OctB9 May/June89
Motorglider checkout procedures	May/June92 Sep/Oct89
Motorglider listing by types	Sep/Oct89 Nov/Dec 90
Motorized Sailplane Listing by OEM	Mar/Apr 94
Muffler springs/Rotax/DG-400	Sep/Oct 89
Newsletter Index	Mar/Apr 95
Nelson Engine	Mar/Anr 94
Netson Hummingbird	Nov/Dec 94
Nimbus 3DM Cockpit Layout	Jan/Feb 95
Nimbus 3DM flight procedures	Jul/Aug 90
Nimbus 3DM Fuel System	Nov/Dec 91
Nimbus 3DM Specs	Jan∕Feb 95
Nimbus 4T	Jul/Aug 91
Nimbus 4M	Nov/Dec 93
Nimbus 40M	Mar/Apr 94

Parts source list (carbs & ignition-Rotax)	Sep/Oct90
	Mar/Apr89
	lay/June92
	Mar/Apr94
PIK-20E Engine restraining straps Jan/Feb95	
	May/Jun90
	Mar/Apr93
Piston conrod bearings/Rotax505&501 Sep/Oct88	
Prop brake system/P1K20E/30	Ju1/Aug88
Prop mounting Rotax/D6-400 June88	Jul/Aug88
Prop braking system DG-400	Jul/Aug94
Prop shaft failure Rotax 505/DG-400 Mar/Ap91	Jul/Aug90
Prop shaft inspection/replacement Rotax/DG-400	Sep/Oct91
Jan/Feb92 Har/Apr92	
Prop support mounting bolts DG400 June88 M	lay/June 88
Ju 1/Aug89	
	Nov/Dec93
Beallmannak Beak, 11-1488 488	I1 /A
•	Jul/Aug 91
· · · · · · · · · · · · · · · · · · ·	lay/June 89
Retractable Engine Sailplane Listing Mar/Apr90	
RF1 Noise caused by flight computer	Jul/Aug92
Rotax Engine high CHT	May/Jun94
Rotax Engine Repair/Parts/Manuals Sep/Oct88	Jan/Feb92
Rotax 505 Starter Motor Problem Sep/Oct94	Jul/Aug94
Rotax Engine O/H Jan/Feb93 May/June93 Jan/Feb94	
Nov/Dec94	
Rotax Engine Q/H.,FAA Comments Rotax Engine Ext/Ret Motor Changeout DG-400	Sep/Oct94 Nov/Dec93
Rotax Engine Ext/Ret Motor Changeout D6-400 Rotax Parts and Service Centers May/June 94	Mar/Apr 92
	a. / mpr 72
Safety Survey Har/Ap91	Nov/Dec90
Sailplane Operations—A Power Pilots Briefing	Sep/Oct94
Scheibe SF-27M Sep/Oct93 Jul/Aug90	Nov/Dec 90
SF-25C	Jan/Feb93
Schleicher ASH-26E Jan/Feb94 Sep/Oct93 Sep/Oct93	
ASH-26E Specs	May/Jun94
ASU-24E May/June92 Nov/Dec91	Mar/Apr92
ASW-22 BLE May/June93 Seat Cuchion Alest (NG-400	Sep/Oct93
Seat Cushion Alert:DG-400	Mar/Apr92
	May/June92
Selflaunch technique Mar/Ap93	Jul/Aug89
Selflaunch precautions	Sep/Oct91
Serv. Bull. #35 PIK-20E/30	Jan/Feb89
SOLO Engine tuning (Ventus CT/CH)	Jan/Feb91
Spare parts list DG-400 Spark plup problems/Ratay/PIK-205	Jul/Aug88
Spark plug problems/Rotax/PIK-20E Spark plugs/Rotax/RG-400 Nov/Dec90	Jul/Aug89
Spark plugs/Rotax/DG-400 Nov/Dec90 Spailer/Aileron connections DG-400 Nav/June90	Jul/Aug88
Spoiler/Aileron connections DG-400 May/June90 Spring Check List	Jul/Aug89 Jan/Feb92
Spring Check List Stamma Sin Space Mar/An93	Jan/Feb92 Nov/Dec92
Stemme S10 Specs Mar/Ap93	
Starter gear cracks/DG-400 Starter relay problems/DG-400	Ju1/Aug89 Ju1/Aug91
Starter relay problems/DG-400 Starter removal/repair/DG-400	Jul/Aug91 June88
ATHE FEL LEHOARINEShELLANG-400	ANUARR

۱			
l	Starter/Rotax		May/Jun88
١	Static system leaks		Nov/Dec89
Ì	Super Dimona HK 36R Specs.		Ju1/Aug94
ı	Super Ximango AMT-200 Specs.		Nov/Dec94
I	Taifun Parts Source		Nov/Dec 91
Į	Tailwheel ball bearing type/OG-40	0	Sep/0c t91
ı	Tailwheel mounting/DG-400		June 88
1	Tailwheel tow dolley fabrication/	DG-400	Mar/Apr91
	Tillotson carbs Jan/Feb91 May/Ju May/June91 Jul/A		Sep/Oct90
ı	TN listing for DG-400	ug //	May/Jun90
ı	Tonopah, NV SLSPA Fly-In 93		Jul/Aug93
ı	T.O.P. Engine Installations		Jul/Aug92
ı	Transition to motorgliders FAA re	ouirements	Jul/Aug90
ı	Transponders	•	May/June92
1	Type Certification for Experiment		Nov/Dec 88
	U.S. Motorized Sailplane Fleet		Jan/Feb93
	VIVAT L-3		Jan/Feb94
	Ventus Elevator Control Rod Corro	sion	Jan/Feb93
	Ventus CM engine tuning		Sep/Oct90
	Ventus CM Specs	Jul/Aug93	May/Jun90
	Ventus T Tech Tips	*. <del>*</del>	Jan/Feb89
	Ventus 2	Ju1/Aug94	Mar/Apr94
	Weight & Balance May/Jun89 Jul/Au	g89 Nov/Dec89	Jan/Feb90
	WINDROSE SL sailplane May/June92	Sep/Oct 91	May/Jun89
	Winter inspection checklist	Sep/Oct94	Nov/Dec 89
	Uinterizing the engine	•	Nov/Dec93
	Wheel Brake Cable Inspection		Sep/Oct94
	WOODSTOCK SL sailplane	Nov/Dec94	Sep/Oct89