

IEMS

Industrial Equipment Monitoring System

Secure visibility for every critical machine.

24/7 MONITORING

SECURE ACCESS

Telemetry • Detection • Alerts • Maintenance

Welcome back

Sign in as an authorized engineer

ENGINEER ID

engineer@company.com

PASSWORD

.....

MFA verification required

Continue securely

Protected session

Role-based access • Audit logged

Need access help? Contact the system administrator.

Security: encrypted transport • least privilege

Industrial monitoring

Live machine health, sensor telemetry and active conditions.

LIVE

Updated 12 sec ago

12

Machines monitored

Normal

10

Normal

Normal

1

Warning

Warning

1

Critical

Critical

Machine status

Select a machine to inspect live telemetry and conditions.

MX-101	Hydraulic Press	72°C	4.2 bar	2.1 mm/s	Normal	View
MX-102	Compressor	81°C	6.8 bar	5.8 mm/s	Warning	View
MX-103	CNC Mill	66°C	3.9 bar	1.9 mm/s	Normal	View
MX-104	Turbine	94°C	8.1 bar	8.7 mm/s	Critical	View

Active alert

CRITICAL • MX-104

Vibration above configured operating threshold.

Detected 09:42 • 2 min ago

Open alert

Quick actions

Configure thresholds

Schedule maintenance

All actions require authorization and are audit logged.

Threshold configuration

Authorized engineers can safely update monitoring conditions.

AUTHORIZED

MX-102 • Compressor

Configuration changes are validated before they are applied.

Temperature

90

°C

High threshold

Pressure

8.0

bar

High threshold

Vibration

6.0

mm/s

High threshold

Power consumption

75

kW

High threshold

Validation: values are within permitted operating ranges.

Change will be recorded in the security audit.

Security guardrails

- 1

Authorization

Engineer role verified
- 2

Validation

Range checks enabled
- 3

Audit trail

Change will be recorded
- 4

Integrity

Configuration versioned

Before you save

Confirm the threshold change against the machine operating specification.

Cancel

Save configuration

Alerts & operational actions

A single workspace for acknowledgement, maintenance and audit visibility.

Active alerts

Maintenance

Audit events

Active alerts

CRITICAL	MX-104	Vibration 8.7 mm/s	09:42	Acknowledge
WARNING	MX-102	Temperature 81°C	09:38	Acknowledge
WARNING	MX-109	Power draw above baseline	09:31	Acknowledge

Selected alert

CRITICAL

MX-104 • Turbine

Vibration exceeded the configured threshold by 45%.

Recommended action

Inspect machine and schedule maintenance.

Acknowledge alert

Schedule maintenance

Audit

Detected • Alert created • Engineer notified

All actions are recorded for traceability.

MX-104 • Turbine

Detailed telemetry, operating condition and recent abnormal behavior.

CRITICAL

Schedule maintenance

Machine overview

Turbine • Line A

RUNNING

Last update 12 sec ago

94°C

Temperature

Critical

8.1 bar

Pressure

Warning

8.7 mm/s

Vibration

Critical

72 kW

Power consumption

Healthy


99.98%

Data availability

Healthy

Telemetry trend

LAST 24 HOURS



Current condition

Vibration	8.7 mm/s	Above threshold
Temperature	94°C	Above threshold
Pressure	8.1 bar	Near threshold
Operating status	Running	Nominal

View alert history

Configure thresholds

Alert center

Prioritize abnormal behavior, acknowledge safely and track resolution.

3 ACTIVE

Export report

Search

Machine, alert type or ID...

All severities

Unacknowledged

Last 24h

Alert queue

CRITICAL	ALT-1042	MX-104	Vibration exceeded threshold	2 min	Unacknowledged
WARNING	ALT-1041	MX-102	Temperature approaching limit	8 min	Acknowledged
WARNING	ALT-1038	MX-109	Power consumption anomaly	21 min	Investigating
INFO	ALT-1032	MX-103	Sensor reconnect detected	1 hr	Resolved

Alert workflow

CRITICAL

ALT-1042 • MX-104

Vibration 8.7 mm/s exceeds 6.0 mm/s.

Detected

Engineer notified

Acknowledged

Maintenance scheduled

Acknowledge

Schedule maintenance

Maintenance planner

Schedule, prioritize and track machine maintenance activities.

Schedule maintenance

Calendar

List

Overdue

2 OVERDUE

5 THIS WEEK

October 2026

< >

Mon	Tue	Wed	Thu	Fri	Sat	Sun
5 MX-102 PM	6	7	8 MX-104 INSPECT	9	10	11 MX-102 PM
12	13	14 MX-102 PM	15	16	17 MX-104 INSPECT	18
19	20 MX-104 INSPECT	21	22	23 MX-102 PM	24	25
26 MX-102 PM	27	28	29 MX-104 INSPECT	30	31	32 MX-102 PM

Upcoming

Today

MX-104Inspect vibration

Tomorrow

MX-102Compressor service

Oct 12

MX-109Sensor calibration

Oct 15

MX-101Routine inspection

View all

Create schedule

Audit & security center

Review security-relevant monitoring and configuration activity.

AUDIT HEALTHY

Export audit

1,248

Events / 24h

Healthy

0

Privilege changes

Healthy

3

Denied actions

Warning

100%

Audit coverage

Healthy

Recent security events

10:42	Engineer	Threshold updated	MX-102	Allowed	IP / session details available
10:31	Engineer	Alert acknowledged	ALT-1042	Allowed	IP / session details available
10:12	Unknown	Configuration attempt	MX-104	Denied	IP / session details available
09:58	Engineer	Maintenance scheduled	MX-109	Allowed	IP / session details available
09:41	Engineer	Login failed	—	Denied	IP / session details available

Investigate event

Engineer & access administration

Manage authorized engineer access using least privilege.

Add engineer

Search engineer...

All roles

Active

MFA enabled

Authorized engineers

AN	Anita Rao Senior Engineer	MFA	Active	Manage
RA	Rahul Kumar Engineer	MFA	Active	Manage
ME	Meera Shah Engineer	MFA	Active	Manage
DE	Dev Ops Read-only	MFA	Active	Manage
MA	Maintenance Bot Service account	Key	Restricted	Manage

Security policy: privileged configuration actions require authorized engineer role and are audit logged.

System health & settings

Operational reliability, integrations and security configuration.

99.98%

Monitoring availability

Healthy

12 sec

Telemetry freshness

Healthy

0

Critical service failures

Healthy

100%

Alert delivery

Healthy

Service health

● Telemetry ingestion	Operational	12 sec lag
● Abnormal detection	Operational	Healthy
● Alert service	Operational	99.99%
● Audit service	Operational	No gaps
● Data persistence	Operational	Healthy

Security settings

MFA for engineers	Required	☒
Audit logging	Enabled	☒
Configuration versioning	Enabled	☒
Session timeout	15 minutes	☐
Alert acknowledgement	Role restricted	☐

Changes to security settings require authorized administrator access and are audit logged.