





This is a list of Mayflower parts with manufacturer part numbers and other vehicles the parts may have been used on. There are also suggestions of possible alternative parts which may do the job. The entries include the Stanpart numbers and page numbers from 'The Triumph Mayflower Spare Parts List' published by The Standard Motor Co. Ltd. The list has been compiled in good faith from various sources including the internet and back copies of the club magazine Flower Power and as such the TMC cannot take responsibility for the accuracy of any entries in the list.

Whilst the club cannot carry a complete stock of spares, if you are looking for a part for your Mayflower a good starting point is the club Spares Secretary, who has a range of new and used parts available for purchase. His contact details are:

Paul Burgess, 14 West Street, Blaby, Leicestershire, LE8 4GY. Email: pburgess1956@gmail.com

The club would like this list to develop over time. If you have any additional information which could be included or spot any inaccuracies please email Paul Burgess at:

Pburgess1956@gmail.com

#### **CONTENTS**

| Engine          | p3  |
|-----------------|-----|
| Fuel & Exhaust  | р5  |
| Cooling         | р9  |
| Electricals     | p11 |
| Running Gear    | p18 |
| Drive           | p24 |
| Body & Interior | p27 |

## **ENGINE**

| Component                           | Parts<br>List<br>Page | Stan<br>part No | Possible Manufacturer Part No(s)  | May also be fitted to/ Possible alternative   |
|-------------------------------------|-----------------------|-----------------|---|---|
| Big End Bearings                    | 20                    | 100461          | Glacier B4214M, Vandervell VP430  | 1939-47 Austin 10-4   |
| Oil Pump Gasket                     | 22                    | 39430           | Payen 7817, KR160   |   |
| Timing (Roller) Chain               | 22                    | 44101           | 3SR56   | Vauxhall Viva HA, HB, HC, 1057,1119,1256; Opel Kadett GT 1100 1969-70, 1.1L 1963-71, 993cc 1962-65, Caravan 1963-   |
| Front Timing Cover Oil Seal         | 12                    | 100499          | Humphrey T13, Payen NA329, C572, Weston<br>(Gitseal) 237162-57R6          | Triumph Herald 1100cc, 1300cc except GK engine prefix, Spitfire Mk1 & 2 1147cc, Mk3 1300cc except GK prefix, Triumph 1300 &1300TC 1965 on; Standard 8 & 10 1953-61, Pennant 1957-61 |
| Timing Cover gasket                 | 12                    | 200102          | Payen 13529, JR037  |   |
| Timing Chain Tensioner              | 22                    | 42425           |   | Triumph Spitfire, Herald, Vitesse, TR5, GT6, 2000, 2500, Dolomite, Sprint   |
| Timing Chain Tensioner Anchor Plate | 22                    | 43752           |   | Triumph Spitfire, Herald, Vitesse, TR5-6, GT6, 2000, 2500   |
| Timing Chain Tensioner Anchor Pin   | 12                    | 33214           |   | Triumph Spitfire, Herald, Vitesse, TR5-6, GT6, 2000, 2500   |
| Air Cleaner Tubing Nut              | 40/1                  | 101302          |   | Triumph Spitfire, Herald, Vitesse, TR2-6, GT6, 2000, 2500   |
| Camshaft Chain Wheel Set Screw      | 22                    | 100500          |   | Triumph Spitfire, Herald, Vitesse, TR5-6, GT6, 2000, 2500   |
| Camshaft (Timing) Chain Wheel       | 22                    | 35960           |   | Triumph Spitfire, Herald, Vitesse, TR5, GT6, 2000, 2500   |
| Camshaft Chain Wheel Locating Plate | 22                    | 36411           |   | Triumph Spitfire, Herald, Vitesse, TR5-6, GT6, 2000, 2500, Dolomite, Sprint   |
| Crankshaft Chain Wheel              | 18                    | 100431          |   | Triumph Spitfire, Herald  |
| Crankshaft Oil Deflector            | 18                    | 100447          |   | Triumph Spitfire, Herald  |
| Bearing In Crankshaft               | 18                    | 47246           |   | Triumph TR2-6, Standard Vanguard Ph 1-3, Vignale,, Ensign, 6 Cyl, Sportsman   |
| Main Bearing, front & rear          | 18                    | 100326          | Vandervell VP431, Glacier M3123S GS 7688S,<br>Remax B305, BK 305, BKT 305 |   |
| Main Bearing, centre                | 18                    | 100325          | Vandervell VP431, Glacier M3123S, GS8014S,<br>Remax B306                  |   |
| Main Bearing Rear Thrust Washer     | 18                    | 100327          | Vandervell VPW191, Glacier W2046S   | Standard 8, 10, Pennant 1954-61, early Vanguard 6 MK1; Triumph Herald 948cc, Vitesse, Spitfire, 2000; Rover 60  |
| Cylinder Block Drain Tap            | 6                     | 61478           |   | Triumph Vitesse, TR2-6, Standard Vanguard Ph 1-3, Vignale, Ensign, Sportsman  |
| Flywheel Gear Ring                  | 26                    | 201350          |   | Triumph Spitfire, Herald, Vitesse, TR5-6, GT6, 2000, 2500, Dolomite, Sprint   |
| Flywheel Locking Plate              | 26                    | 102076          |   | Triumph Spitfire, Herald, Vitesse   |
| Flywheel Set Screw                  | 26                    | 102065          |   | TR2-4A  |

| Flywheel Dowel                                   | 26  | 500045  |   | TR3   |
|--|-----|---------|---|---|
| Dynamo Pedestal                                  | 26  | 59015   |   | Triumph Vitesse, TR2-4A   |
| Piston   | 20  | 101215  | BHB/Shhepbridge SA151, Hepolite RSW<br>11587    | Morris 1000 (?)   |
| Piston Compression Ring                          | 20  | 101216  | Cords 30, 30R, Hepolite R3172, KTP8137, TP8138  | Morris 1000 (?)   |
| Piston Scraper Ring                              | 20  | 102811  | Cords 30, 30R, Hepolite RX3175, DO8139, DO814OM | Morris 1000 (?)   |
| Gudgeon pin                                      | 20  | 101218  | Hepolite Type SC 3/4 " diam                     |   |
| Gudgeon Pin Bush                                 | 20  | 100798  | Glacier S4537L (Bedford)                        |   |
| Cylinder Liners                                  |     |         | Hepolite FS444, Glacier B3472                   |   |
| Cylinder Head Gasket<br>Head Gasket (decoke) set | 10  | 200175  | Payen AB650, 1A317<br>Payen HS1A 317, CB650     |   |
| Cylinder Head Plug                               | 10  | 57216   |   | TR2/3   |
| Bottom End (Conversion) Gasket Set               |     |         | Halls AES 120, Payen CS1A317                    |   |
| Sump Gasket                                      | 10  | 200623  | Payen 7715A, JH208                              |   |
| Sump Drain Plug Washer                           | 10  | WF.0524 | Payen KG673, HR064                              |   |
| Engine Rear Plate Gasket                         | 12  | 200097  | Payen 13527, KT568                              |   |
| Engine Plate Front Gasket                        | 12  | 200091  | Payen 13528, KR590                              |   |
| Manifold Gasket                                  | 34  | 103978  | Payen M3278, JA217                              | Standard Flying 9   |
| Exhaust Pipe Gasket                              | 104 | 32301   | Payen 34F7, JE262                               |   |
| Distributor gasket, pedestal to head             | 24  | 33831   | Payen 4651, KR018                               |   |
| Distributor seal felt                            | 24  | 34469   | Payen 13526, KG135                              |   |
| Tappet Cover Gasket                              | 14  | 43669   | Payen 7696, JM220                               | Standard Flying 9   |
| Inlet Valve                                      | 24  | 100363  | James 1933, Tranco 2594                         |   |
| Exhaust Valve                                    | 24  | 100364  | James 1934, Tranco 2595                         |   |
| Valve Guide                                      | 8   | 100862  | Tranco G440                                     |   |
| Valve Spring                                     | 24  | 47757   | Terry 451543, Aero VS295, 451.295               | Fiat 1200, 1100, 103D, 103H, Standard 8 1009cc 1939-48  |
| Front Engine Mounting, rh                        | 62  | 200662  |   | Conversion: QH EMN46. Try gearbox mounts from Ser 2 Morris Minor, or engine mounts from Jaguar XJ6 (raises engine 1/4 inch) |
| Front Engine Mounting, Ih                        | 62  | 200663  |   | Conversion: QH EMN46. Try gearbox mounts from Ser 2 Morris Minor, or engine mounts from Jaguar XJ6 (raises engine 1/4 inch) |
| Flexible Oil Pipe                                | 111 | 101050  | Smiths PFP106 or 107                            |   |

| Flexible Oil Pipe              | 125 | 101052 | Smiths PFP106 or 107 |                          |
|--------------------------------|-----|--------|----------------------|--------------------------|
| Fibre Washer for flexible pipe | 111 | 500469 |                      | Standard Vanguard Ph 1-2 |

## **FUEL & EXHAUST**

V9.1

| Component                        | Parts<br>List<br>Page | Stan<br>part<br>No | Possible Manufacturer Part No(s)  | May also be fitted to/ Possible alternative  |
|----------------------------------|-----------------------|--------------------|---|--|
| Carburettor                      | 36                    | 201209             | Solex 30FAIO, 30FAIO-2/R275, 30FAIO-2S,<br>Singer C12013, C12014, Rootes P89594,<br>P100226-30FAIO, P111220 | Hillman Minx Mk1-4 1948-52; Singer SMI500 1949-52, Roadster 1946-50; Standard 12 1946; Morgan 4-4 1946-52; Rover 12hp 1946; Commer 25cwt 1946-47, 8cwt van 1946-50 |
| Float Chamber                    | 36                    | 500424             | Solex 11510, Rootes K20117  |  |
| Float Chamber Cover              | 36                    | 57510              | Solex 60069/2, Singer C9485ND   |  |
| Gasket, Float Chamber Cover      | 36                    | 500430             | Solex 51429, Singer C9504ND, Rootes<br>K11416   |  |
| Screw, Float Chamber Cover       | 36                    | 500431             | Solex 50239, Singer C9505ND, Rootes<br>K11419   |  |
| Tube, choke size 21 size 22      | 36                    | 59721              | Solex 52846/21, Rootes K22422/21,<br>5102685, K13681/21<br>Solex 52846/L1/22, Singer C9486ND                |  |
| Screw, choke tube fixing         | 36                    | 57422              | Solex 50362, Singer C9487ND, Rootes<br>K11423   |  |
| Banjo Union                      | 36                    | 59700              | Solex 4120/18   |  |
| Bolt for Banjo Union             | 36                    | 57513              | Solex 4122  | Ph 1-3, Vignale, Ensign  |
| Washer, Banjo Union Bolt, large  | 36                    | 57515              | Solex 4124  |  |
| Washer, Banjo Union Bolt, small  | 36                    | 57516              | Solex 4124/1, Singer C9493ND, Rootes<br>P55984, 9078023   |  |
| Throttle chamber, only complete  | 38                    | 57503              | Solex 60148/2, Singer C9456ND, Rootes<br>K13003<br>Solex 60148/2/R275                                       |  |
| Throttle Butterfly               | 38                    | 57505              | Solex 51270, Singer C9458ND, Rootes<br>K11402   | Hillman Minx Mk1-7, Californian Mk6-7 1946-54; Singer SM1500, 9HP 4AB 4A, 1½L 4AD, Hunter, Gazelle Ser 1 & early 2   |
| Screw, throttle butterfly fixing | 38                    | 57506              | Solex 3947, Rootes K23283   |  |
| Throttle Spindle                 | 38                    | 57504              | Solex 50460, Singer C9457ND, Rootes<br>K11401   |  |

February 2018

| Screw, throttle chamber fixing                   | 38 | 57437  | Solex 51183, Singer C9470ND, Rootes<br>K20114   |   |
|--|----|--------|---|---|
| Washer, throttle chamber fixing screw            | 38 | 57547  | Solex 901, 4031/1, Singer C9471ND,<br>C9484ND, Rootes 9660121, W1, K26027               |   |
| Plate, throttle abutment                         | 38 | 58330  | Solex 10191, 4019, Rootes K25992  |   |
| Screw, slow running adjustment                   | 38 | 59558  | Solex 4023, Singer C9461ND, Rootes K15299   |   |
| Spring, slow running screw, volume control screw | 38 | 57413  | Solex 4384, Singer C9462ND, Rootes K11432   |   |
| Screw, throttle stop                             | 38 | 58331  | Solex 50537, Singer C9463ND, Rootes<br>K11405   |   |
| Nut, throttle spindle end, starter spindle end   | 38 | 57419  | Solex 3950, Singer C9464ND, Rootes K11406, 9029000                                      |   |
| Lever, throttle                                  | 38 | 101888 | Solex 10873   |   |
| Screw, volume control                            | 38 | 57412  | Solex 1171, Singer C9467ND, Rootes K11431   |   |
| Needle Valve                                     | 36 | 57511  | Solex 51305/7/1.5, Singer C9488ND, Rootes<br>K13027/7                                   |   |
| Washer, Needle Valve                             | 36 | 57424  | Solex 2261, Singer C9489ND, Rootes K12555   |   |
| Float, 26gms                                     | 36 | 57524  | Solex 50772/3/26g, 50772/1, Singer<br>C9503ND, Rootes K12551                            | Commer Q Series 1510, 1522, 2522, 3020, 1946-50 |
| Jet, main, size 105<br>size 100<br>size 110      | 36 | 57519  | Solex 50552/6/105<br>Solex 50552/6/100, Rootes K11426/100,<br>5102513<br>Singer C9495ND |   |
| Bolt, main jet carrier                           | 36 | 57430  | Solex 50820, C9500ND, Rootes K13026   | Standard Vanguard Ph 1-3, Vignale, Ensign       |
| Washer, main jet carrier bolt                    | 36 | 57431  | Solex 50815, Rootes K12553  |   |
| Jet, air correction, size 220<br>200             | 38 | 59716  | Solex 57612/220<br>Solex 51612/200, Rootes K14603/200,<br>5102583                       |   |
| Jet, pilot, auxilliary, size 45                  | 36 | 57428  | Solex 50797/4/45, Singer C9498ND, Rootes<br>K11424/45, 5102490                          |   |
| Bleed, main jet correction                       | 36 | 59718  | Solex 51274/1/150, Singer C9499ND, Rootes K23109/150, 5102696                           |   |
| Tube, main jet emulsion                          | 36 | 500987 | Solex 52043/L4, Singer C9497ND, Rootes<br>K21439  |   |

| Jet, starter, size 135<br>120<br>100 | 36  | 57434  | Solex 50676/2/135<br>Solex 50676/2/120, Singer C9507ND, Rootes<br>K14606/120, 5102607<br>Solex 52823/100, Rootes K22763/100, |   |
|--------------------------------------|-----|--------|--|---|
|                                      |     |        | 5102880  |   |
| 90                                   |     |        | Solex 52823/90   |   |
| Washer, starter petrol jet           | 34  | 57435  | Solex 52825, Rootes K19653, 9078015  |   |
| Gauze, banjo union filter            | 36  | 57514  | Solex 4123   | Standard Vanguard Ph 1-3, Vignale, Ensign |
| Carburettor Gasket Set               |     |        | Solex G508   |   |
| Carburettor Plate Facing Gasket      | 38  | 100657 | Payen X4008, KD026, Solex 9348, Singer C9472ND, Rootes K19087  |   |
| Carb Starter Assembly, complete      | 38  | 500429 | Solex 12655  |   |
| Valve, Starter Assembly              |     |        | Solex 13309  |   |
| Cover, Starter                       | 38  | 500425 | Solex 11115  |   |
| Spring, starter valve ball           | 38  | 57416  | Solex 51762, Singer C9480ND, Rootes<br>K12547  |   |
| Ball, Starter Valve                  | 38  | 57415  | Solex 51728, Singer C9479ND, Rootes<br>K12546  |   |
| Lever, Starter                       | 38  | 500428 | Solex 11514  |   |
| Washer, Starter Spindle              | 38  | 59679  | Solex 4031/1, Singer C9484ND, Rootes<br>K26027   |   |
| Nut, starter spindle end             | 38  | 57419  | Solex 4024, Singer C9483ND, Rootes K11445  |   |
| Bolt, outer cable locking            | 38  | 500427 | Solex 50924  |   |
| Bolt, inner cable locking            |     |        | Solex 51760, Singer C9476ND, Rootes<br>K12557  |   |
| Clip, cable                          | 38  | 500426 | Solex 50881  |   |
| Bolt, starter unit                   | 38  | 59682  | Solex 51421/1, Singer C9481ND, Rootes<br>K22762  |   |
| Manifold clamp                       | 34  | 33148  |  | TR3                                       |
| Manifold Gasket                      | 34  | 103978 | Payen M3278  | Standard Flying 9                         |
| Exhaust gasket                       | 104 | 32301  | Payen 34F7   | Standard Flying 9                         |
| Exhaust Front Pipe                   | 104 | 300505 | Harmo SU303  |   |
| Silencer                             |     | 300163 | Harmo SU206, Celast CE213BO  |   |
| Exhaust Tail Pipe                    | 104 | 300162 | Harmo SU304  |   |

| Exhaust Flexible Support, front to frame   | 104 | 45484  |   | Standard Vanguard Ph 1, 2 |
|--|-----|--------|---|---------------------------|
| Fuel Pump Type YD  | 32  | 200141 | AC 7950196, 1524712   |                           |
| Fuel Pump Type YD Repair Kit   |     |        | ACBD4 AC7950298   |                           |
| Fuel Pump Type Y Repair Kit  |     |        | ACBD3 AC1524632   |                           |
| Fuel Pump Upper Casting & Valve Seat Ass   | 32  | 500295 | AC 856856   |                           |
| Fuel Pump Screw, upper to lower casting  | 32  | 52489  | AC132113, 132117, Rootes K19785, 5220204  |                           |
| Fuel Pump Filter Cover   | 32  | 52467  | AC856820, Rootes K19777   | Triumph Spitfire          |
| Fuel Pump Filter Cover Screw   | 32  | 52487  | AC856824, Rootes K19784, 9003018  |                           |
| Fuel Pump Body, lower  | 32  | 500291 | AC856812  |                           |
| Fuel Pump Filter Gauze   | 32  | 52469  | AC 856820, 856850, Rootes K19779  | Triumph Spitfire          |
| Fuel Pump Drain Plug   | 32  | 52465  | AC856783, Rootes K13628, 9303000  |                           |
| Fuel Pump Drain Plug Gasket  | 32  | 52471  | AC856784  |                           |
| Fuel Pump Diaphragm, complete diaphragm fabric only pull rod pull rod lock washer lower protector upper protector pull rod nut | 32  | 500292 | AC1524631, Rootes K19776<br>AC856798<br>AC856816<br>AC1519385<br>AC856819<br>AC856818<br>AC120614 | Triumph Spitfire          |
| Fuel Pump Link   | 32  | 500293 | AC856817, Rootes K19780   | Triumph Spitfire          |
| Fuel Pump Diaphragm Spring   | 32  | 52491  | AC856829, Rootes K19786   | Triumph Spitfire          |
| Fuel Pump Rocker Arm Spring  | 32  | 52493  | AC 856830, 856887, Rootes K19787, K19789  | Triumph Spitfire          |
| Fuel Pump Rocker Arm Clip  | 32  | 52484  | AC1524112, 848429, Singer C11938ND,<br>Rootes K17752  | Triumph 2-4A              |
| Fuel Pump Rocker Arm Clip washer   | 32  | 52485  | AC856828, Rootes K19783, 9067212  |                           |
| Fuel Pump Rocker Arm   | 32  | 500294 | AC1524214, Rootes K20731  | Triumph Spitfire          |
| Fuel Pump Gasket to engine   | 32  | 100529 | AC 856794, Payen 13158, KR561, Rootes<br>P44187   | Triumph Spitfire, Herald  |
| Fuel Pump Gasket, filter screw   | 32  | 52472  | AC 851297, Rootes K9021, 9078003  | Triumph Spitfire          |
| Fuel Pump Valve  | 32  | 57351  | AC855003, Rootes K1570, 5038228   |                           |
| Fuel Pump Gasket, valve plate  | 32  | 57355  | AC 856826, Rootes K19792  | Triumph Spitfire          |
| Fuel Pump Gasket, filter cover   | 32  | 52473  | AC 856821, 5506636, Rootes K19778, 9079058  |                           |

| Fuel Pump Valve Spring Retainer (Y)                            | 32  | 57358   | AC 1524344, 856827, Rootes K19793  |   |
|--|-----|---------|--|---|
| Fuel Pump Valve Spring Retainer (YD)                           |     |         | AC 1521956   |   |
| Fuel Pump Valve Spring   | 32  | 52495   | AC 856832, Rootes K19788   |   |
| Fuel Pump Rocker Arm Pin                                       | 32  | 52483   | AC 856035, Rootes K9033  | TR3   |
| Fuel Pump Rocker Pin Clip                                      | 32  | 52484   | AC 1524112   | Triumph Spitfire  |
| Fuel Pump Valve Plate  | 32  | 57353   | AC 1524569, 856825, Rootes K19791  |   |
| Fuel Pump Valve Plate Screw                                    | 32  | 57357   | AC856374, Rootes K9047, 9050094  |   |
| Fuel Pump Lock Washer  | 34  | 57361   | AC114648, Singer C11930ND, Rootes 9660121                                  |   |
| Fuel Pump Washer oil seal, fabric                              | 34  | 500296  | AC 1524573   |   |
| Fuel Pump Repair Kits: Major Minor Diaphragm Priming lever set |     |         | AC37<br>AC BD3, 1524632<br>AC11524097<br>AC1524223, 1524325, Rootes K19781 |   |
| Petrol Tank Drain Plug, from TT8959                            | 110 | 103222  |  | Triumph TR2-6, TR250, Stag                                |
| Petrol Pipe Tubing Nut   | 111 | 60176   |  | Triumph Spitfire, TR2-5                                   |
| Tubing Nut, female pipe to flex                                | 111 | 60141   |  | TR3   |
| Tubing Nut, male pipe to tank                                  | 111 | 60142   |  | Triumph TR2-6, TR250                                      |
| Air Silencer Tubing Nut  | 40  | 101302  |  | Triumph Spitfire, Herald, Vitesse, GT6, TR2-6, 2000, 2500 |
| Air Silencer (home)  | 40  | 200344  | AC 1579553   |   |
| Petrol Flexi pipe  | 111 | 103070  | Smiths PFP111, Titeflex GT32   |   |
| Petrol Tank Filler Neck  | 110 | 600481  |  | Standard Vanguard Ph 1                                    |
| Petrol Filler Pipe Rubber Connection                           | 110 | CD25567 |  | Standard Vanguard Ph 2                                    |

# COOLING

| Component  | Parts<br>List<br>Page | Stan<br>part<br>No | Possible Manufacturer Part No(s)                                | May also be fitted to/ Possible alternative |
|------------|-----------------------|--------------------|---|---|
| Thermostat | 16                    | 100876             | AC 1572001, 1572115, AC Sphinx 16B/5769,<br>AC1, Quickstat WB1A | Land Rover Mk2 Ser 2                        |

| Thermostat Gasket                   | 16  | 101657 | Unipart GTG 103, Payen 13815  | Triumph Spitfire, TR3   |
|-------------------------------------|-----|--------|---|---|
| Water Elbow Gasket                  | 16  | 57103  | Unipart GTG 103, Payen 11383, KR351   | Triumph Spitfire, TR3, Standard Vanguard Ph 1-3, Vignale, Ensign, Sportsman                                     |
| Radiator Top Hose                   | 108 | 101466 | QH RH225, Harmo 225, Drayco 71790<br>(modify to fit)                                | Simco 693; Austin Allegro 1500, 1750; Ford Fiesta Mk2 1983-89; VW Polo 1981-94, Standard Vanguard Ph 1-2, TR2-4 |
| Radiator Bottom Hose                | 108 | 200280 | QH RH1157 (cut to fit), Harmo 228, Holdtite<br>M1938                                | Rover 2000; Austin Allegro 1500, 1750; Ford Fiesta Mk2 1983-89; VW Polo 1981-94                                 |
| Bypass Hose                         | 16  | 101656 | John Bull 309, QH RH309   | Toyota Celica, Corona, Hi-Lux, Pickup; Mini top hose (QH RH595)   |
| Heater Tubing Nut                   | 168 | 101302 |   | TR3   |
| Radiator Drain Tap                  | 108 | 101416 |   | Triumph Spitfire  |
| Radiator Filler Cap                 | 108 | 422222 |   | Standard Vanguard Ph 1  |
| Water Pump, body only               | 28  | 200198 |   | Standard 8, 10 1953-9; Atlas Van 1958-65; Triumph Herald, Spitfire, Vitesse, 2000, 1300, TR5, GT6               |
| Water Pump Impellor                 | 28  | 101400 |   | Standard 8, 10 1953-9; Atlas Van 1958-65; Triumph Herald, Spitfire, Vitesse, 2000, 1300, TR5, GT6               |
| Water Pump Bearings                 | 28  | 100764 | Hoffman N2897V2, SKF G-8016   | Triumph Spitfire, TR5,6   |
| Water Pump Seal                     | 28  | 100858 | Payen NB020, W126   | Triumph Spitfire, TR2/3, Standard Vanguard Ph 1-3, Vignale, Ensign, Sportsman                                   |
| Water Pump Bearing Seal             | 28  | 60313  | Payen NB016, W105, Burtonwood 6519,<br>Humphrey ST27                                | Triumph Spitfire, TR3,5,6   |
| Water Pump Plug                     | 28  | 57216  | Leyland 114774  | TR3; MG Midget 1500 (sump & gearbox); Standard Vanguard, Ensign (sump, diff & gearbox)                          |
| Water Pump Gasket, housing to body  | 28  | 100847 | Leyland 138701, 138201  | Triumph Herald, Vitesse, GT6, Dolomite & Sprint, 2000/2500, TR5/6   |
| Water Pump Gasket, pump to cyl head | 28  | 100820 | Payen 13159, KA042  |   |
| Water Pump Heater Adaptor           | 30  | 101343 |   | Triumph TR2-6, Herald, Vitesse, Spitfire, GT6, 2000/2500  |
| Water Pump Circlip                  | 28  | 500047 |   | TR3,5,6   |
| Water Pump Circlip                  | 28  | 100851 |   | Triumph Spitfire, TR5,6   |
| Water Pump Distance Piece           | 28  | 100760 |   | TR2/3   |
| Fan Belt                            | 30  | 200203 | Edmunds Walker EWB B33, Ferodo V564,<br>V513, Belaco 211R, Challenge UK Classic B34 |   |
| Fan Balance Piece                   | 30  | 38665  |   | Triumph Spitfire  |
| Fan Assembly                        | 30  | 200826 |   | Standard Vanguard Ph 1-3, Vignale, Ensign, 6 Cyl, Sportsman   |

## **ELECTRICALS**

| Component                              | Parts<br>List<br>Page | Stan<br>part No  | Possible Manufacturer Part No(s)   | May also be fitted to/ Possible alternative  |
|--|-----------------------|------------------|--|--|
| Coil                                   | 116                   | 200327           | Lucas Q12, 45020B, LA12, 45053, DLB100, 45074, DLB101, 45213                                     | All Standard Triumph models from 1934 Gloria to 1970 Triumph 2000  |
| Radio Suppressor                       | 115                   | 52200            | Lucas 78105A   |  |
| Distributor                            | 116                   | 200326           | Lucas DKYH4A, 40232A/B   |  |
| Distributor Base Plate                 |                       |                  | Lucas 409613   | Fits distributors DKY4A, DKYH4A, DKY2A, DK24A  |
| Distributor Cap                        | 116                   | 57467            | Lucas 409635, 418888, 421324, DDB111,<br>XD56, 410591  | Austin A40 1948-52; Citroen 1950-52; Humber Hawk 1946-53; Jowett Javelin 1951-54; Triumph 14, 18T, 18TR, 1800 1939-40; Standard 8, 10, 12, 14 1946-48; Sunbeam 10,80 1946-50; MG 1947-52; Morgan 1949-50; Lea Francis 1951-53; also Ford 100e fits |
| Distributor Bearing/bush, top          | 116                   | 59773            | Lucas 404374   | MG TC 1948-9; Austin A40 Devon 1949-53; Hillman Minx 1948-55, Husky 1955-7; Singer 9HP 1948-50; Morgan Plus 4 1948-50; Jaguar 3½L 1947   |
| Distributor Bearing/bush, bottom       | 116                   | 59774            | Lucas 410590   |  |
| Distributor Carbon Brush & Spring      | 116                   | 57468            | Lucas 404435, HT55   |  |
| Distributor Driving Dog                | 116                   | 57991            | Lucas 410601   | TR2/3, Standard Vanguard Ph 1-3, Vignale, Ensign, Sportsman  |
| Distributor Peg For Dog                | 116                   | 57992            |  | Triumph TR2-4A   |
| Distributor Cam                        | 116                   | 59769            | Lucas 420588   |  |
| Condensor                              | 116                   | 58308            | Lucas DCB101C, DCB121C, 400308, 422368, 424535, 407044, 409613                                   |  |
| Contact Points                         | 116                   | 57470            | Intermotor INT22500, Lucas DSB122C,<br>DSB139, DSB112 CS14, 407050,<br>488657,491255, Park PB101 |  |
| Rotor Arm                              | 116                   | 57469            | Lucas DRB101C, 400051, 405468, RA1, R101, Park PB32  | TR2/3  |
| Spark Plugs                            |                       |                  | Champion NA8, N5C, N5, N8, N8B, NGK<br>B6ES, BP6ES, Bosch W145T2                                 |  |
| Starter Motor to TT1000<br>from TT1001 | 115                   | 200325<br>200535 | Lucas M35G/1, 25022, 25034A/B<br>Lucas 25022A/F/L, 25149   | Austin A30, A40 Devon & Somerset; Hillman Minx Mk4-6, Californian; MG TD; Morris Minor; Singer 9; Vauxhall E Series, Wyvern & Velox; Wolseley 4/44; Triumph Spitfire, Standard Vanguard 6 cyl  |
| Starter Motor Switch                   | 115                   | 101253           | Lucas 76423A   | Austin A50, A55; Hillman Husky, Minx; MG Midget MK1, TD, TF, MGA; Morris Minor, Oxford   |
| Starter Motor Switch Coupling          | 115                   | 101254           | Lucas 764428   | MGA,Y; Morris Minor  |

| Starter Motor Brushes/Springs                       |            |                  | Lucas 251108/9, Remax CB500/ES1591, BMC 7H5040/3                              |   |
|---|------------|------------------|---|---|
| Starter Motor Bush commutator end drive end         | 115        | 500926<br>500927 | Lucas 250626, Remax ES453, BMC 7H5042<br>Lucas 250678, Remax ES457, BMC 7H678 | Triumph Spitfire; Austin 7; MG A, TD&TF Triumph Spitfire  |
| Starter Motor Armature                              | 115        | 70052            | Lucas 250851  |   |
| Starter Bendix                                      |            |                  | Lucas TLB   | Leyland Mini  |
| Starter Motor Main Spring                           | 115        | 70057            | Lucas 250404, Remax SB16, BMC 7H5045  | Mini Mk1&2; Austin Healey Sprite, A30 1952-56, A35 1957-; MG Midget, TD & TF 1950-55; Jowett Javelin 1948-54, Jupiter 1951-54   |
| Starter Motor Pinion & Sleeve to TT1000 from TT1001 | 115<br>115 | 70051<br>500892  | Lucas 250698<br>Lucas 250698, Remax SB43, BMC 7H5046                          | Triumph Spitfire, TR250, TR3 Triumph Spitfire, TR250, TR3, Standard Vanguard 6 cyl  |
| Starter Motor Sundry Parts Kit                      | 115        | 70391            | Lucas 256726  | Triumph Spitfire, TR2-4A, TR250   |
| Dynamo to TT6155                                    | 115        | 60950            | Lucas C39PV/2, 22258, 22250F  | Austin A40 Devon; Bristol 401; Citroen Light 15; Hillman Minx Mk4; Humber Hawk Mk4; Jowett Javelin; Morgan Plus 4; Morris Minor, Oxford MO, Cowley; Riley RME; Landrover; Singer 9; Triumph Renown; Vauxhall Wyvern, Velox; Wolseley 4/50 1951-2; Standard Vanguard |
| from TT6156   |            | 200657           | Lucas 22258D, 22715   | Triumph TR2-4A  |
| Dynamo Brushes                                      | 115        | 59743            | Lucas 227305, 22258, Park DB15, Remax<br>CB405, BMC 7H5028                    | MG A, TD&TF Austin Healey Sprite, TR2/3, Standard Vanguard Ph 1-3, Vignale, Ensign, Sportsman   |
| Dynamo Bearing , commutator end                     | 115        | 70033            | Lucas 227713, Remax ES489   |   |
| Dynamo Bearing, drive end                           | 115        | 70027            | Lucas 189307  |   |
| Dynamo Oiler  | 115        | 70046            | Lucas 238367  |   |
| Dynamo Spring Set                                   | 115        | 57577            | Lucas 228159, Remax ES1564, BMC 7H5031  | TR2/3   |
| Dynamo Bracket, drive end                           | 115        | 59748            | Lucas 227698  |   |
| Dynamo Armature                                     | 115        | 59751            | Lucas 227693  |   |
| Dynamo Field Coils                                  | 115        | 59752            | Lucas 227291  |   |
| Dynamo Sundry Parts Set                             | 115        | 70388            | Lucas 227726  |   |
| Dynamo Pedestal                                     | 26         | 59015            |   | Triumph Vitesse, TR2-4A   |
| Dynamo Fan Assembly                                 | 26         | 102968           |   | TR3   |

| Windscreen Wiper Motor                | 117 | 300238 | Lucas CR5, CRT15             | Motor from Morris 1000 or Mini may fit.  |
|---------------------------------------|-----|--------|------------------------------|--|
| 1950                                  |     |        | 75064J                       | Austin A40 Devon, Dorset 1948-59, Austin A70 Hampshire 1948-50, Triumph Renown 1950  |
| 1951                                  |     |        | 75064K                       | Austin A40 Devon, Dorset, Sports 1951, Singer SM1500 1951-52, Triumph Renown 1951  |
| 1952-3                                |     |        | 75145A                       | Austin A40 Devon, Dorset 1952, Austin A40 Sports 1951-53, Austin A90 Atlantic 1952, Austin Metropolitan 1957-69, Nash Metropolitan 1954-60, Singer SM1500 1953-54 Singer Hunter 1955-56, Triumph Renown 1952-54  |
| Windscreen Wiper Brush Set            | 117 | 59491  | Lucas 729367                 | See above  |
| Brush Gear                            |     |        | Lucas 733661                 | See above  |
| Armature                              |     |        | Lucas 739731                 | See above  |
| Field Coils                           |     |        | Lucas 739734                 | See above  |
| Guide wheel & plate                   |     |        | Lucas 738909                 | See above  |
| Windscreen Wiper Motor Fixing Plate   | 117 | 700305 | Lucas 741628                 |  |
| Windscreen Wiper Wheelbox             | 117 | 500528 | Lucas 72616A                 | Triumph Renown 1950-51, TR2-3  |
| Windscreen Wiper Crosshead & Rack     |     |        | Lucas 736177                 | AC Cars 16hp Saloon 1948-49, Allard 16hp 1949, Allard J,J2,J2X 1951, Allard P,M 1949-50, Armstrong Siddeley Hurricane, Lancaster, Typhoon 1956-51, Armstrong Siddeley Whitley 1950-52, Austin A70 Hereford 1951-55, Austin A70 Countryman, Pickup 1952-55, Bristol X404 1954, Citroen 15hp 1949-52, Citroen 23hp 1949-55, Daimler 2.5l Consort 1950-53, Healey 16hp Saloon 1948-49 Healey Sportsmobile 1949, Hillman Minx 1948, Jaguar XK120 1951-54, Jowett Javelin 1948-51, Morgan Plus 4 1951-55, Triumph Renown 1950-51, Triumph TR2 |
| Windscreen Wiper Arm RHD              | 117 | 500537 | Lucas 737525, 742270, 737903 | Morris Oxford 1948-54, Morris Traveller 1953-54, Morris 6 Saloon 1948-54, Standard 8, 10 1954-56, Standard Vanguard 1948-50, Wolseley 4/50 1949-53, Wolseley 6/80 1949-54  |
| LHD                                   | 118 | 61237  | Lucas 737526, 742271         | As above   |
| Windscreen Wiper Blade                | 118 | 58304  |                              | Standard Vanguard Ph 1   |
| Steering Column Control Head Assembly | 117 | 102553 | Lucas 32827L                 |  |
| Steering Column Stator Tube TT3984 on | 117 | 102554 | Lucas 324937                 |  |

| Horns High note  Low Note            | 116 | 58024<br>58025   | Lucas 43643, 43644, 69012F/H, 069504  Lucas 43643, 43644, 69011F/H, 069504 | Austin A40 Devon, Dorset, Somerset 1948-54, Austin A40 Van, Countryman, Pickup 1950-55, Austin A40 Sports 1951-53, Austin A70 Countryman, Pickup 1952-55, Austin A90 Atlantic 1949-52, Citroen 15hp 1949-50, Humber Hawk 1949-55, Humber Imperial, Pullman 1951-54, Super Snipe 1951-55, Jenson 4ltr Intercepter 1950-55, Jowett Javelin 1948-54, Lanchester 1951-53, MG Magnette 1954-55, Morgan Plus 4 1954-56, Morris Oxford 1950-55, Morris Traveller 1953-55, Morris 6 Saloon 1948-54, Nash Meropolitan 1954-56, Rover 60 1954-55, Rover 75 1950-55, Singer SM1500 1949-54, Standard Vanguard 1948-55, Sunbeam Alpine 1953-54, Sunbeam Talbot 90 1951-54, Triumph TR2 1955-56, Triumph Renown 1950-54, Vauxhall Wyvern, Velox, Cresta 1948-55, Wolseley 4/44 1953-55, Wolseley 4/50 1949-53, Wolseley 6/80 1949-54 |
|--------------------------------------|-----|------------------|--|---|
| Horn Contact Assembly                | 117 | 501033           | Lucas 321824   | TR2/3   |
| Horn Cam, Pawls & Spring Set         | 117 | 500997           | Lucas 324527   | TR2/3   |
| Horn Sundry Parts Set                | 117 | 501034           | Lucas 324882   | TR2/3   |
| Horn Push Spring                     | 117 | 501043           | Lucas 322093   | TR2/3   |
| Horn Top Cover Assembly              | 117 | 501041           | Lucas 323926   | TR2/3   |
| Horn Rotor Plunger                   | 117 | 500996           | Lucas 322150   | TR2/3   |
| Number Plate Lamp                    | 122 | 61272            | Lucas 53093E (1 bulb), Lucas 53836 (2 bulb), 467/2, 53101E,                | Austin A30 1952-55, Austin A40 Sports 1951-53, Hillman Minx 1948-53, Jowett Javelin 1952-54, Mini pre 1972; Morris Minor 1000, Morris Cowley 1955-59, Morris Oxford 1950-51, Morris 6 1948-50, MG Midget, MGA 1949-60, Reliant Regal 1953-54, Rover 75 1948-49, Landrover 1951, Standard Vanguard Ph2   |
| Glass For Number Plate Lamp          | 122 | 500492           | Lucas 572596   | Triumph Spitfire, Standard Vanguard Ph 2  |
| Cover for number plate lamp          |     |                  | Lucas 572603   |   |
| Dip Switch                           |     |                  | Lucas 31284A, FS22/1   | Triumph Renown; Morris Minor  |
| Brake Light Switch                   | 101 | 56865            | Lucas 31082B/D, 34542, 34765   | Triumph Renown, TR3   |
| Fuse Box                             | 116 | 101932           | Lucas SF4 type L24, 37134A, 033240, SF6                                    | Triumph TR2-4A; Morgan Plus4; AC ACE & ACEAC 1955-60  |
| Control Box to TT6155<br>from TT6156 | 116 | 101929<br>101931 | Lucas RB106, 37126, 37048E<br>Lucas 37138B, 37182                          | Morgan Plus 4 1951-53; Daimler DC27 Ambulance 1949; AC 16hp 1952-57 Triumph Renown; Austin A30 Seven 1952-56, Austin A40 Devon, Somerset, Cambridge 1951-55, A50 Cambridge 1955, Austin A40 Van, Countryman, Pickup 1951-55, A40 Sports 1951-53, Morris Minor Saloon, Traveller 1952-55, Nash Metropolitan 1954-55, Landraver 1952-55, Standard 8, 10 1954-55, Standard Vanguard 1951-55, Wolseley 4/50; Triumph TR2 1954-55, Triumph Renown 1952-54, Ford Anglia 1961-68   |
| Control Box Cover                    | 116 | 500729           | Lucas 391600   | See above   |

| Headlamp Assembly (RHD) TT4218 on    | 120 | 500481  | Lucas F700, 51010A                             | Standard Vanguard Sal/Est Ph 1&2 1951-54, Sunbeam Talbot 90 1952   |
|--------------------------------------|-----|---------|--|--|
| to TT4217 LH)                        |     | 61905   | Lucas 50835A                                   | Standard Vanguard Sal/Est Ph 1&2 1950-51   |
| to 4217 (RH)                         |     | 61903   | Lucas 50836A                                   | Standard Vanguard Sal/Est Ph 1&2 1951  |
| Headlamp Light Unit (RHD) TT4218 on  | 120 | 500518  | Lucas 553921                                   | See above  |
| to TT4217                            |     |         | Lucas 59782                                    | See above  |
| Headlamp Assembly (LHD not France)   | 120 |         |  |  |
| 1952-3                               |     | 501105  | 51011A   |  |
| TT3264 to ?                          |     | 500483  | 50968A   |  |
| to TT3263                            |     | 61907   | B50835A  |  |
| Headlamp Assembly (LHD France)       | 120 |         |  |  |
| 1950-52                              |     | 501106  | Lucas F700EF, 51329A                           |  |
| 1953                                 |     | 61908   | Lucas 50837A                                   |  |
| Headlamp Ring                        | 132 | CD24401 |  | TR3, Standard Vanguard Ph 1-2  |
| Headlamp Outer Rim                   | 120 | 59779   | Lucas 552949                                   | Standard Vanguard Ph 1   |
| Headlamp Inner Rim                   |     |         | Lucas 552816                                   |  |
| Headlamp Rubber Excluder             |     |         | Lucas 552906                                   |  |
| Headlamp Rubber Gasket (lamp to car) |     |         | Lucas 552996                                   |  |
| Panel/Roof Light Switch              | 118 | 58033   | Lucas PPG2, 31114A/D                           | Triumph Renown 1950-54; Austin A40 Devon, Dorset, Van, Countryman, Pickup, 1948-51, A50, A125; Jaguar 3.5ltr MkV, VII 1951-58; Armstrong Siddeley Sapphire 1953-55, Standard Vanguard 1948-57  |
| Panel/Roof Light Switch Knob         | 118 | CD25594 | Lucas 315215                                   | Standard Vanguard Sal/Est Ph 1&2 1948-57   |
| Wiper Switch                         | 118 | 58036   | Lucas PS16, 31113D/A                           | Rover 75 1950; Austin A40 Devon, Dorset, Van, Countryman, Pickup, 1948-51; Austin A70 Hampshire, Hereford 1948-55, Austin A90 Atlantic 1949-52, Jaguar 3.5ltr MkV, VII 1951-58; Armstrong Siddeley Sapphire 1953-55, Standard Vanguard 1951-57, Triumph Renown 1950-54   |
| Wiper Switch Knob                    | 118 | CD25596 | Lucas 315121                                   | Standard Vanguard Sal/Est Ph 1&2 1948-57   |
| Trafficator                          | 118 | 58029   | Lucas 54039A, 54044A/D, 053981, SF80,<br>SF34N | Austin A40, Devon, Somerset, Cambridge 1952-56, Austin A40 Sports 1951-53, Humber Hawk 1951-52, Super Snipe 1953; Jaguar 2.5ltr, 3.5ltr 1950-54; Morris Minor 1953-56, Riley 1.5ltr 1951-52, Riley 2.5ltr 1950-52, Rover 75 1951-52; Standard Vanguard 1951-56, Wolseley 6/90 1955-59, Morgan Plus 4 1946-55, Triumph Renown 1950-54 |
| Trafficator Arm                      | 118 | 59794   | Lucas 581175, 582026                           | Austin A40, Devon, Somerset, Cambridge 1952-56, Austin A40 Sports 1951-53, Humber Hawk 1951-52, Super Snipe 1953; Jaguar 2.5ltr, 3.5ltr 1950-54; Morris Minor 1953-56, Riley 1.5ltr 1951-52, Riley 2.5ltr 1950-52, Rover 75 1951-52; Standard Vanguard 1951-56, Wolseley 6/90 1955-59, Morgan Plus 4 1946-55, Triumph Renown 1950-54 |

| Trafficator Cover                               | 118 | 59797            | Lucas 581124, 582027                                     | Austin A40, Devon, Somerset, Cambridge 1952-56, Austin A40 Sports 1951-53, Humber Hawk 1951-52, Super Snipe 1953; Jaguar 2.5ltr, 3.5ltr 1950-54; Morris Minor 1953-56, Riley 1.5ltr 1951-52, Riley 2.5ltr 1950-52, Rover 75 1951-52; Standard Vanguard 1951-56, Wolseley 6/90 1955-59, Morgan Plus 4 1946-55, Triumph Renown 1950-54 |
|---|-----|------------------|--|--|
| Trafficator Lead                                | 118 | 59796            | Lucas 539698, 582021                                     |  |
| Trafficator Switch Base                         | 117 | 501032           | Lucas 323438   |  |
| Trafficator Switch Lever                        | 117 | 501042           | Lucas 323808   | TR2/3  |
| Heater/Fan Switch                               | 166 | 101934           | Lucas 31201, 31202A, PS7                                 | Triumph TR2-3; Morris Minor; Mini; MGA&B, TD&TF  |
| Heater/Fan Switch Knob                          | 118 | 600310           | Lucas 316221   |  |
| Ignition & Light Switch                         | 118 | 101255           | Lucas PRS2, 31194A/B                                     | Austin A40 Dorset, Somerset 1952-54, Austin A40 Sports 1951-53, Austin A70 Hampshire, Hereford 1948-55, Austin A70 Countryman, Pickup 1952-55, Austin A90 Atlantic 1949-52, Landrover Ser1   |
| Ignition & Light Switch Knob                    | 118 | 104297           | Lucas 316276   | Austin A90 Atlantic 1949-52, Morgan Plus 4 1955-60   |
| Side lamp                                       | 120 | 61834            | Lucas 52139B, 489  |  |
| Side Lamp Rim & Glass                           | 122 |                  |  | Standard Vanguard Ph 1-2   |
| Side lamp rim                                   | 122 | 70341            | Lucas 572776   |  |
| Side lamp lens                                  | 122 | 70340            | Lucas 572772   | Standard Vanguard Ph 1   |
| Side lamp bulb holder                           |     |                  | Lucas 572767   |  |
| Side lamp cable sleeve                          | 122 | 500040           | Lucas 572763   | Standard Vanguard Ph 2   |
| Rear Light                                      | 122 | 101257           | Lucas 488, 53178D,53211A/H/J                             |  |
| Rear Light Lens                                 | 122 | 500496           | Lucas 572704   | Morris 1000 Traveller  |
| Rear Light Rim                                  | 122 | 500495           | Lucas 572734   | TR3  |
| Rear Light Bulb Holder                          | 122 | 200716           | Lucas 552101   | Morris 1000 Traveller  |
| Front & Rear Light Rubbers                      | 122 | 500497           | Lucas 572733   | Morris 1000 Traveller; Mini Indicator  |
| 3-in-1 Panel assembly (TT1-2176)<br>(TT2177-)   | 117 | 200476<br>102965 | Smiths IP 3205-00<br>Smiths IP 3205-02, X 70907/4 PA 128 |  |
| Petrol Gauge, dash unit (TT1-2161)<br>(TT2162-) | 117 | 101679<br>102723 | Smiths FG 6231-01<br>Smiths FG 6231-02, X 76150/2 PG 147 |  |
| Petrol Gauge, tank unit (TT1-8958)<br>(TT8959-) | 117 | 200477<br>200900 | Smiths FT 5320-18<br>Smiths FT 5366-08                   |  |
| Thermometer assembly (TT1-2161)                 | 117 | 101681           | Smiths TG 6202-00 5'                                     |  |
| Grommet for capiliary                           | 117 | 600395           | Smiths 31-781-302  |  |
| Oil Pressure Gauge                              | 117 | 101680           | Smiths PG 6601-00  |  |

| 118        | 54902  | Smiths 31-752-119   |                          |
|------------|--|---|--------------------------|
| 116        | 200499<br>102965   | Smiths SN 5311-01<br>Smiths SN 5311-05, Jaeger X 76392/9 S562<br>1600   |                          |
| 116<br>117 | 200500<br>102964   | Smiths SN 5311-02<br>Smiths SN 5311-06  |                          |
|            | 200374<br>200375   | Smiths SN 7509-01<br>Smiths SN 7509-02  |                          |
|            | 103018<br>103019   | Smiths SN 7509-11<br>Smiths SC 70 K   |                          |
| 117        | CD26074  | Smiths 41-741-111-07  | Standard Vanguard Ph 1-2 |
|            |  | Smiths F 275/57748, DF 1104-00 4'6"<br>Smiths F 283/57748, DF 1104-00 5'3"  |                          |
| 118<br>120 | 400081/I<br>400085/I                                       | Smiths I 135/52108/1, DI 1110-00 4'6"<br>Smiths I 143/52108/1, DI 1110-00 5'3"  |                          |
| 120<br>120 | 400081/O<br>400085/O                                       | Smiths O/F 275/57749, DO 1104-00 4'6"<br>Smiths O/F 283/57749, DO 1104-00 5'3"  |                          |
| 118        | 57599  | Lucas 256 12V 3W festoon  |                          |
| 120        |  | Lucas 354, Lucas/Lumax LLB414 12V 50/40W  | Triumph Spitfire, TR3    |
| 122        | 59467  | Lucas 989 12V 5W  |                          |
| 122        | 500070   | Lucas 380 12V 21/5W, Lucas 353 12V 6/24W, Lucas 361   |                          |
| 122        | 59467  | Lucas 989 12V 5W, Lucas 994 12V 4W  | Triumph Spitfire, TR3    |
| 123        | 600715   | Lucas 254 12V 6W festoon  |                          |
| 122        | 101933   | Lucas 38048A  |                          |
| 122        | 58031  | Lucas 304862  |                          |
| 122        | 59492  | Lucas 987 12V 2.2W screw cap  | Triumph Spitfire, TR3    |
| 122        | 59492  | Lucas 987 12V 2.2W screw cap  | Triumph Spitfire, TR3    |
|            | 116  116  117  117  118  120  120  122  122  122  122  122 | 116 200499<br>102965  116 200500<br>117 102964 200374<br>200375 103018<br>103019 117 CD26074  118 400081/I<br>400085/I 120 400081/O<br>400085/O  118 57599 120 122 59467 122 500070 122 59467 123 600715 122 101933 122 58031 122 59492 | 116                      |

#### **RUNNING GEAR**

| Component   | Parts<br>List<br>Page | Stan<br>part No            | Possible Manufacturer Part No(s)   | May also be fitted to/ Possible alternative  |
|---|-----------------------|----------------------------|--|--|
| Front Hub Grease Seal   | 66                    | 100867<br>100868           | Payen 14198, KG166<br>Payen NA980, Halls L102, Humphrey ST53   | Triumph TR2, TR3, TR3A, TR4, TR4A (all 1953-57), Herald 1959-62, Herald 13/60, TR5 & TR6 1967-75   |
| Rear Hub Oil Seal   | 88                    | 103811                     | Payen C404, C472, NA303, NA280,<br>Burtonwood 150-225-12, Humphry GM68,<br>MS28, McCord 80141, National 50548,<br>1026, Standard 43-944, Victor 4827, 60498,<br>63298, 44059, Weston (Gitseal) 22515037,<br>Angus (Gaco) B3943 | Triumph TR2 1953 on, TR3; Morris Minor Series MM 1949-52, ser2 1952-3; Hillman Minx gearbox rear 1949-56; Humber Snipe Pullman 1-4 gearbox front 1948-56; Armstong Siddeley Sapphire 346 gearbox front 1952-9  |
| Front Wheel Brake Cylinder to TT14829  from TT14830             |                       | 103278<br>201098/9         | Lockheed 30284, BP3  Lockheed BQ1, 35000/1. Moss 180-640   | Hillman Minx Mk3-6; Humber Hawk Mk3-5; MG TD & YB, Midget; Morris Six 21 hp 1949-54, Oxford MO Series1 1949-54; Triumph TR2, TR3, Renown; Singer SM 1500 1949-54, Hunter, Hunter S; Standard Vanguard Ser 1 & 2 1948-56; Sunbeam Talbot 90 Mk 2/2A; Wolseley 4/44 1953-56, 4/50 1949-53, 15/50 1956-59, 6/80 1949-54 Austin Sprite 1958-61 & some Mk2; Hillman Minx Mk 7-8; Humber Hawk Ser1 & 1A; MG Midget 1961-62, MGA; Morris 8 hp Ser 2 & Traveller 1953-60, Cowley 1200 1955-56, Cowley 1500 1956-59, Oxford Ser3 1957-58, Minor 1000 1957-60; Triumph TR2; Sunbeam Mk3 1954-55, Alpine Mk3 1955-57; Wolseley 4/44 1953-56 |
| Front brake assembly RH TT1-TT1450 TT1451-TT7436 TT7437-TT14828 | 95                    | 200226<br>200756<br>200918 | Lockheed 30382<br>Lockheed 30378<br>Lockheed 33776   |  |
| Front brake assembly LH TT1-TT1450 TT1451-TT7436 TT7437-TT14828 | 95<br>96              | 200228<br>200757<br>200919 | Lockheed 30383<br>Lockheed 30379<br>Lockheed 33777   |  |
| Back plate RH TT1-TT14829<br>TT14830 on                         | 95                    | 200227<br>201096           | Lockheed 28431<br>Lockheed 29336   |  |
| Back plate LH TT1-TT14829<br>TT14830 on                         | 96                    | 200229<br>201097           | Lockheed 28432<br>Lockheed 29367   |  |
| Front wheel cylinder body to TT14829                            | 97                    | 59251                      |  | Standard Vanguard Ph1, 2   |
| Front wheel cylinder body RH TT14830 on                         | 97                    | 103842                     | Lockheed 34998   |  |
| Front wheel cylinder body LH TT14830 on                         | 97                    | 103843                     | Lockheed 34999   |  |
| Front Wheel Brake Cylinder Repair Kit from TT14830              |                       |                            | Lockheed KL71496 , Moss 180-458, 8G8243  |  |

| Front Brake Cylinder Cup to TT14829               | 97         | 59253   | Lockheed 586   | TR2/3   |
|---|------------|---------|--|---|
| from TT14830                                      | 97         | 103845  | Lockheed 9580  | TR3   |
| Front Brake Cylinder Cup Filler to TT14829        | 97         | 102735  | Lockheed 29574   | Triumph TR2/3   |
| from TT14830                                      |            | 103846  | Lockheed 29328   | TR3   |
| Front Brake Cylinder Piston Assembly from TT14830 | 97         | 103844  |  | TR2/3   |
| Front Brake Cylinder Rubber Seal from TT14830     | 97         | 103847  | Lockheed 30449   | TR2/3   |
| Piston Assembly TT1-TT14829                       | 97         | 59252   | Lockheed 25277   | Standard Vanguard Ph1, 2  |
| TT14830 on  |            | 103844  | Lockheed 33667   |   |
| Rear brake assembly RH TT1-TT14829                | 97         | 200920  | Lockheed 33778, 30380  |   |
| Rear brake assembly LH TT1-TT14829                | 98         | 200921  | Lockheed 33779, 30381  |   |
| Rear back plate RH                                | 97         | 200231  | Lockheed 28435   |   |
| Rear Wheel Brake Cylinder                         | 98         | 200914  | Lockheed BX2, 30285, 33668, Moss 180-630                     | Hillman Minx Mk3-6; Humber Hawk Mk3-5; MG TD & YB, Midget; Morris 1000, Oxford Ser MO 1949-54; Triumph Renown, Standard Vanguard Ph 1, 2  |
| Rear Wheel Brake Cylinder Repair Kit              | 99         | 5000901 | Lockheed KL71569, KL71469, KL71506,<br>KL71496, Moss 180-470 | Humber Hawk Mk3, 4, 5; MGYB; Hillman Minx Mk2-6, 1948-53; Morris Oxford MO series 1949-54, Six 21 hp 1949-54; Triumph Renown; Standard Vanguard Ser 1 1948-56; Sunbeam Talbot 90 Mk2; Wolseley 4/50 1949-53, 6/80 1949-54 |
| Rear Brake Cylinder Cup                           | 99         | 59253   | Lockheed 586   | TR2/3, Standard Vanguard Ph1, 2   |
| Rear Brake Cylinder Cup Filler                    | 99         | 102735  | Lockheed 29574   | TR3   |
| Rear wheel cylinder body                          | 98         | 59260   | Lockheed 33673   | Standard Vanguard Ph1, 2  |
| Rear Wheel Cylinder Piston                        | 99         | 59261   | Lockheed 21692   | TR2/3, Standard Vanguard Ph1, 2   |
| Rear wheel cylinder service kit                   | 99         | 500901  | Lockheed KL71469   | Standard Vanguard Ph 1-2  |
| Rear wheel cylinder boot                          | 98         | 59255   | Lockheed 27699   | Standard Vanguard Ph1, 2  |
| Pivot Pin   | 99         | 59263   | Lockheed 36185   | Triumph TR2, TR3  |
| Piston assembly, handbrake                        | 99         | 59262   | Lockheed 366332  | Standard Vanguard Ph1, 2  |
| Handbrake lever                                   | 99         | 59264   | Lockheed 33674   | Standard Vanguard Ph1, 2  |
| Brake Pull Off Spring                             | 98         | 101825  | Lockheed 21814   |   |
| Tension spring                                    | 97         | 101826  | Lockheed 25553   |   |
| Brake Banjo connection                            | 98         | 59283   | Lockheed 22477   | TR2/3, Standard Vanguard Ph1, 2   |
| Brake Banjo connection bolt                       | 95-<br>101 | 59291   | Lockheed 94011   | TR2/3   |
| Gasket, small, cylinder front top                 | 95-<br>101 | 59245   | Lockheed KL44516   | TR2/3   |
| Gasket, large, cylinder front top                 | 95-<br>101 | 59246   | Lockheed KL44518   | TR2/3   |

| Spring   | 97/9         | 102736          | Lockheed 29368                                | TR2/3  |
|--|--------------|-----------------|---|--|
| Abutment Assembly                                    | 97/8         | 59256           | Lockheed 25294                                | TR3  |
| Bleed Screw, bottom banjo to TT14829<br>from TT14830 | 95-8<br>95-8 | 59248<br>102001 | Lockheed 21995<br>Lockheed 28696              | TR2/3, Standard Vanguard Ph 1, 2<br>TR2/3  |
| Brake/Clutch Pedal Return Spring                     | 48           | 27645           |   | Triumph TR2-6  |
| Brake/Clutch Pedal Oilite Bush                       | 48           | 100954          |   | Triumph TR2-4A   |
| Clevis Joint Assembly                                | 50           | 57190           |   | Triumph TR2-4A   |
| Brake Master Cylinder                                | 99           | 300868          | Lockheed NG7, 31232, 88187                    | Hillman Minx Mk3-8 1949-56; Humber Hawk Mk3-6; Standard Vanguard Ser 1 1948-56; Triumph Renown; Morris 1000  |
| Handbrake Cable Fork End, rear                       | 102          | 101247          |   | Triumph TR2-4  |
| Handbrake Compensator Bar                            | 103          | 100569          |   | Triumph TR2-4  |
| Handbrake Compensator & Boss                         | 103          | 100571          |   | Triumph TR2, TR3   |
| Handbrake Cable Pin, for jaw cab to comp             | 103          | PJ8708          |   | Triumph TR2-4, TR7   |
| Grease Nipple  | 103          | 500098          |   | TR3  |
| Felt Seal  | 103          | 100572          |   | Triumph TR2-4  |
| Master Cylinder Repair Kit                           | 100          | 500900          | Lockheed KL71408, Moss 180-910, BMC<br>8G7103 | Morris 1000, Oxford 13.5 hp ser MO 1949-54, Oxford Ser 3 1957-58, Six 21 hp 1949-54; Riley 2.6; Standard Vanguard Ser 1 1948-56; Sunbeam Mk3 1954-55, Alpine Mk3 1955-57, Talbot 80, 90, 90 Mk2, 90 Mk2A; Triumph Renown 1949-51; Wolseley 4/50 1949-53, 60/90 Ser3 1957-59; Austin Princess Mk4 1956-59, Vanden Plas Princess 1959-63 |
| Master Cylinder Piston                               | 99           | 59273           | Lockheed 21407                                | TR2/3  |
| Master Cylinder Piston Washer                        | 99           | 103020          | Lockheed 90865                                | TR2/3  |
| Master Cylinder Washer                               | 99           | 59268           | Lockheed 27591                                | Standard Vanguard Ph1  |
| Master Cylinder Valve Cup                            | 99           | 59269           | Lockheed 108128                               | TR2/3, Standard Vanguard Ph1   |
| Gasket For Master Cylinder Filler Cap                | 99           | 59279           | Lockheed KL46141                              | Standard Vanguard Ph1  |
| Plug For Cylinder                                    | 99           | 59280           | Lockheed 23558                                |  |
| Gasket For Plug                                      | 99           | 60221           | Lockheed KL46136                              |  |
| Master Cylinder Filler Cap                           | 99           | 59278           | Lockheed 89833                                | Standard Vanguard Ph1  |
| Master Cylinder Valve Body                           | 99           | 59267           | Lockheed 2379                                 | Triumph TR2/3  |
| Secondary Cup  | 99           | 59274           | Lockheed 87366                                | TR2/3  |
| Retaining Washer                                     | 99           | 59275           | Lockheed 101629                               |  |
| Circlip For Washer                                   | 99           | 59276           | Lockheed KL47011                              |  |

| Boot For Master Cylinder  | 99             | 59277                      | Lockheed 437   | Standard Vanguard Ph1   |
|---|----------------|----------------------------|--|---|
| Push Rod  | 99             | 59282                      | Lockheed 21413   |   |
| Master Cylinder Tank & Body                                     | 99             | 59266                      | Lockheed 25489   | Standard Vanguard Ph1   |
| Master Cylinder Piston Return Spring                            | 99             | 59270                      | Lockheed 21410   | Triumph TR2-4A  |
| Retainer For Spring   | 99             | 59271                      | Lockheed 90839   |   |
| Master Cylinder & tank body sub ass                             | 99             | 60220                      | Lockheed 25501   |   |
| Pipe, master cyl to front banjo, rhd                            | 100            | 200638                     | Lockheed T 15/050N   |   |
| Pipe, rh to lh front banjo TT1-14829                            | 100            | 200515                     | Lockheed T 15/033N   |   |
| Pipe, rh front to rear bracket                                  | 100            | 300360                     | Lockheed T 15/086N   |   |
| Pipe, top to bottom cyls TT1-14829                              | 100            | 101827                     | Lockheed T 35/013 50N  |   |
| Pipe, 3 way to rh rear  | 100            | 201129                     | Lockheed T 15/020N   |   |
| Pipe, 3 way to lh rear  | 100            | 201130                     | Lockheed T 15/043N   |   |
| Locknut, hose to frame brackets                                 | 100            | 59364                      | Lockheed 23897   | Standard Vanguard Ph 1-3, Vignale, Ensign, 6 Cyl, Sportsman   |
| Shakeproof washer, hose to frame brkts                          | 100            | WE0613                     | Lockheed K19411  |   |
| Banjo connection  | 100            | 59247                      | Lockheed 21990   |   |
| Stop light switch in banjo                                      | 101            | 59865                      |  | TR2/3   |
| Adaptor   | 100            | 102008                     | Lockheed 25611   |   |
| Brake Hose Rear   | 100            | 59950                      | Lockheed KL57306, KL101406L, KL48806,<br>KL56806   | Morris 8 hp 1949-52, Oxford 13.5 hp ser MO 1949-54, Oxford Ser 3 1957-58, Six 21 hp 1949-54; 1000 with modification; Hillman Minx MkII 1948 on front; Standard Vanguard Ser 2/3 rear, Pennant; Sunbeam Talbot 80 front/rear, Sunbeam Talbot 90 MkII/IIA rear; Saab 1950s front; Wolseley 4/50 front, early 6/8 front          |
| Brake Hose Front TT1-14829 11.5 ins<br>15.5 ins<br>from TT14830 | 100            | 103840                     | Lockheed KL57302, KL48802<br>KL57306, KL101406L, KL48806, KL56806<br>Lockheed KL57302, KL101203L, KL56503,<br>KL57203, KL48703, Motaproducts BH220   | Morris 8 hp 1949-52, Oxford 13.5 hp ser MO 1949-54, Oxford Ser 3 1957-58, Six 21 hp 1949-54; 1000 with modification; Hillman Minx MkII 1948 on front; Standard Vanguard Ser 2/3 rear, Pennant; Sunbeam Talbot 80 front/rear, Sunbeam Talbot 90 MkII/IIA rear; Saab 1950s front; Wolseley 4/50 front, early 6/8 front As above |
| Brake Shoes Front & Rear to TT14829 TT14830-TT21094 TT21095 on  | 98<br>98<br>98 | 101824<br>103841<br>105378 | Lockheed LB.29, KB1003, Belaco 101824<br>Lockheed LB.78, LB3132 AM8, 4523/092<br>AM8, KB1003, Belaco 101824<br>Lockheed KB1003, Mintex MLR4, Ferodo<br>F132L, Autela DL11, Small&Parks SL2,<br>Homer HLR 132 | Morris 1000; Hillman Minx 58-62<br>Morris 1000; Hillman Minx 58-62<br>Morris 1000; Hillman Minx 58-62   |
| 3 way piece, rear axle  | 101            | 59295                      | Lockheed 21993   |   |

| Brake Drum Set Screw to hub   | 66   | V5435                      |   | Triumph TR2,3,6,7, Spitfire, Herald, Vitesse, 2000/2500, GT6, Dolomite & Sprint                                |
|---|------|----------------------------|---|--|
| Micram adjuster assembly  | 98   | 59240                      | Lockheed 25254  | TR2/3, Standard Vanguard Ph 1-3, Vignale, Ensign, 6 Cyl, Sportsman   |
| Mask  | 95-8 | 59241                      | Lockheed 25253  | TR2/3, Standard Vanguard Ph 1-3, Vignale, Ensign, 6 Cyl, Sportsman   |
| Track Rod Ends (outer)  | 72   | 102692                     | Quinten Hazell 229, TRC 185                                 | TR3  |
| Track Rod Ends (centre)   | 72   | 100914                     | QH QR804, QR 230, B&A/Nobby TR 185,<br>Chorley SE 152       | Austin A40 Farina 1959-; Nash Metropolitan 1956-62   |
| Pinion Oil Seal   | 90   | 100898                     | Payen NA328, C571, Burtonwood 150-262-<br>19L, Humphrey T12 | Triumph TR2, TR3/A, TR4; Standard Vanguard Ph 1-3, Vignale, Ensign, 6 Cyl, Sportsman                           |
| Inner Front Suspension Wishbone Bush                                | 68   | 102228                     |   | Triumph TR2, TR3/A/B, TR4  |
| Front wheel Inner Bearing   | 66   | 100573                     | Timken K07100S- K07210X                                     | Triumph Spitfire, TR2/3  |
| Front Wheel Outer Bearing   | 66   | 100536                     | Timken K03062-K03162  | Triumph Spitfire, TR2/3  |
| Front Wheel Bearing Kit   |      |                            | QH QW107C, OE: GHK 1244                                     |  |
| Top Wishbone Assembly, front LH & rear RH                           | 70   | 100696                     |   | Triumph TR2-4  |
| Top Wishbone Assembly, front RH & rear LH                           | 70   | 100695                     |   | Triumph TR2-4  |
| Top Wishbone Distance Piece   | 70   | 100697                     |   | Triumph TR2-4  |
| Top Inner Fulcrum Pin   | 70   | 200659                     |   | Triumph TR2-4A, TR6  |
| Upper Wishbone Ball Assembly  | 72   | 200771                     | Leyland 200772, QH QSJ 102                                  | Triumph TR2-4; Daimler SP250   |
| Gaiter  | 72   | 100726                     |   | Triumph TR2-4, Standard Vanguard Ph 1-3, Vignale,, Ensign, 6 Cyl, Sportsman                                    |
| Lower Wishbone Outer Shackle Pin Grease<br>Seal                     | 68   | 101540                     | Leyland 115702  | Triumph TR3-4  |
| Lower Spring Pan Assembly   | 70   | 200193                     |   | TR2/3  |
| Front Stub Axle   | 66   | 100866                     |   | TR2/3  |
| Front Hub D Washer  | 66   | 102690                     |   | Triumph Spitfire, Herald, TR2-4A,6   |
| Front Shock Absorber to TT1451<br>TT1452 to TT25000<br>from TT25001 | 70   | 101095<br>103306<br>106151 | {Armstrong 62-2080, RF4038<br>{Armstrong AT7-1125<br>{      | { TR2-4 (Rimmer Bros RF4038)<br>{ Bedford (Monzof pn 622080) or Bedford Midi Van<br>{ (Monzof pn 1041) may fit |
| Rubber Washer , for coil spring                                     | 70   | 100751                     |   | Triumph TR2-4A,6   |
| Bottom Trunnion Sub Assembly  | 72   | 101557                     |   | Triumph TR2-4  |
| Bottom Trunnion Stop Lock   | 74   | 101407                     |   | Triumph TR2-4  |
| Trunnion Grease Nipple  | 72   | 56934                      |   | Triumph TR2-4A: Rover V8   |
| Trunnion Thrust Washer  | 68   | 101533                     |   | Triumph TR2-4  |

| Trunnion Lock Washer                                      | 68 | 101591           |   | TR3   |
|---|----|------------------|---|---|
| Trunnion & Link Oil Seal                                  | 68 | 58224            | Payen X142, Burtonwood 8217   | Triumph TR2-4   |
| Trunnion Bush   | 68 | 101615           |   | Triumph TR2-4   |
| Cap for Front Hub   | 66 | 102689           |   | Triumph Spitfire, Herald, TR2-4A,6  |
| Eye Bush, Shock Absorber                                  | 74 | 102987           |   | Triumph Spitfire, Herald, Vitesse, TR2-4, GT6   |
| Wheel Stud on hub   | 66 | 100869           |   | Triumph TR2-5   |
| Rear Axle Shaft   | 88 | 200196           | Regent 1114   |   |
| Rear Axle Taper Roller Bearing rear of pinion             | 90 | 100897           | Timken 3188S/3120   | TR2/3   |
| Rear Axle Taper Roller Bearing front of pinion            | 90 | 100422           | Timken 15100SR/15245  | Triumph TR2-6, 2000/2500, Dolomite & Sprint   |
| Rear Axle Slotted Nut                                     | 88 | 100892           |   | TR3   |
| Rear Hub Bearing  | 88 | 500031           | SKF/Timken 6206, Hoffman 130, RMLJ 30   |   |
| Bearing Differential Casing, front & rear                 | 88 | 100899           | Timken K16150/K16283  | Triumph TR2-6, 2000/2500, Stag  |
| Differential Gear   | 92 | 102800           |   | Triumph TR2-3   |
| Differential Pinion                                       | 92 | 100823           |   | TR2/3   |
| Breather on Pinion Housing                                | 88 | 56894            |   | Triumph TR2-4A, Standard Vanguard Ph 1, 2   |
| Cross Pin for Pinion                                      | 92 | 100844           |   | Triumph TR2-6, Stag   |
| Differential Cover Plate Gasket                           | 90 | 101359           |   | Triumph TR2-4A, Dolomite & Sprint, Standard Vanguard Ph 3, Vignale, Ensign, 6 Cyl, Sportsman  |
| Differential Filler Plug                                  | 90 | 62058            |   | TR2/3   |
| Differential Drain Plug                                   | 88 | 57216            |   | TR3; MG Midget 1500 (sump & gearbox); Standard Vanguard, Ensign (sump, diff & gearbox)  |
| Rear Shock Absorber (up to TT450)  (TT451 - )  (all cars) | 94 | 103307<br>106152 | Girling A7262, Gabriel 83406, Armstrong<br>AT7-1137<br>Girling A7262, Gabriel 83406, Boge 27-550-0<br>Armstrong AT7-1137, 62-1970/1, Girling<br>DAS 6, 4197, Woodhead LP 166 0-3134/5,<br>03528 | { Bedford (Monzof pn 622080) or Bedford Midi Van { Bedford Midi Van (Monzof pn 1041) may fit, Humber Sceptre; Mitsubishi L300, Austin Metro, Land Rover Mk1 |
| Rear Shackle Bush   | 94 | 101280           | QH Y145, ACA5242  | MG TD&TF 1949-53; Morris Minor MM 1948-52, Minor Ser 2 1952-56, Minor 1000 1956-71; Wolseley 1500 1957-65; Riley 1.5 1957-65                                |
| Rear Road Spring, rubber bush, front end                  | 94 | 47259            | Silentbloc AHH 5015   | MGA   |
| Rear Road Spring (up to TT450)<br>(TT451 - 927)           | 94 | 300351<br>300409 | Duraflex 2053<br>Duraflex 2057  |   |

| Steering Wheel                     | 76    | 300389 | Triumph TR2-3A   |
|------------------------------------|-------|--------|--|
| Steering Wheel Nut                 | 76    | 60372  | Triumph TR2-3A   |
| Steering Box Thrust Screw          | 78    | 500279 | Triumph TR2-3A   |
| Steering Box Thrust Screw Lock Nut | 78    | 60360  | Triumph TR2-3A   |
| Steering Idler Arm Oil Seal        | 72    | 58615  | Triumph TR2-3A, Standard Vanguard Ph 1, 2                      |
| Grease Nipple                      | 50/56 | 58392  | TR3, Standard Vanguard Ph 3, Vignale, Ensign, 6 Cyl, Sportsman |

# DRIVE

| Component               | Parts<br>List<br>Page | Stan<br>part<br>No | Possible Manufacturer Part No(s)             | May also be fitted to/ Possible alternative  |
|-------------------------|-----------------------|--------------------|--|--|
| Propellor Shaft         | 86                    | 102061             | Hardy Spicer KR1110, 49/0924                 |  |
| Flange Yoke             | 86                    | 500263             | Hardy Spicer 1402-039                        |  |
| Universal Joint Package | 86                    | 52405              | Hardy Spicer K5-L1, 1451-194Y, BMC<br>8G3000 | Morris Oxford MO, 10/4 Ser M, Cowley Ser 1&2, Oxford Traveller 2-5; Austin 8, 10, A30, A35, A40, A50, A55, Nash, Metropolitan; Hillman Minx 1945-57, Husky 1955-57; Jowett Jupiter; Wolseley 8, 4/44, 15/50, 15/60, 1500; MG TC, TD, TF; Singer 9, Gazelle; Standard 8, 10 1953-57 |
| Clutch Cover Assembly   | 42                    | 500257             | Borg & Beck 45686/23, Rootes P45228          | Morris Oxford MO, 10/4 Ser M, Cowley Ser 1; Austin 10, A40, Nash, Metropolitan;<br>Hillman Minx Mk5 & 8, Husky, Californian, New Minx Ser 1; Wolseley 10, MG TC  |
| Clutch Cover            | 42                    | 500258             | Borg & Beck 44638, Rootes K5597              |  |
| Thrust Spring yellow    | 42                    | 38771              | Borg & Beck 40442, Rootes K9136              |  |
| Anti-rattle spring      | 42                    | 38777              | Borg & Beck 41073, Rootes K5603              |  |
| Pressure Plate          | 42                    | 42527              | Borg & Beck 42200, Rootes K10043             | Bedford CA Van; Morris Oxford MO, 10/4 Ser M, Cowley Ser 1; Austin 10, A40, Nash, Metropolitan; Hillman Minx Mk7 & 8, Husky, Californian, New Minx Ser 1; Wolseley 10; MG TC   |
| Release Lever           | 42                    | 42529              | Borg & Beck 48376, Rootes K23348             |  |
| Nut-eye bolt            | 42                    | 38776              | Borg & Beck 48542, Rootes K18828             |  |
| Eye-bolt                | 42                    | 42532              | Borg & Beck 48542, Rootes K18828             |  |
| Strut                   | 42                    | 42530              | Borg & Beck 42203, Rootes K10040             |  |
| Release Lever Pin       | 42                    | 42531              | Borg & Beck 42204, Rootes K10041             |  |
| Release Lever Plate     | 42                    | 500259             | Borg & Beck 41069 (?), Rootes K9970 (?)      |  |

| Release Lever Retainer                            | 42 | 500260         | Borg & Beck 40178 (?)  |  |
|---|----|----------------|--|--|
| Clutch Driven Plate                               | 42 | 500436         | Borg & Beck HB313, 45589/54, 45589/14,<br>Rootes P45230  | Morris Oxford MO, 10/4 Ser M, Minor; Austin A40, Nash, Metropolitan; Hillman Minx Mk5 & 8, Husky, Californian, New Minx Ser 1; Jowett Javelin & Jupiter; Sunbeam Talbot 80 |
| Clutch Release Bearing                            | 42 | 501009         | Borg & Beck 46889, 48503, 48314,<br>Autonational 146892  | Austin A40; Singer 9; Hillman Minx; Bedford CA Van; Moskvich 407, 408, 426 1959-70; Commer 8cwt 1964-65  |
| Facing Package                                    | 42 | 500262         | Ferodo B6/WO/2   |  |
| Pin For Fork                                      | 46 | 56965          |  | Triumph TR2-6, Stag, Dolomite & Sprint   |
| Bolt, operating shaft to gearbox                  | 46 | 102805         |  | TR2/3  |
| Set Screw, cover to gearbox                       | 44 | 55771          |  | TR2/3  |
| Speedo Oil Seal                                   | 46 | 60247          | Payen NA033, B203, Angus (Gaco) B22603,<br>Burtonwood 037-075-8, Humphrey MS25,<br>McCord 80228, National 50385, Smiths 40-<br>343-104, Standard 43-1115, 43-1505, Victor<br>63232, Weston (Gitseal) 0750372-5R4 | Triumph Renown, TR2, TR3, TR3A, TR4, TR4A  |
| 2nd/3rd Gear Op Sleeve to TT24065<br>from TT24066 | 56 | 55695<br>62065 |  | Triumph TR2, TR3, Standard Vanguard Ph 1-3, Sportsman  |
| Selector Lever only                               | 80 | 100290         |  | Standard Vanguard Ph 1   |
| Nut   | 80 | 500056         |  | Standard Vanguard Ph 1   |
| Lock Washer                                       | 80 | 500057         |  | Standard Vanguard Ph 1   |
| Top Clamp, selector lever to steering clamp       | 80 | 101369         |  | Standard Vanguard Ph 1-3, Vignale, Ensign, 6 Cyl, Sportsman  |
| Spring, control shaft assembly                    | 82 | 58780          |  | Standard Vanguard 1-2  |
| Tension Spring, cross shafts                      | 84 | 58996          |  | Standard Vanguard Ph 1, 2  |
| Gear Change Fork End to TT26455                   | 84 | 57191          |  | TR3  |
| Clevis Joint Assembly T0 TT26455                  | 84 | 57190          |  | Triumph TR2-4A   |
| Spring for Clevis joint to TT26455                | 84 | 57239          |  | Triumph TR2-4  |
| Pin for Clevis Joint to TT26455                   | 84 | 57192          |  | Triumph TR2-4  |
| Clutch Housing: Cover, front end countershaft     | 44 | 55773          |  | Triumph TR2-6, Stag, 2000, 2500  |
| Gasket, cover front end countershaft              | 44 | 55774          | Payen 14612, KR840   | TR2/3  |
| Speedo bearing                                    | 46 | 58968          | Smiths 31-387-105  |  |
| Speedo Driven Gear                                | 46 | 58969          | Smiths 31-832-465  | TR2/3  |
| Speedo driven gear & bearing assembly             | 46 | 60259          | Smiths SK 69978, 41-281-301-00   | Standard Vanguard Ph 1-3, Vignale, Ensign, Sportsman   |

| Locating Screw, speedo bearing                          | 46       | 56305          |                        | Triumph Spitfire, TR2-4A  |
|---|----------|----------------|------------------------|---|
| Bush, Clutch Shaft                                      | 44       | 36998<br>36997 |                        | TR2-5<br>TR2-5, Standard Vanguard 1-3, Vignale, Ensign, 6 cyl, Sportsman  |
| Retaining Ring on Countershaft                          | 54       | 55721          |                        | Triumph TR2-3B  |
| Thrust Washer, countershaft front                       | 54       | 59454          |                        | TR2/3   |
| Thrust Washer, countershaft rear                        | 54       | 55720          |                        | TR2/3, Standard Vanguard Ph 1-3, Vignale, Ensign, 6 Cyl, Sportsman  |
| Retaining Screw   | 54       | 55715          |                        | Triumph TR2-3B  |
| Washer for Mainshaft                                    | 56       | 59443          |                        | TR2/3, Standard Vanguard Ph 1-3, Vignale, Ensign, 6 Cyl, Sportsman  |
| Screwed End, Speedo Driven Gear                         | 46       | 60246          | Smiths 31-358-508      | Triumph TR2-5, Stag   |
| Washer, 2nd Gear  | 56       | 101586         |                        | TR2/3, Standard Vanguard Ph 1-3, Vignale, Ensign, 6 Cyl, Sportsman  |
| Needle Roller On Countershift Gear                      | 54       | 58088          | SKF 3x29.8             | Triumph TR2-3B  |
| Countershaft  | 54       | 55699          |                        | Standard Vanguard Ph 1-3, Vignale, Ensign, 6 Cyl, Sportsman   |
| First Speed Gear, on countershaft                       | 54       | 62068          |                        | Standard Vanguard Ph 1-3, Sportsman   |
| Constant Gear on countershaft                           | 54       | 62069          |                        | Standard Vanguard Ph 1-3, Vignale,, Ensign, 6 Cyl, Sportsman  |
| Front End Cover Gasket                                  | 44       | 59537          | Payen 11387, KR354     | Triumph TR2-6, Stag, 2000/2500, Dolomite & Sprint   |
| Spring  | 56       | 37502          |                        | TR2/3   |
| Ball Bearing, Constant Pinion                           | 56       | 58391          | RHP MJ1¼, SKF RMS 10 N | Triumph TR2-3B,6, Stag, 2000/2500, Dolomite & Sprint, Standard Vanguard Ph 1-3, Vignale, Ensign, 6 Cyl, Sportsman |
| Distance Piece, 2nd & Constant                          | 54       | 59456          |                        | Triumph TR3,4,6, Stag, 2000/2500  |
| Bush, 2nd Gear  | 56       | 101585         |                        | Triumph TR2-3B  |
| Bush, first gear  | 56       | 59453          |                        | Standard Vanguard Ph 1-3, Vignale, Ensign, 6 Cyl, Sportsman   |
| Bush for Selector Rod                                   | 58       | 58951          |                        | Triumph TR2-3B, Standard Vanguard Ph 1-3, Vignale, Ensign, 6 Cyl, Sportsman                                       |
| Selector bush gasket                                    | 58       | 55994          | Payen 16862            |   |
| Interlock spigot gasket                                 | 58       | 55993          | Payen 15113            |   |
| Synchronising Cup, first                                | 56       | 59043          |                        | Standard Vanguard Ph 1-3, Vignale, Ensign, 6 Cyl  |
| Synchronising Cup, 2nd & Top                            | 56       | 60570          |                        | TR2/3   |
| Synchronising Sleeve 2nd/Top to TT24065<br>from TT24065 | 56<br>56 | 55694<br>62064 |                        | TriumphTR3-6, Standard Vanguard Ph 1-3, Vignale,, Ensign, 6 Cyl, Sportsman  |
| Baulk Pin, reverse                                      | 56       | 59048          |                        | Standard Vanguard Ph 1-3, Vignale, Ensign, 6 Cyl, Sportsman   |
| Bush, Constant Pinion                                   | 54       | 55911          |                        | Triumph TR2-3B, Standard Vanguard Ph 1-3, Vignale, Ensign, 6 Cyl, Sportsman                                       |
| Oil Thrower, Constant Pinion                            | 58       | 60658          |                        | Triumph TR2-4,6, Stag, 2000/2500  |
| Spring For Plunger                                      | 58       | 101236         |                        | TR2/3   |

| Taper Set Screw, selector rod to gearbox | 58  | 55815  |   | Triumph TR2-3B   |
|--|-----|--------|---|--|
| Selector Fork, first & reverse, RHD      | 58  | 58198  |   | Standard Vanguard Ph 1-3, Vignale, Ensign, 6 Cyl, Sportsman                            |
| Selector Fork, first & reverse, LHD      | 58  | 59099  |   | Standard Vanguard Ph 1-3, Vignale, Ensign, 6 Cyl, Sportsman                            |
| Coupling Lever, to selector              | 58  | 58319  |   | Standard Vanguard Ph1, 2   |
| Interlock                                | 60  | 55981  |   | Standard Vanguard Ph 1, 2  |
| Front Gearbox Oil Seal                   | 44  | 60215  | Payen NA299, C461, Burtonwood 125-200,<br>Humphrey ST23, Weston (Gitseal) 200125-<br>50R4   | Triumph TR2-4; Standard Vanguard Ph 1-3, Vignale, Ensign                               |
| Gearbox Extension Oil Seal               | 44  | 100650 | Payen C570, Advance 2534, Burtonwood 137-237-20L, 137-237-20GL, Humphrey CAS27, T8, McCord 80162, 84558, National 20055, 30055, Standard 43-1251, 43-2070, Victor 47206 |  |
| Gearbox Extension Gasket                 | 44  | 55778  | Payen 11289, KR332  | TR2/3  |
| Gearbox Drain Plug                       | 44  | 57216  | Leyland 114774  | TR3; MG Midget 1500 (sump & gearbox); Standard Vanguard, Ensign (sump, diff & gearbox) |
| Gearbox Top Cover Gasket                 | 44  | 55791  | Payen 11290, KR333  | Standard Vanguard Ph 1-3, Vignale, Ensign, 6 Cyl, Sportsman                            |
| Gearbox Dipstick                         | 44  | 58959  |   | Standard Vanguard Ph 1-3   |
| Speedometer Cable                        | 120 | 400085 |   | Morris Oxford (CN113 1N9); Hillman Minx late 50s to early 60s                          |
| Gearbox Mount                            |     |        | 104086  | TR2-6  |

#### **BODY & INTERIOR**

| Component                               | Parts<br>List<br>Page | Stan<br>part<br>No | Possible Manufacturer Part No(s) | May also be fitted to/ Possible alternative   |
|---|-----------------------|--------------------|----------------------------------|---|
| Door Armrest to TT14222<br>from TT14223 | 144                   | CD27974<br>700426  |                                  | {Wolseley 1500 c1960; some Morris Oxfords; Jaguar XK150,<br>{ E Type 3.8 & 4.2 p no BD-14963-(col code) |
| Inner Door Handles                      | 142                   | 600831             |                                  | Ford 100e, 105e   |
| Escutcheon, inner door handle           | 140                   | 600826             |                                  | Standard Vanguard Ph 1-2  |
| Escutcheon Spring, inner door handle    | 140                   | 600827             |                                  | Standard Vanguard Ph 1-2  |
| clutch Operating Link                   | 142                   | 600626<br>601200   |                                  | Standard 8, 10, Pennant<br>Standard 8, 10, Pennant, Vanguard Ph 1, 2                                    |

| Ext Door Handle (locking) to TT15067<br>from TT15068 | 138 | 600361<br>700520 |  | Standard 8, 10, Pennant Standard 8, 10, Pennant, Vanguard Ph 1,2                       |
|--|-----|------------------|--|--|
| Window Handles                                       | 142 | 600824           |  | Ford 100e, 105e: Triumph Herald, Standard Vanguard Ph 1-2                              |
| Striker Plate, door LH                               | 144 | 601021           |  | Standard Vanguard Ph 2   |
| Door Handle End Clip                                 |     | 601021           |  |  |
| · ·  | 138 |                  |  | Standard Vanguard Ph 1A, 2   |
| Boot Handle (locking)<br>(non lock)                  | 154 | 600632<br>600627 |  | Pre 1974 Mini door handles   |
| Boot Handle Escutcheon                               | 154 | 600635           |  | Triumph Spitfire   |
| Boot Lid Strap Staple                                | 154 | 600546           |  | TR3  |
| Number Plate & Light Swivel Bracket                  | 114 | 700339           |  | Morris Minor 1000  |
| Front Quarterlight Seal, rear vertical section       |     |                  | IRS1652  |  |
| Door Side Window Channel seal                        |     |                  | FC L   |  |
| Screw  | 138 | 500205           |  | Standard Vanguard Ph 1   |
| Globe Badge  | 108 | 101042           |  | Triumph TR2-5  |
| Sealing Rubber For Dash Vent                         | 158 | 600597           |  | Triumph TR2-3A   |
| Ventilator Spring                                    | 158 | 600549           |  | Triumph TR2-3A   |
| Blanking Plug, dipper switch, RHD                    | 164 | 600399           |  | Standard Vanguard Ph 1-3, Vignale, Ensign, 6 Cyl, Sportsman                            |
| Rubber Pad, Brake & Clutch Pedals                    | 50  | 56168            | Leyland 136609   | Triumph 2000, 2500, 2.5PI, Standard Vanguard Ph 1-3, Vignale, Ensign, 6 Cyl, Sportsman |
| Throttle pull off spring                             | 52  | 44664            |  | Standard Vanguard Ph 3, Ensign, 6 Cyl, Sportsman                                       |
| Clutch Operating Link                                | 48  | 57079            |  | Standard Vanguard Ph 1   |
| Petrol Filler Cap                                    | 110 | 600482           | Guide Win TCK-8B p no 13427                              |  |
| Radiator Grill left hand                             | 108 | 800149           |  | Triumph renown   |
| Radiator Grill right hand                            | 108 | 800188           |  | Triumph renown   |
| Front & Rear Overider                                | 112 | 700110           |  | Triumph renown   |
| Nave Plate (Hub cap)                                 | 111 | 200244           |  | Standard Ensign  |
| Heater Kit Assembly                                  | 166 | 550736           | Smiths CHS 2001-07                                       |  |
| Heater Unit  | 166 | 800273           | Smiths FHF 3522  |  |
| Blower Assembly<br>Blower Casing<br>Blower Motor     | 166 | 700381           | Smiths FHB 1301-03<br>Smiths CHS 10515<br>Smiths CHS 720 |  |

| Paint: Comet Blue (dark blue trim)         | ICI 2281; Cellulose MX 227231; 1/2 Hour<br>Synthetic DY 15386; Gipgloss 15386; Dockers<br>E8451 | Formula: TXGL 47/1 Dark Grey 65%, TXGL 1/357 Light Blue 26%, TXGL 76 Purple Oxide 6%, TXGL 69 Fast Purple 3% |
|--|---|--|
| Paint: Jade Green (brown trim)             | ICI 5398M; Cellulose 228127/M; 1/2 Hour<br>Synthetic DY 16423/M; Dockers E9352                  |  |
| Paint: Royal Maroon                        | ICI 3105; Dockers E8688   |  |
| Paint: Black (brown or red trim)           | ICI 2007; Dockers E7277   |  |
| Paint: Cotman Grey (dove grey or red trim) | Cellulose 228490; 1/2 Hour Synthetic DY<br>16769; Gipgloss GL16769; Dockers E9009               | Formula: TXGL 47/1 Dark Grey79%, TXGL 18 Yellow Ochre 13%, TXGL 86/1 Pink Oxide 4%, TXGL 47 Black 4%         |