CSD2 GF6, GF9 and GFx Tagging and Marking Requirements



Refer to this list to determine if a Certified Material Tag is required

Controlled by: Arun Janardhan Last Revised: 25-Sep-24

Location	Required:	Part Number:	Picture of Issue:	Issue / Feature:	Marking:	Picture of Marking:	On Cert Tag:	
				GF-6				Date Implemented
GM/Ford	100% Inspection: 1. Marking is required for both customers. 2. Cert tag only for GM	50-4865 50-9641	Description: Incorrect laser marking against design. 11 digits instead of 16.	Quality Issue 1: **Incorrect Laser Mark on different customer**	Green sharpie mark on pedestal face away from the laser marker.		Pink Cert Tag at 100% Table FOR GM ONLY on 50-4865 "Incorrect and Missing Laser Mark"	16-Jul-24
			37AL 724	Quality Issue 2: **Missing Laser Mark**				