Team Meeting 2/26/20 - 1.5 Wks to CDR: Mar 6

Meeting Agenda

- Timeline for build & test / Spring quarter
 - Igniter systems
- Deliverables for Friday & Monday
 - PDR feedback
 - o Refinements & modifications

Timeline

• Work from test schedule - what dependencies must be fulfilled for each test?

Sun	Mon	Tue	Wed	Thu	Fri	Sat
2/23	PDR		TODAY		Chamber O- ring swap	
3/1	Bolt notch machining?		Feed Sys Assembly updated		CDR?	
3/8	CDR?	Order all parts for igniter test	Start Ox cleaning parts from lab			
3/15	Winter Finals - continue Ox cleaning parts from lab, notched bolt pull testing					
3/22	Spring Break					
3/29	Machine igniter body, build test stand					
4/5	Assemble igniter feed system & test config					
4/12						
4/19	Receive machined graphite nozzles					
4/26						
5/3						

5/10		
5/17		
5/24		
5/31		
6/7	Spring Finals	

- Igniter Testing
 - ~2 weeks for machining
 - Test stand
 - Igniter body
 - ~2 weeks for electronics & controls
 - Simultaneous with machining
 - ~3-4 weeks for purchased parts
 - Metering valves
 - Solenoid valves?
 - ~2 weeks for ox cleaning lab hardware

Deliverables for Friday & Monday / CDR Prep

Main Injector

- Decide element type & work on printability
- Move propellant inlets to give space for igniter fittings
- Update wall thk for FS > 2 all around, ensure no weak links for nozzle ejection
- CFD

Igniter

- CFD
- Redo FEA with 316 stainless and inconel 718

Controls & electronics

•

Nozzle

- Integrate BOM into main
- Quote for nozzle(s)
 - o Multiple identical, varied throat diameters

Alternative throat diameters (chamber pressures) (Jeff)

Combustion Chamber

- Integrate BOM into main
 - Explore cheaper options for raw materials
- Switch O-ring gland from flange to chamber
- Bolt notch machining & test

Test Stand

- Switch welded joints to bolted
- Find cart/stand to support engine at tank level
- Aluminum nozzle replacement plug for hydrostatic testing
- Back plate

Propellant Feed System

- Update full assembly CAD (make everything more compact, figure out elevation of chamber)
 - o Move all tubing to tank end if possible, have fittings back to back into engine
- Look for new pressure reg. CAD model w/ 90 deg turn
- Add burst disk for LOx run pressure relief how much \$\$\$?
- Look into helium price & nitrogen solubility (Rishav)
 - Maybe Argon? NO, saturation curve too similar to oxygen, will dissolve easily
 - o Get quotes on Gox, nitrogen, helium
 - Make sure ox dewar is low-pressure for low boiling temp
- Look for ultrasonic cleaner on campus
 - o PRL?