Wiring guide for Smart Slow Sign V0.01 $\underline{\textbf{Sender}}$ Module

LoRa Module	ESP 32
3v3	3v3
GND	GND
Reset	IO14
NSS	105
SCK	IO18
MOSI	1023
MISO	IO19
Sonar A	ESP 32
VCC	5V (Breadboard power rail)
Trig	1012
Echo	IO13
GND	GND (Breadboard grounding rail)
Sonar A	ESP 32
GND	5V (Breadboard power rail)
Trig	1027
VCC	5V (Breadboard power rail)

Wiring guide for Smart Slow Sign V0.01 *Receiver* Module

LoRa Module	ESP 32
3v3	3v3
GND	GND
Reset	IO14
NSS	105
SCK	IO18
MOSI	IO23
MISO	IO19