# HEIGHT MEASUREMENT



Digital Height Gages Page 85-87



**Dial Indicator Stands** Page 87










#### HIGH PRECISION DIGITAL HEIGHT GAGES








power supplied by charge pal



data transmitted to Excel without software; short press the foot switch to transmit data, long press to zero

- High stability, high precision, high response speed (5000mm/s)
   High brightness LED display
- Ceramic base flatness: 1µm



Code	•	Range	Resolution	Accuracy (20°C)	Measuring force	Output	Power supply
1155-	-505	0~50mm	0.5μm/0.00002" (can switch to: 1μm/0.00005")	1.5µm	0.8~1.2N	USB	5V/1A (adapter or charge pal)
1155-	-510	0~50mm	0.1µm/0.000005" (can switch to: 1µm/0.00005")	1µm	0.8~1.2N	USB	5V/1A (adapter or charge pal)

#### STANDARD DELIVERY

	Main unit	1 pc
--	-----------	------

#### **OPTIONAL ACCESSORY**

Contact point	code <b>6282</b>
Charge pal	1155-5-POB
Data output cable (including foot switch)	1155-5-FOS

#### **DIGITAL HEIGHT GAGES**








1157-501



1157-502






- High response speed (5000mm/s)
  High brightness LED display




power supplied by charge pal



data transmitted to Excel without software; short press the foot switch to transmit data, long press to zero



#### measuring tips (included)



Code	Range	Resolution	Accuracy (20°C)	Measuring force	Output	Power supply	Base
1157-501	0~50mm	1µm/0.00005"	3µm	0.8~1.2N	USB	5V/1A (adapter or charge pal)	granite (flatness: 2µm)
1157-502	0~50mm	1µm/0.00005"	3µm	0.8~1.2N	USB	5V/1A (adapter or charge pal)	ceramic (flatness: 1µm)

#### OPTIONAL ACCESSORY

Contact point	code <b>6282</b>
Charge pal	1155-5-POB
Data output cable (including foot switch)	1155-5-FOS

#### STANDARD DELIVERY

Main unit 1 pc
----------------



#### LARGE RANGE DIGITAL HEIGHT GAGE




Unit: mm Ø35

400(W)X300(D)

LED display mm/inch on/off, zero spindle lift knobgranite base **♦INSIZE** 

measuring tips (included)







power supplied by charge pal

foot switch

1158-100

data transmitted to Excel without software; short press the foot switch to transmit data, long press to zero

Code	Range	Resolution	Accuracy (20°C)	Measuring force	Output	Power supply
1158-100	0~100mm	0.1µm/0.000005" (can switch to: 1µm/0.00005")	3µт	0.8~1.2N	USB	5V/1A (adapter or charge pal)

#### STANDARD DELIVERY

Main unit	1 pc
	P 1

#### **OPTIONAL ACCESSORY**

Contact point	code <b>6282</b>
Charge pal	1155-5-POB
Data output cable (including foot switch)	1155-5-FOS







#### **DIGITAL HEIGHT GAGES**




- Non waterproof
- Resolution: 0.01mm/0.0005"
- Buttons: on/off, zero, mm/inch, ABS/INC, data hold, TOL, set
- ABS/INC is for absolute and incremental measurement
- TOL is for tolerance measurement
- Carbide tipped scriber
   Made of stainless steel (except the base)
- LR44 battery, data output
- Supplied with dial test indicator holder
- Supplied with dust cover (except 1150-1500/2000)
   Optional accessory: data output cable (code 7302-SPC7 page 13, keyboard format), wireless data transmission


(transmitter code **7315-1150 need receiver** page 6), clamp for protractors (code **2372-CLAMP**, for **1150-300**)








clamp for protractors (**optional**) for **1150-300** 





#### dial test indicator holder (included)



Code	Range	Type	Accuracy	L	a1	a2	b	c1	c2	с3	d	е	f
1150-300	0-300mm/0-12"	Α	±0.04mm	485mm	138mm	45mm	95mm	80mm	30mm	10mm	28mm	9mm	9mm
1150-500	0-500mm/0-20"	В	±0.06mm	720mm	180mm	55mm	95mm	103mm	25mm	12mm	30mm	10mm	12mm
1150-600	0-600mm/0-24"	В	±0.06mm	820mm	180mm	55mm	95mm	103mm	25mm	12mm	30mm	10mm	12mm
1150-1000	0-1000mm/0-40"	С	±0.08mm	1275mm	250mm	80mm	125mm	110mm	39mm	15mm	50mm	10mm	15mm
1150-1500	0-1500mm/0-60"	С	±0.12mm	1790mm	280mm	80mm	125mm	110mm	39mm	15mm	50mm	10mm	15mm
1150-2000	0-2000mm/0-80"	С	±0.16mm	2290mm	280mm	80mm	125mm	110mm	39mm	15mm	50mm	10mm	15mm






#### DIGITAL HEIGHT GAGES WITH DRIVING WHEEL




- Non waterproof
- Resolution: 0.01mm/0.0005"
- Buttons: on/off, zero, mm/inch, preset +, preset -, ABS/INC
   Automatic power off, move the digital unit to turn on power
- Carbide tipped scriber
- Made of stainless steel

- Battery CR2032
  Data output
  Supplied with dust cover
- With dial test indicator holder
- Optional accessory: data output cable (code 7302-22 page 12), wireless data transmission (transmitter code 7315-22 need receiver page 4), clamp for protractors (code 2372-CLAMP)






#### dial test indicator holder (included)



#### clamp for protractors (optional)



Code	Range	Accuracy	L	W	Н	а	b	С	h
1156-300 <b>*</b>	0-300mm/0-12"	±0.03mm	515mm	180mm	55mm	80mm	30mm	35mm	9mm
1156-600*	0-600mm/0-24"	±0.05mm	815mm	180mm	55mm	80mm	30mm	35mm	9mm
1156-1000*	0-1000mm/0-40"	±0.07mm	1220mm	265mm	70mm	92mm	48mm	40mm	12mm

<sup>\*</sup>Supplied with manufacturer inspection certificate

#### **DIGITAL HEIGHT GAGES**

dial test indicator holder (included)






- Resolution: 0.01mm/0.0005"
- Buttons: on/off, zero, mm/inch, data hold, ABS/INC, preset
- ABS/INC is for absolute and incremental measurement
- Automatic power off, move the digital unit to turn on power
- Carbide tipped scriber
- Made of stainless steel
- Battery CR2032, data output
- With driving wheel
- With dial test indicator holder
- Supplied with dust cover
- Optional accessory: data output cable (code **7302-1151** page 13, keyboard format), wireless data transmission (transmitter code 7315-1151 need receiver page 6), clamp for protractors (code 2372-CLAMP)



1151-300A



DATA OUTPUT

clamp for protractors (optional)



#### (mm)

Code	Range	Accuracy	L	a1	a2	b	С	ØD
1151-300A	0-300mm/0-12"	±0.04mm	475	135	43	84	33	15
1151-450A	0-450mm/0-18"	±0.05mm	660	180	54	88	38	20
1151-600A	0-600mm/0-24"	±0.05mm	810	180	54	88	38	20

#### **DIAL HEIGHT GAGES**






- Dial indicator graduation: 0.01mm
- One counter reads in the plus direction and another in the minus direction, so incremental measurement can be made in either direction
- Carbide tipped scriber
- Made of stainless steel (except the base)
- With driving wheel
- With dial test indicator holder
- Supplied with dust cover
- Optional accessory: clamp for protractors (code 2372-CLAMP)



1351-300

								(mm)
Code	Range	Accuracy	L	a1	a2	b	С	ØD
1351-300	0-300mm	±0.04mm	475	135	43	84	33	15
1351-450	0-450mm	±0.05mm	660	180	54	88	38	20
1351-600	0-600mm	±0.05mm	810	180	54	88	38	20



clamp for protractors (optional)



MINI DIGITAL HEIGHT GAGES

## DATA OUTPUT

- Non waterproof
- Resolution: 0.01mm/0.0005"
- Buttons: on/off, zero, mm/inch
- Automatic power off, move the digital unit to turn on power
- Carbide tipped scriber
- With fine adjustmentMade of stainless steel
- Battery CR2032
- Optional accessory: dial test indicator holder (code 7151-CL1)


With data interface (data output cable code 7315-21 need receiver page 4, 7302-21 page 12, optional)

Code	Range	Accuracy
1154-150	0-150mm/0-6"	±0.03mm

# Unit: mm 1154-150

**Built-in wireless** (receiver code 7315-2/3/6/7/8/9 is required)

Code	Range	Accuracy
1154-150WL	0-150mm/0-6"	±0.03mm





#### MINI VERNIER HEIGHT GAGES

- Graduation: 0.02mm/0.001"
- Carbide tipped scriber
- Made of stainless steel (except the base)
- Satin chrome plated scale
  Optional accessory: dial test indicator holder (code 7151-CL1)

Range

Code




	(mm)
b	d
57	16


	scriber (included)	Unit: mm
1253-200		

1253-150	0-150mm/0-6"	±0.03mm	265	75	57	16
1253-200	0-200mm/0-8"	±0.03mm	325	90	70	20

Accuracy




- Graduation: 0.02mm/0.001"
- Adjustable main scale to set zero
- Carbide tipped scriber
- Made of stainless steel (except the base)
- Satin chrome plated scale
- Supplied with magnifier
- With fine adjustment
- Supplied with dust cover
- Optional accessory: dial test indicator holder (code **6293-6**), clamp for protractors (code 2372-CLAMP)



1250-300

									(mm)
Code	Range	Accuracy	L	a1	a2	b	c1	c2	d
1250-300	0-300mm/0-12"	±0.04mm	545	135	43	75	80	30	28
1250-450	0-450mm/0-18"	±0.05mm	720	180	54	85	80	41	35
1250-600	0-600mm/0-24"	±0.05mm	870	180	54	85	80	41	35

#### **VERNIER HEIGHT GAGES**





dial test indicator holder (optional)




### **VERNIER HEIGHT GAGES (BASIC TYPE)**


- Graduation: 0.02mm/0.001"
- Carbide tipped scriber
   Made of stainless steel (except the base)
- Satin chrome plated scale
- With dial test indicator holder
- Supplied with dust cover



dial test indicator holder (included) Unit: mm /Ø8 for 1251-200/300 for 1251-500 for 1251-1000/ 1500/2000



1251-200



									(mm)
Code	Range	Accuracy	L	c1	c2	с3	d	е	f
1251-200	0-200mm/0-8"	±0.03mm	370	76	25	10	23	6	8
1251-300	0-300mm/0-12"	±0.04mm	470	76	25	10	23	6	8
1251-500	0-500mm/0-20"	±0.05mm	720	105	25	12	30	10	12
1251-1000	0-1000mm/0-40"	±0.07mm	1275	110	39	15	50	10	15
1251-1500	0-1500mm/0-60"	±0.11mm	1790	110	39	15	50	10	15
1251-2000	0-2000mm/0-80"	±0.14mm	2290	110	39	15	50	10	15


#### **SCRIBERS FOR HEIGHT GAGES**

Carbide tipped

Code	For height gages	Type	c1	c2	D	E
7150-SC2	1150-500, 1150-600	Α	103mm	25mm	10mm	12mm
7150-SC3	1150-1000, 1150-1500, 1150-2000	Α	110mm	39mm	10mm	15mm
7150-SC4	1351-300, 1351-450, 1351-600, 1151-300A, 1151-450A, 1151-600A	В	78mm	15mm	9mm	9mm
7150-SC6	1250-300, 1156-300, 1156-600, 1150-300	А	80mm	30mm	9mm	9mm
7150-SC7	1250-450, 1250-600	Α	80mm	41mm	9mm	9mm
7150-SC9	1253-150, 1253-200, 1154-150	В	55mm	12.5mm	6mm	8mm
7150-SC10	1156-1000	Α	92mm	48mm	9mm	12mm



7150-SC3



#### **CALIPER/HEIGHT GAGE CHECKERS**

REFER TO PAGE 332 FOR DETAILS



4