	Port 1 (LEFT)			Port 2 (RIGHT)		Port Pin
Status [F1]	Program [F2]	Stack [F3]				1
Variable [F4]	Output [F5]	Graphics [F6]				2
Step [F11]	Slower [CTRL -]	Faster [CTRL =]				3
Run/Halt [F10]	mode [TAB]	Erase [Backsp.]	Backward [LEFT]	Forward [RIGHT]	New Line [ENTER]	4
		←				
+	-	[:]	1	2	3	1
* [*]	÷ [/]	NOTE [↑ N]	4	5	6	2
HOR1 [↑ H]	VER1 [↑ V]	KEY [↑K]	7	8	9	3
Run/Halt [F10]	mode [TAB]	Erase [Backsp.]	HOR2 [ALT H]	VER2 [ALT V]	0	4
Α	В	С	J	K	L	1
D	E	F	M	N	0	2
G	H	<u>'</u>	P	Q	R	3
Run/Halt [F10]	mode [TAB]	Erase [Backsp.]	S	Т	Space	4
1=	THEN	FLOE				
	THEN [↑ T]	ELSE [↑ E]	U	V	W	1
GOTO [↑ G]	PRINT [?]	11	X	Υ	Z	2
()	,	Clear [↑ HOME]	MOD [%]	HIT [ALT T]	3
Run/Halt [F10]	mode [TAB]	Erase [Backsp.]	=	>	<	4
5	9	6	5	9	6	Port Pin