

Power	Analogue_Flow_Rate_HART
	51 4 1 51 8 1 11487
File: Power.sch	File: Analogue_Flow_Rate_HART.sch
USB_BLE	Analogue_Tidal_Vol
	, madagas_mas_rat
File: USB_BLE.sch	File: Analogue_Tidal_Vol.sch
	3 - 2
Sensors_Pressure	Analogue_Abs_Press
Sensors_r ressure	Allatogue_Abs_i Tess
File: Sensors_Pressure.sch	File: Analogue_Abs_Press.sch
The sensors in resourcise.	Titel Amatogota toal Teasisen
Sensors_Temp	Indicators
File: Sensors_Temp.sch	File: Indicators.sch
Farana Farina	C
Sensors_Environ	Connectors
File: Sensors_Environ.sch	File: Connectors.sch





Both pressure sensors must be configured as either analogue output or SPI output.

