Team 9 Stevie Taylor Nick Short Calvin Xaybanha Zeming Zhou

Design Review

Reviewers: Team 12 Miles Breslin Miguel Higgins Moy Noah Page John Sharpe

• To-Do

- o Schematic:
 - Need to add linear regulator and make sure voltage nets are applied properly.
 - Add ISP header.
- o Board:
 - Need thicker traces all around.
 - Primarily surface mount components.
 - Need to add stitching vias.