

## Mavic 2 Enterprise Advanced Known Issue List

1.	M2EA Released Version.....	2
2.	Unsolved Issues.....	2
	Unsolved Issues in this Version .....	2
	V01.00.0200 Unsolved Issues .....	3
3.	Solved Issues.....	4

Please download and install the latest version to get better performance.

<https://www.dji.com/id/mavic-2-enterprise-advanced>

## 1. M2EA Released Version

---

Released Date:	2022.03.30
Aircraft Firmware:	V01.00.0428
Smart Controller Firmware:	V01.01.0064
Pilot App Android version:	V2.5.1.3
DJI Assistant 2 (Enterprise Series):	v2.1.3

---

## 2. Unsolved Issues

### ➤ Unsolved Issues in this Version

Index	Issue Description	Workaround Solution
1	Playback function, the media file is unable to be loaded at random, when the storage of the SD card reach the limitation.	In fact, the file status is normal, please try again to recover.

## ➤ V01.00.0200 Unsolved Issues

---

Released Date:	2021.03.31
Aircraft Firmware:	V01.00.0200
Smart Controller Firmware:	V01.01.0058
Pilot App Android Version:	V2.3.1.5
DJI Assistant 2 (Enterprise Series):	v2.1.2

---

Index	Issue Description	Workaround Solution
1	During the mission flight, if pause the mission and direct aircraft to the position which is not on the mission route, the aircraft is unable to move.	Please exit the flight mission, than control the aircraft to the target position.  This issue will be optimized in the later firmware versions.
2	If you import a waypoint mission for P4 RTK, and change the aircraft model to Mavic 2 Enterprise Advanced, the camera actions will be lost.	Currently it is not supported to import the waypoint mission with other aircraft models.
3	When the aircraft is powered on, the camera may frequently performs FFC, and camera view is refreshing or shaking rapidly.	FFC frequency will be slowed down after the aircraft warms up; or you can manually turn off the FFC function.
4	In video recording mode, the maximum digital zoom level is 4x.	Please switch to photo mode in order to further zoom in.

### 3. Solved Issues

Index	Issue Description	Workaround Solution	How it is solved
1	In a waypoint flight mission, the gimbal pitch angle cannot be $>0^\circ$ , otherwise the mission cannot be uploaded	Configure the gimbal pitch angle to be $90^\circ \sim 0^\circ$ .  This issue will be optimized in later firmware versions.	Aircraft version : V01.00.0428  Smart Controller Version : V01.01.0064  Solved
2	In the live mission record function, if the horizontal distance between two consecutive points are within 0.5m, the latter point could not be created.	This issue will be optimized in later firmware versions.	Aircraft version : V01.00.0428  Smart Controller Version : V01.01.0064  Solved
3	In the live mission record function, you cannot record the current point with taking a picture	This issue will be optimized in later firmware versions.	Aircraft version : V01.00.0428  Smart Controller Version : V01.01.0064  Solved
4	After zooming in with the visible light camera, the photo saved in SD card still shows the view without digital zoom.	This issue will be optimized in later firmware versions.	Aircraft version : V01.00.0428  Smart Controller Version : V01.01.0064  Solved

## Mavic 2 Enterprise Advanced Known Issue List



Index	Issue Description	Workaround Solution	How it is solved
5	After upgrading to the latest firmware version, there is still an upgrade notification when you power on the aircraft.	You don't need to upgrade again. This issue will be optimized in later firmware versions.	Aircraft version : V01.00.0428  Smart Controller Version : V01.01.0064  Solved
6	When using the network RTK (Ntrip) function, when you find that the RTK cannot converge after a long time, please check the RTCM version you use. Only RTCM3.2 is supported.	If you are using RTCM 3.0 and 3.1, please contact DJI  Support to get a beta version of DJI Pilot.  RTCM 2 cannot be supported.	Aircraft version : V01.00.0428  Smart Controller Version : V01.01.0064  Pilot App Android version: V2.5.1.3  Solved

<https://www.dji.com/id/mavic-2-enterprise-advanced>