Tox no.: 173665 Last Reviewed: 23/Sep/2004

Tox no.: 17366 Fire Fighting Measures

Extinguishing Media: Any standard extinguishing media may be used.

Exposure Hazards: When heated to very high temperatures, may give off smoke and

decomposition products which may contain toxic compounds.

Protective Equipment: Fire fighters and others exposed, wear self-contained breathing

apparatus.

6. Accidental Release Measures

Personal Precautions: Use personal protection recommended in Section 8. Avoid breathing

dust.

Methods for Cleaning up: Any dust generated should be removed by vacuum or wet cloth.

7. Handling & Storage

Handling: Excessive handling may generate dust. When machining or abrading use

local exhaust ventilation.

Storage: Store in dry place.

8. Exposure Control/Personal Protection

Engineering Measures: Ensure adequate exhaust ventilation when abrading or machining.

Occupational Exposure

Limits:

Dusts: Total Inhalable Dust: 10 mg/m³ - 8 hour TWA

Respirable Dust: 5 mg/m³ - 8 hour TWA

Eye Protection: Goggles.

Respiratory Protection: Wear suitable respiratory protection if exposure limits may be exceeded.

Hand Protection: Wear impervious gloves.

Skin Protection: Wear suitable protective clothing.

9. Physical and Chemical Properties

Appearance: Dense, sold material.

Odour: Characteristic friction material odour.

10. Transport Information

Use any container of suitable size and strength.

11. Regulatory Information