both physically and chemically and do not necessarily exhibit the properties of the individual components. The ingredients may be released as general dust from the product by operations such as overheating, burning, machining, abrading, or riveting.

4. First-aid measures

Inhalation Move injured person into fresh air and keep person calm under observation. If necessary, seek

hospital and take along these instructions.

Skin contact Remove contaminated clothing immediately and wash skin with soap and water. Get medical

attention if irritation develops and persists.

Dust in the eyes: Flush thoroughly with water for at least 15 minutes. Make sure to remove any **Eve contact**

contact lenses from the eyes before rinsing. Get medical attention if irritation develops and

persists.

Ingestion If swallowed, rinse mouth with water (only if the person is conscious). Get medical attention if any

Exposed individuals may experience eye tearing, redness, and discomfort.

discomfort continues.

Most important symptoms/effects, acute and

delayed

Indication of immediate Treat symptomatically.

medical attention and special treatment needed

General information

Ensure that medical personnel are aware of the material(s) involved, and take precautions to protect themselves.

5. Fire-fighting measures

Suitable extinguishing media

Unsuitable extinguishing

media

Use fire-extinguishing media appropriate for surrounding materials.

None.

Specific hazards arising from

the chemical

By heating and fire, toxic vapors/gases may be formed.

Special protective equipment and precautions for firefighters

Selection of respiratory protection for firefighting: follow the general fire precautions indicated in the workplace.

Fire fighting

equipment/instructions

Use standard firefighting procedures and consider the hazards of other involved materials.

General fire hazards This product is not flammable.

6. Accidental release measures

Personal precautions, protective equipment and emergency procedures

Use explosion-proof electrical equipment if airborne dust levels are high. Avoid dust formation. Avoid inhalation of dust and contact with skin and eyes. Wear necessary protective equipment. See Section 8 of the SDS for Personal Protective Equipment.

Methods and materials for containment and cleaning up In the event of a spill or accidental release, notify relevant authorities in accordance with all applicable regulations. Collect powder using special dust vacuum cleaner with particle filter or carefully sweep into closed container. Do not vacuum clean unless vacuum cleaners are equipped with HEPA filter. For waste disposal, see Section 13 of the SDS.

Environmental precautions

Avoid discharge into drains, water courses or onto the ground. Collect and dispose of spillage as indicated in Section 13 of the SDS.

FER 9223