

Material Safety Data Sheet

169305 Level: 1 FIR No.:

Version Number: US-US-2 Release Date: 2009-07-29

4. First-Aid Measures

Inhalation: If dust from the friction material is inhaled, move to fresh air. Seek

medical attention or advice if irritation persists.

Skin Contact: For skin contact, wash immediately with soap and water.

If irritation persists, get medical attention.

Eye Contact: If in eyes, flush with water to remove particulate.

5. Fire-Fighting Measures

This material is not combustible.

Extinguishing Media: Water, foam, ABC-powder, or Halon.

Specific Hazards: When heated to very high temperatures, the material may give off

smoke and decomposition products which may contain toxic

compounds such as sulfur and/or nitrogen oxides.

Protection of Firefighters: Wear self-contained breathing apparatus.

6. Accidental Release Measures

Personal Precautions: Wear appropriate protective equipment and clothing during clean-up.

Avoid inhalation of fibers/dust and contact with skin and eyes. Dust should be collected by vacuuming with a HEPA-filter equipped

vacuum or by wet mopping.

Do not use compressed air or dry brushing for cleaning dust.

Environmental Precautions: No available information.

Methods for Cleaning Up: If a release of dust occurs during machining, abrading, or riveting,

remove dust by vacuuming or wet mopping. Vacuums used for this

purpose should be equipped with HEPA filters. Do not use

compressed air to blow dust from the workplace.

7. Handling and Storage

Handling:

Technical Measures: Avoid spreading dust.

Precautions and Advice for Safe Do not breathe dust.

Handling: Avoid skin and eye contact.

PRINTED DOCUMENT IS TRANSIENT Owner: Ford Motor Company Ford Proprietary Official Record Application: MATS Page: 2 / 7