US. ACGIH Threshold Limit Values	s Type	Value	
ACETONE (CAS 67-64-1)	STEL	500 ppm	
(0.00 0.00)	TWA	250 ppm	
METHYLCYCLOHEXANE (CAS 108-87-2)	TWA	400 ppm	
TOLUENE (CAS 108-88-3)	TWA	20 ppm	
US. NIOSH: Pocket Guide to Chen	nical Hazards		
Components	Туре	Value	
ACETONE (CAS 67-64-1)	TWA	590 mg/m3	
		250 ppm	
METHYLCYCLOHEXANE (CAS 108-87-2)	TWA	1600 mg/m3	
		400 ppm	
Naphtha (petroleum), hydrotreated light (CAS 64742-49-0)	TWA	400 mg/m3	
,		100 ppm	
Solvent naphtha (petroleum), light aliph. (CAS 64742-89-8)	TWA	400 mg/m3	
,		100 ppm	
TOLUENE (CAS 108-88-3)	STEL	560 mg/m3	
		150 ppm	
	TWA	375 mg/m3	
		100 ppm	

Biological limit values

Components	re Indices Value	Determinant	Specimen	Sampling Time
ACETONE (CAS 67-64-1)	25 mg/l	Acetone	Urine	*
TOLUENE (CAS 108-88-3)	0.3 mg/g	o-Cresol, with hydrolysis	Creatinine in urine	*
	0.03 mg/l	Toluene	Urine	*
	0.02 mg/l	Toluene	Blood	*

^{* -} For sampling details, please see the source document.

Exposure guidelines

US - California OELs: Skin designation

TOLUENE (CAS 108-88-3)

Can be absorbed through the skin.

US - Minnesota Haz Subs: Skin designation applies

TOLUENE (CAS 108-88-3) Skin designation applies.

Appropriate engineering controls

Provide eyewash station and safety shower. Use adequate ventilation to control airborne concentrations below the exposure limits/guidelines. If user operations generate a vapor, dust and/or mist, use process enclosure, appropriate local exhaust ventilation, or other engineering controls to control airborne levels below the recommended exposure limits/guidelines.

Individual protection measures, such as personal protective equipment

Eye/face protection Wear safety glasses with side shields (or goggles).

Skin protection

Hand protection Suitable chemical protective gloves should be worn when the potential exists for skin exposure.

The choice of an appropriate glove does not only depend on its material but also on other quality features and is different from one producer to the other. Silver Shield® - PE/EVAL/PE gloves are

recommended.

Other Wear appropriate chemical resistant clothing if applicable.

Respiratory protectionIf engineering controls do not maintain airborne concentrations to a level which is adequate to protect worker health, an approved respirator must be worn. Respirator selection, use and maintenance should be in accordance with the requirements of OSHA Respiratory Protection

Standard 29 CFR 1910.134 and/or Canadian Standard CSA Z94.4.

FIR No.: 186859 SDS US Version: 03 4 / 10

Issue Date: 07-10-2023