### SAFETY DATA SHEET

# Honeywell

## 000000011078

Version 3.2 Revision Date 08/03/2018 Print Date 05/08/2019

protective equipment and emergency procedures

Keep people away from and upwind of spill/leak.

Wear personal protective equipment. Unprotected persons

must be kept away.

Wear self-contained breathing apparatus and protective suit.

Eliminate all ignition sources if safe to do so.

Avoid skin contact with leaking liquid (danger of frostbite).

Ventilate the area.

Vapors may travel to areas away from work site before

igniting/flashing back to vapor source.

Vapours are heavier than air and can cause suffocation by

reducing oxygen available for breathing. Avoid accumulation of vapours in low areas.

Unprotected personnel should not return until air has been

tested and determined safe.

Ensure that the oxygen content is >= 19.5%.

Environmental precautions

Prevent further leakage or spillage if safe to do so.

The product evapourates readily.

Discharge into the environment must be avoided.

Methods and materials for containment and cleaning

up

Use explosion-proof equipment.

No sparking tools should be used.

Ventilate the area. Allow to evaporate.

#### **SECTION 7. HANDLING AND STORAGE**

### Handling

Precautions for safe

handling

Handle with care.

Wear personal protective equipment.

Do not breathe vapour.

Avoid contact with skin, eyes and clothing.

Use only in well-ventilated areas.

Pressurized container. Protect from sunlight and do not expose

to temperatures exceeding 50 °C.

Follow all standard safety precautions for handling and use of

compressed gas cylinders.
Use authorized cylinders only.

Protect cylinders from physical damage.

Do not puncture or drop cylinders, expose them to open flame

or excessive heat.

Page 5 / 17