MATERIAL SAFETY DATA SHEET

Section 6. Accidental Release Measures

Steps to be taken if material is released or spilled:

Wear appropriate personal protective equipment if large amounts of dust are generated. Avoid generating dust when collecting material. Collect and label waste for approved disposal in accordance with all Federal, State and Local laws and regulations.

Section 7. Handling and Storage

Avoid generating dust and dust accumulation. Remove the accumulated dust by suitable industrial vacuum cleaner, central exhausting, or wet methods. Store this product in a ventilated, dry storage area. Do not store with oxidizing materials or corrosive materials (Acids and bases).

Section 8. Exposure Controls/Personal Protection

Ventilation: Under some industrial conditions, use of local ventilation may be

appropriate to control dust or vapor hazards.

Respiratory Protection: If needed, use a NIOSH-approved dust mask/respirator when needed

to control exposure to respirable dust. Follow OSHA requirements

found in 29 CFR 1910.134 regarding the use of respirators.

Eye Protection: Use safety glasses with side shields when handling material.

Skin Protection: Use appropriate rubber gloves when handling material. Light

protective clothing is recommended. Wash hands before eating.

Note: Personal protection information in Section 8 is based upon general information for normal uses and conditions. Where special or unusual uses or conditions exist, it is suggested that the assistance of an industrial hygienist or other qualified

professional be sought.

Section 9. Physical and Chemical Properties

Appearance: Grey solid

Odor: Not characteristic

Melting Point: Not determined

Boiling Point: Not determined

Vapor Pressure: Not determined

Vapor Density (Air = 1): Not determined

Solubility in Water: Practically insoluble

Specific Gravity ($H_2O = 1$): Not determined

Percent Volatile by Volume: Not determined

Evaporation Rate (Ethyl Ether = 1): Not determined

Viscosity: Not determined