| | Methods for Clean up | | Small spill: Move containers from spill area. Vacuum or sweep up material and place in a designated, labeled waste container. Dispose of via a licensed waste disposal contractor. Large spill: Move containers from spill area. Prevent entry into sewers, water courses, basements, or confined areas. Vacuum or sweep up material and place in a designated, labeled waste container. Dispose of via a licensed waste disposal contractor. Note: See section 1 for emergency contact information and section 13 for waste disposal. | | | |
|----|---|---|---|----------------|---------|--|
| 7. | Handling and Sto | Handling and Storage | | | | |
| 7. | Handling | age | Put on appropriate personal protection equipment (see section 8). Eating, drinking, and smoking should be prohibited in areas where this material is handled, stored, and processed. Workers should wash hands and face before eating, drinking, and smoking. Remove contaminated clothing and protective equipment before entering eating areas. | | | |
| | Storage | | Store in accordance with local regulations. Store in original container protected from direct sunlight in a dry, cool, and well-ventilated area, away from incompatible materials (see section 10) and food and drink. Keep container tightly closed and sealed until ready for use. Containers that have been opened must be carefully resealed and kept upright to prevent leakage. Do not store in unlabeled containers. Use appropriate containment to avoid environmental contamination. | | | |
| 8. | Exposure Limits and Personal Protective Equipment | | | | | |
| | United States | | | | | |
| | | Occupational Exposure Limits ngredient Exposure Limits | | | | |
| | Canada Occupational Exposure Limits | | | | | |
| | Ingredient | List Name | TWA (8 Hours) | STEL (15 mins) | Ceiling | |
| | | | Mexico | | | |
| | | | pational Exposure Limits | | | |
| | Ingredient | | Exposure Limits | | | |
| | If this product contains in gradients with supervise in | | | | | |
| | Recommended Monitoring Procedures | | If this product contains ingredients with exposure limits, personal, workplace, atmosphere, or biological monitoring may be required to determine the effectiveness of the ventilation or other control measures and/or the necessity to use respiratory protective equipment. | | | |
| | Engineering Measure | s | No specific ventilation requirements. Good general ventilation should be sufficient to control worker exposure to airborne contaminants. If this product contains ingredients with exposure limits, use process enclosures, local exhaust ventilation or other engineering controls to keep worker exposure below any recommended or statutory limits. | | | |
| | Hygiene Measures | | Wash hands, forearms and face thoroughly after handling chemical products, before eating, smoking or using the lavatory and at the end of the working period. Appropriate techniques should be used to remove potentially contaminated clothing. Wash contaminated clothing before reusing. Ensure that eyewash stations and safety showers are close to the workstation location. | | | |