8. Exposure controls/personal protection

Occupational exposure limits

_			_		
 S.		$\boldsymbol{\frown}$	c	ш	•
	_			п	4

Components	Туре	Value	Form		
Pet coke (CAS 64743-05-1)	PEL	5 mg/m3 15 mg/m3	Respirable fraction. Total dust.		
US. OSHA Table Z-1 Limits	for Air Contaminants (29 CFR 1910.1000)				
Components	Туре	Value	Form		
Barium sulphate (CAS 7727-43-7)	PEL	5 mg/m3	Respirable fraction.		
		15 mg/m3	Total dust.		
Calcium dihydroxide (CAS 1305-62-0)	PEL	5 mg/m3	Respirable fraction.		
,		15 mg/m3	Total dust.		
Graphite (CAS 7782-42-5)	PEL	5 mg/m3	Respirable fraction.		
US. OSHA Table Z-3 (29 CF	R 1910.1000)	15 mg/m3	Total dust.		
Components	Туре	Value	Form		
Graphite (CAS 7782-42-5)	TWA	15 mppcf			
Mullite (CAS 1302-93-8)	TWA	5 mg/m3	Respirable fraction.		
Mainto (6/16 1662 66 6)		15 mg/m3	Total dust.		
		50 mppcf	Total dust.		
		15 mppcf	Respirable fraction.		
ACGIH					
Components	Туре	Value	Form		
Pet coke (CAS 64743-05-1)	TWA	3 mg/m3	Respirable fraction.		
US. ACGIH Threshold Limit	t Values	10 mg/m3	Total dust.		
Components	Туре	Value	Form		
Barium sulphate (CAS 7727-43-7)	TWA	5 mg/m3	Inhalable fraction.		
Calcium dihydroxide (CAS 1305-62-0)	TWA	5 mg/m3			
Graphite (CAS 7782-42-5)	TWA	2 mg/m3	Respirable fraction.		
Mullite (CAS 1302-93-8)	TWA	1 mg/m3	Respirable fraction.		
US. NIOSH: Pocket Guide to	o Chemical Hazards				
Components	Туре	Value	Form		
Barium sulphate (CAS 7727-43-7)	TWA	5 mg/m3	Respirable.		
Calcium dihydroxide (CAS	TWA	10 mg/m3 5 mg/m3	Total		
1305-62-0)		_	.		
Graphite (CAS 7782-42-5)	TWA	2.5 mg/m3	Respirable.		
ogical limit values	No biological exposure limits noted for the ingr	()			
ropriate engineering trols	Use explosion-proof electrical equipment if airborne dust levels are high. Provide adequate ventilation. Observe Occupational Exposure Limits and minimize the risk of inhalation of dust.				
	, such as personal protective equipment				
Eye/face protection	Wear approved safety goggles.				
Skin protection Hand protection	Wear protective gloves (i.e. latex, nitrile). Suita	ible aloves can be re-	commended by the alove		
•	supplier.	ibio gioves can be le	commended by the glove		
Other	Wear suitable protective clothing.				

FM2160, FM2123, AB-607 SDS US