WPS-AKE-001 - Non-Asbestos Drum Brake Lining L635

Revision Date 23-Sep-2014

Precautions for safe handling

Wash thoroughly after handling. Avoid contact with eyes. Wear personal protective Handling

equipment. Refer to Section 8.

Conditions for safe storage, including any incompatibilities

Storage Keep in a dry, cool and well-ventilated place. Keep out of the reach of children.

Incompatible Products None known.

## 8. EXPOSURE CONTROLS / PERSONAL PROTECTION

## Control parameters

## **Exposure Guidelines**

Chemical Name	ACGIH TLV	OSHA PEL	NIOSH IDLH
Calcium carbonate 471-34-1	-	TWA: 15 mg/m³ TWA: 5 mg/m³ (vacated) TWA: 15 mg/m³ (vacated) TWA: 5 mg/m³	TWA: 10 mg/m³ total dust TWA: 5 mg/m³ respirable dust
Calcium hydroxide 1305-62-0	TWA: 5 mg/m <sup>3</sup>	TWA: 15 mg/m³ total dust TWA: 5 mg/m³ respirable fraction (vacated) TWA: 5 mg/m³ not in effect as a result of reconsideration	TWA: 5 mg/m³
Glass, oxide 65997-17-3	TWA: 1 fiber/cm3 respirable fibers: length >5 µm, aspect ratio >=3:1, as determined by the membrane filter method at 400-450X magnification [4-mm objective], using phase-contrast illumination TWA: 5 mg/m³ inhalable fraction	-	-
Copper 7440-50-8	TWA: 0.2 mg/m³ fume	TWA: 0.1 mg/m³ fume TWA: 1 mg/m³ dust and mist (vacated) TWA: 0.1 mg/m³ Cu dust, fume, mist	IDLH: 100 mg/m³ dust, fume and mist TWA: 1 mg/m³ dust and mist TWA: 0.1 mg/m³ fume
Calcium molybdate 7789-82-4	TWA: 10 mg/m³ Mo inhalable fraction TWA: 3 mg/m³ Mo respirable fraction	TWA: 15 mg/m³ total dust (vacated) TWA: 10 mg/m³ Mo	IDLH: 5000 mg/m³ Mo
Chromium (III) oxide 1308-38-9	TWA: 0.5 mg/m³ Cr	TWA: 0.5 mg/m³ Cr (vacated) TWA: 0.5 mg/m³ Cr	IDLH: 25 mg/m³ Cr(III) TWA: 0.5 mg/m³ Cr

ACGIH TLV: American Conference of Governmental Industrial Hygienists - Threshold Limit Value. OSHA PEL: Occupational Safety and Health Administration - Permissible Exposure Limits. NIOSH IDLH: Immediately Dangerous to Life or Health.

Other Exposure Guidelines Vacated limits revoked by the Court of Appeals decision in AFL-CIO v. OSHA, 965 F.2d 962

(11th Cir., 1992).

Appropriate engineering controls

Showers **Engineering Measures** 

> Eyewash stations Ventilation systems

Individual protection measures, such as personal protective equipment

**Eye/Face Protection** No special protective equipment required. Risk of contact, wear: Safety glasses with

side-shields.

No protective equipment is needed under normal use conditions. Under non-recommended **Skin and Body Protection** 

use conditions or altered form of product leather or canvas work gloves are recommended.

None required under normal usage. If exposure limits are exceeded or irritation is **Respiratory Protection** 

experienced, approved respiratory protection should be worn.