| 3. | Composition/Component Data | | | | |
|----------|---|---|--|---|---|
| | | | 0.46.31 | FINITES | |
| | Name | | CAS Number | EINECS Number | % |
| | 1-Decene, homopolymer, hydrogenated | | 68037-01-4 | | 50-65 |
| | Calcium carbonate | | 471-34-1 | | 10-13 |
| | Sulfonic acids, petroleum, calcium salts | | 61789-86-4 | | 10-13 |
| | Calcium di(acetate) | | 62-54-4 | | 10-13 |
| | Calcium(2+) 12-hydroxyoctadecanoate | | 3159-62-4 | | 3-5 |
| | Calcium borate | | 13701-64-9 | | 3-6 |
| | No Hazardous or Reportable Ingredients | | | | |
| 4. | First Aid Measures | | | | |
| | Eye Contact | Check for and remove any contact lenses. Immediately flush eyes with plenty of water for at least 15 minutes, occasionally lifting the upper and lower eyelids. Get medical attention if symptoms occur. | | | |
| | Skin Contact | In case of contact, immediately flush skin with plenty of water for at least 15 minutes while removing contaminated clothing and shoes. Wash clothing before reuse. Get medical attention if symptoms occur. | | | |
| | Inhalation | Move exposed person to fresh air. If not breathing, if breathing is irregular or if respiratory arrest occurs, provide artificial respiration or oxygen by trained personnel. Loosen tight clothing such as a collar, tie, belt, or waistband. Get medical attention if symptoms occur. Wash out mouth with water. Do not induce vomiting unless directed to do so my medical personnel. Never give anything by mouth to an unconscious person. Get medical attention if symptoms occur. | | | |
| | Ingestion | | | | |
| | Protection for first-aiders | sui | o action shall be taken involving any personal risk or without uitable training. | | |
| | Note to Physician | trea | | Treat symptomatically nediately if large quar | |
| 5. | Firefighting Measures | | | | |
| Ο. | Suitable Extinguishing Media | Dry | Chemical, CO _{2.} Foan | or Water Foo | |
| | Special Exposure Hazards | Pro vic inv | Promptly isolate the scene by removing all persons vicinity of the incident if there is a fire. No action shal involving any personal risk or without suitable training. | | |
| | Hazardous thermal decomposition products | 1 | | carbon monoxide, small amounts of other | |
| | Special protective equipment for firefighters | bre | Fire-fighters should wear protective equipment and self-conta breathing apparatus (SCBA) with a full face-piece operate positive pressure mode. | | |
| 6. | Accidental Release Measures | | | | |
| . | Personal Precautions | sui and thro equ | table training. Evacual d unprotected personiough spilled material. uipment (see Section 8 | | Keep unnecessary not touch or walk ersonal protection |
| | Environmental Precautions | wat the | terways, drains, and | material and runoff and sewers. Inform the rele sed environmental p | vant authorities if |