

Product name: RENOLIT CX-TP 1

Specific end use(s): Not available.

8 EXPOSURE CONTROLS / PERSONAL PROTECTION

Exposure Limits

Chemical name	Туре	Exposure Limit Values	Source
Molybdenum thiocarbamate - Inhalable fraction as Mo	TWA	10 mg/m3	US. ACGIH Threshold Limit Values (02 2012)
Molybdenum thiocarbamate - Respirable fraction as Mo	TWA	3 mg/m3	US. ACGIH Threshold Limit Values (02 2012)
Molybdenum thiocarbamate - Respirable fraction as Mo	TWA	0.5 mg/m3	US. ACGIH Threshold Limit Values (02 2012)
Molybdenum thiocarbamate - Total dust as Mo	PEL	15 mg/m3	US. OSHA Table Z-1 Limits for Air Contaminants (29 CFR 1910.1000) (02 2006)
Molybdenum thiocarbamate - as Mo	PEL	5 mg/m3	US. OSHA Table Z-1 Limits for Air Contaminants (29 CFR 1910.1000) (02 2006)
Molybdenum thiocarbamate - Total dust as Mo	TWA	10 mg/m3	US. OSHA Table Z-1-A (29 CFR 1910.1000) (1989)
Molybdenum thiocarbamate - as Mo	TWA	5 mg/m3	US. OSHA Table Z-1-A (29 CFR 1910.1000) (1989)
disodium tetraborate - Inhalable fraction.	STEL	6 mg/m3	US. ACGIH Threshold Limit Values (02 2012)
disodium tetraborate - Inhalable fraction.	TWA	2 mg/m3	US. ACGIH Threshold Limit Values (02 2012)
disodium tetraborate	TWA	10 mg/m3	US. OSHA Table Z-1-A (29 CFR 1910.1000) (1989)

Exposure controls

Appropriate engineering controls:

No data available.

Individual protection measures, such as personal protective equipment

General information: Wash hands before breaks and after work. Use personal protective

equipment as required. Personal protection equipment should be chosen according to the CEN standards and in discussion with the supplier of the personal protective equipment. The usual precautionary measures should

be adhered to inhandling the chemicals or the mineral oil products.

Eye/face protection: Wear goggles/face shield.

Skin protection

Hand Protection: Nitrile butyl rubber (NBR). Avoid long-term and repeated skin contact.

Suitable gloves can be recommended by the glove supplier. Use skin protection cream for preventive skin protection. Protective gloves, where permitted in acc. to safety directions. The exact break trough time has to be

found out by the manufacturer of the protective gloves and has to be

observed.

Other: Do not carry cleaning cloths impregnated with the product in trouser

pockets. Wear suitable protective clothing.

Respiratory Protection: In case of inadequate ventilation use suitable respirator. Seek advice from

local supervisor. Avoid breathing vapour/ aerosol.