Section 7 Handling and Storage

Handling

Handle in accordance with good industrial hygiene and safety practices. Minimize dust generation. Use adequate ventilation if dust is generated.

Inhalation: Avoid prolonged or repeated breathing of dust. Avoid prolonged or repeated contact with skin. Skin:

Avoid eye contact. Eye:

Storage

Store in a dry area. Contact with moisture may promote rust.

Section 8: Exposure Controls / Personal Protection

Exposure Controls

If user operations generate dust, use ventilation to keep exposure to airborne contaminants below applicable exposure limits.

Personal Protective Equipment

Eye / Face: Use protective safety glasses with side shields or goggles if dust is generated. Individuals with sensitive skin should wear protective gloves and clothing that Skin:

covers any skin that may come into repeated or prolonged contact with this

product or any dust generated from this product.

A respiratory protection program that meets OSHA's 29 CFR 1910.134 and ANSI Respiratory:

Z88.2 requirements must be followed whenever workplace conditions warrant a

respirator's use.

Exposure Guidelines

001309-48-4 Magnesium Oxide

750 ma/m³ IDLH:

OSHA PEL:

ACGIH TLV:

15 mg/m³ TWA Total particulate 10 mg/m³ TWA 10 mg/m³ TWA, 20 mg/m³ STEL CANADA

007440-44-0 Carbon / Graphite

OSHA PEL: 15 mg/m³ TWA, Total Dust; 5 mg/m³ TWA, Respirable Fraction 10 mg/m³ TWA, Total Dust; 5 mg/m³ TWA, Respirable Fraction **CANADA**

007727-43-7 Barium Sulfate

> 15 mg/m³ TWA, Total Dust; 5 mg/m³ TWA, Respirable Fraction OSHA PEL: 10 mg/m³ TWA. Inhalable (total) particulate matter containing no ACGIH TLV:

asbestos and , 1% crystalline silica.

10 mg/m³ TWA, Total Dust; 5 mg/m³ TWA, Respirable Fraction NIOSH:

060676-86-0 Silica amorphous, fused

0.1 mg/m³ TWA, Respirable fraction of particulate matter from a ACGIH TLV:

size selector.

0.3 mg/m³ TWA, Total mass, 0.1 mg/m³ TWA, Respirable mass. CANADA:

Haldex MSDS # 101 Page 3 of 5 March 2005