Material Data Sheet for N550H/B23

MSDS No.: NAC-DP-03-24-06A Current Issue Date: May.23 2013

## **SECTION-7** HANDLING AND STORAGE

**Handling:** Keep away from fire, heat, and flame. Avoid breathing or creating dust.

Storage: Keep away from fire, heat, and flame. Keep material dry. Keep away from acids, alkalis.

Exhaust ventilation is recommended.

SECTION-8 EXPOS	SURE CON	TROLS / PERSONAL PROTECTION	
Exposure guidelines :			
Ingredient Name	CAS No	OSHA PEL	ACGIH TLV
Calcium hydroxide	1305-62-0	15mg/m <sup>3</sup> TWA(total dust)	5mg/m <sup>3</sup> TWA
Calcium carbonate	471-34-1	5mg/m <sup>3</sup> TWA(respirable fraction) 5mg/m <sup>3</sup> TWA(respirable fraction) 15mg/m <sup>3</sup> TWA(Total dust)	10mg/m <sup>3</sup> TWA
Tin	7440-31-5	2mg/m³ TWA(dust, as Sn)	2mg/m <sup>3</sup> TWA
Zirconium silicate	10101-52-7	5mg/m <sup>3</sup> TWA(dust, as Zr)	5mg/m <sup>3</sup> TWA
Mica	12001-26-2	20mppcf TWA	$3 \text{mg/m}^3 \text{TWA}$
Copper	7440-50-8	0.1mg/m <sup>3</sup> TWA (fume)	0.2mg/m <sup>3</sup> TWA (fume)
Barium sulfate	7727-43-7	1mg/m <sup>3</sup> TWA (dust and mist) 15mg/m <sup>3</sup> TWA (total dust) 5mg/m <sup>3</sup> TWA (respirable fraction)	mg/m <sup>3</sup> TWA (dust and mist) 10mg/m <sup>3</sup> TWA
Graphite	7782-42-5	15mg/m³ TWA (synthetic, total dust) 5mg/m³ TWA (synthetic, respirable fraction	2mg/m³ TWA (all forms except graphite fibers, respirable fraction)
Titanium dioxide	13463-67-7	15mg/m <sup>3</sup> TWA(total dust)	$10 \text{mg/m}^3 \text{ TWA}$
Zirconium dioxide	1314-23-4	5mg/m³ TWA(dust, as Zr)	5mg/m <sup>3</sup> TWA
Cured Phenolic Resi	n none	none	none

## **Engineering controls:**

Friction materials are molded articles and neither gives off nor reveals hazard materials. But machining (grinding, drilling, etc) can result in the release of airborne dust, and dust excess OSHA permissible exposure Level (PEL) is considered hazardous.

## **Personal Protective Equipment:**

Eye/face protection : Safety glasses are recommended.

Skin protection: Niterile rubber gloves are recommended.

Respiratory protection: Not required under normal conditions and adequate ventilation. If the

exposure limit is exceeded, use of NIOSH approved face mask(N-95 or

better) is recommended.

In the case of fire or explosion, Self Contained Breathing Apparatus

(SCBA) should be used.

General hygiene considerations: Wash thoroughly after handling.

Tox no.: 178587 Last Reviewed (C2 Status): 22/Oct/2015

Page 3 of 8