FIR No. 173745

Contact product manufacturer for latest (M)SDS

WPS-AKE-053 - Non-Asbestos Friction Material NS307, NS307H Revision Date 18-May -2015

Handling Wash thoroughly after handling.

Conditions for safe storage, including any incompatibilities

Storage Keep in a dry, cool and well-ventilated place. Keep out of the reach of children.

Incompatible Products None known.

8. EXPOSURE CONTROLS / PERSONAL PROTECTION

Control parameters

Exposure Guidelines

Chemical Name	ACGIH TLV	OSHA PEL	NIOSH IDLH
Copper	TWA: 0.2 mg/m ³ fume	TWA: 0.1 mg/m ³ fume	IDLH: 100 mg/m ³ dust, fume and
7440-50-8		TWA: 1 mg/m ³ dust and mist	mist
		(vacated) TWA: 0.1 mg/m ³ Cu	TWA: 1 mg/m ³ dust and mist
		dust, fume, mist	TWA: 0.1 mg/m ³ fume
Zircon	STEL: 10 mg/m ³ Zr	TWA: 5 mg/m ³ Zr	IDLH: 25 mg/m ³ Zr
14940-68-2	TWA: 5 mg/m ³ Zr	(vacated) TWA: 5 mg/m ³ Zr	TWA: 5 mg/m³ except Zirconium
		(vacated) STEL: 10 mg/m ³ Zr	tetrachloride Zr
			STEL: 10 mg/m ³ Zr
Mica	TWA: 3 mg/m ³	TWA: 20 mppcf (<1% crystalline	IDLH: 1500 mg/m ³ containing
12001-26-2		silica)	<1% quartz
		3 mg/m³ (vacated)	TWA: 3 mg/m³ respirable dust
Graphite	-	TWA: 15 mg/m ³ total dust	IDLH: 1250 mg/m ³
7782-42-5		synthetic	TWA: 2.5 mg/m ³ respirable
		TWA: 5 mg/m³ total dust	dust
		synthetic	
		(vacated) TWA: 2.5 mg/m ³	
		respirable dust natural	
		(vacated) TWA: 10 mg/m³ total	
		dust synthetic	
		(vacated) TWA: 5 mg/m ³	
		respirable fraction synthetic	
		TWA: 15 mppcf natural	
Carbon black	TWA: 3.5 mg/m ³	TWA: 3.5 mg/m ³	IDLH: 1750 mg/m ³
1333-86-4		(vacated) TWA: 3.5 mg/m ³	TWA: 3.5 mg/m ³
			TWA: 0.1 mg/m³ Carbon black in
			presence of Polycyclic aromatic
ACCULTIVE Assessing Conference		- Thursday I have the last three is Notice	hydrocarbons PAH

ACGIH TLV: American Conference of Governmental Industrial Hygienists - Threshold Limit Value. OSHA PEL: Occupational Safety and Health Administration - Permissible Exposure Limits. NIOSH IDLH: Immediately Dangerous to Life or Health.

Other Exposure Guidelines Vacated limits revoked by the Court of Appeals decision in AFL-CIO v. OSHA, 965 F.2d

962 (11th Cir., 1992).

Appropriate engineering controls

Engineering Measures Showers

Eyewash stations Ventilation systems

Individual protection measures, such as personal protective equipment

Eye/Face ProtectionNo special protective equipment required. Risk of contact, wear: Safety glasses with

side-shields.

Skin and Body Protection No protective equipment is needed under normal use conditions. Under non-recommended

use conditions or altered form of product leather or canvas work gloves are recommended.

Respiratory Protection None required under normal usage. If exposure limits are exceeded or irritation is

experienced, approved respiratory protection should be worn.

Hygiene Measures Do not eat, drink or smoke when using this product. Regular cleaning of equipment, work

area and clothing is recommended. Keep away from food, drink and animal feeding stuffs.