

## **MATERIAL SAFETY DATA SHEET**

## 1. Product and Company Identification

Material name DLB040 Version # 03

Revision date 01-22-2016

Product Name DLB040 Friction Material (Asbestos free)

Manufacturer information Shandong Double Link Brake Material Co., Ltd.

No. 8, Haicheng Street, Rushan City, Shandong Province, 264500, China

> Telephone Number: 0086- 631-660-8097 Attn: Jiaju Geng

2. Hazards Identification

Physical state Solid.

Appearance Greyish solid
Emergency overview WARNING

Exposure to airborne dust may cause eye, skin and respiratory tract irritation. May cause allergic

skin reaction.

High concentrations of dust may form explosive mixture with air.

Potential health effects Inhalation. Eye contact. Skin contact.

Routes of exposure

Dust may irritate the eyes.

Eyes Dust may irritate skin. May cause allergic skin reaction.

Skin May cause respiratory tract irritation. Dust may irritate throat and respiratory system and cause

couahina.

Inhalation May cause discomfort if swallowed.

Eyes. Skin. Respiratory system

Target organs
Frequent inhalation of fume/dust over a long period of time increases the risk of developing lung

diseases.

Chronic effects

Upper respiratory tract irritation. Coughing. Irritation of eyes and mucous membranes. Skin

irritation. Sensitization.

Signs and symptoms

The product components are not classified as environmentally hazardous. However, this does not

Potential environmental effects

exclude the possibility that large or frequent spills can have a harmful or damaging effect on the

environment.

## 3. Composition / Information on Ingredients

Components	CAS#	Percent
Straight Phenolic Resin Asbestos free	9003-35-4	15-17%
Cashew nutshell Polymer Asbestos free	68583-06-2	10-18%
Synthetic Barium Sulfate Asbestos free, less than 0.1% Crystalline Silica	7727-43-7	13-16%
Glass Fiber Asbestos free	65997-17-3	13-15%
Powder Aluminum Oxide Asbestos free	1344-28-1	1-3%
Synthetic Graphite Asbestos free	7782-42-5	5-8%
Calcium Carbonate Asbestos free	1317-65-3	25-28%
Calcium Hydroxide Asbestos free	1305-62-0	6-9%

## 4. First Aid Measures

First aid procedures

**Eye contact**Dust in the eyes: Do not rub eyes. Immediately flush with plenty of water for at least 15 minutes. **Skin contact**Remove contact lenses, if present and easy to do. Get medical attention if irritation develops and

Inhalation persists.

Flush skin thoroughly with water. Get medical attention if irritation develops or persists.

Move to fresh air. Get medical attention if any discomfort continues.