Tox no.: 180134 Last Reviewed (C2 Status): 13/Jun/2007

MSDS No.: NAC060707 <u>Material Data Sheet for N561HB</u>

Current Issue Date: May,31 2007 Page 2 of 8

OSHA Hazardous Components:

Ingredients	CAS No.	TSCA No.	Weight %
Cured Phenolic Resin	Not Applicable	Not Listed	1-10
Calcium hydroxide	1305-62-0	1305-62-0	5-10
Zirconium silicate	10101-52-7	10101-52-7	1-5
Mica	12001-26-2	Exempted (Natural substance)	5-10
Copper	7440-50-8	7440-50-8	10-20
Barium sulfate	7727-43-7	7727-43-7	10-20
Graphite	7782-42-5	7782-42-5	5-10
Tin sulfide	1314-95-0	1314-95-0	1-5
Zirconium dioxide	1314-23-4	1314-23-4	5-10
Lithium potassium titanium oxide	39318-30-4	39318-30-4	10-20

## SECTION-4 FIRST AID MEASURES

If any of the symptoms persist, seek medical attention immediately.

Skin: Wash skin with soap and water after handling parts. Seek medical attention for

persistent irritation.

Eyes: Flush eye with cool running water if dust becomes embedded.

Seek medical attention if reddening persists.

Inhalation: Remove affected person to fresh air.

Ingestion: Not anticipated route of entry.

Note to Physician: No special first aid or medical treatment procedures are required.

## SECTION-5 FIRE FIGHTING MEASURES

Suitable extinguishing media: Water, Splay, Dry, Chemical, Form, CO2

Protection of firefighters: Decomposition product may be irritating to eyes, skin and the respiratory

tract. Firefighters should wear self-contained breathing apparatus.

## SECTION-6 ACCIDENTAL RELEASE MEASURES

Personal Precautions: In case dust may occur, use personal protective equipment recommended

in Section8.

Environmental Precautions: Not applicable. Method for containment: Not applicable.

Method for clean-up: Use wet method or vacuums to clean up dust from products.

Other information: Not required.

## SECTION-7 HANDLING AND STORAGE

Handling: Keep away from fire, heat, and flame. Avoid breathing or creating dust.

Tox no.: 180134 Last Reviewed (C2 Status): 13/Jun/2007