FIR No. 177239

Contact product manufacturer for latest (M)SDS

MSDS No.: VCM-546 ADVICS CO.,LTD. VC036

Date prepared: 2018.05.31

Page 2 of 5

3. COMPOSITION/INFORMATION ON INGREDIENTS

Chemical name of component	CAS No.	Content wt.%	OSHA PEL	ACGIH TLV
Copper fiber	7440-50-8	12	1mg/m ³	1mg/m ³
Antimony sulfide	1345-04-6	2.0	0.5mg/m^3	0.5mg/m^3
Zirconium silicate	10101-52-7	6.0	5mg/m ³	5mg/m^3
Iron oxide	1309-37-1	8.0	10mg/m^3	5mg/m^3
Calcium hydroxide	1305-62-0	2.0	15mg/m³ (Total dust)	5mg/m ³
Alkaline-earth silicate wool	436083-99-7	2.0	15mg/m ³ (Total dust)	10mg/m^3
Mica	12001-26-2		20mppcf	3mg/m^3
Graphite (synthetic)	7782-42-5		15mg/m³ (Total dust)	$2mg/m^3$
Calcium silicate	1344-95-2		15mg/m³(Total dust)	10mg/m^3
Barium sulfate	7727-43-7		15mg/m³ (Total dust)	10mg/m^3
Cured phenolic resin	9003-35-4			
p-Aramid pulp	26125-61-1			
Cashew nutshell liq.polymer	68583-07-3		***	
mixture				
1				

(Note: mppcf – million particles per cubic foot of air)

4. FIRST AID MEASURES

"If any of the symptoms persists, seek medical attention immediately."

Skin:

Wash skin with soap and water after handling compound. Seek medical attention for

persistent irritation.

Eyes:

Flush eyes with cool running water if dust becomes embedded. Seek medical attention

if reddening persists.

Inhalation:

Remove affected person to fresh air.

Ingestion:

Not an anticipated route of entry.

Advice to physician:

No specialized first aid or medical treatment procedures are required.