US - Minnesota Haz Subs: Skin designation applies

1,4-DIOXANE (CAS 123-91-1) Skin designation applies.

US - Tennessee OELs: Skin designation

1,4-DIOXANE (CAS 123-91-1) Can be absorbed through the skin.

US ACGIH Threshold Limit Values: Skin designation

1,4-DIOXANE (CAS 123-91-1) Danger of cutaneous absorption ETHYLENE OXIDE (CAS 75-21-8) Danger of cutaneous absorption

US. OSHA Table Z-1 Limits for Air Contaminants (29 CFR 1910.1000)

1,4-DIOXANE (CAS 123-91-1) Can be absorbed through the skin.

Appropriate engineering

controls

Provide eyewash station and safety shower. Use adequate ventilation to control airborne concentrations below the exposure limits/quidelines. If user operations generate a vapor, dust and/or mist, use process enclosure, appropriate local exhaust ventilation, or other engineering controls to control airborne levels below the recommended exposure limits/guidelines.

Individual protection measures, such as personal protective equipment

Eye/face protection Wear safety glasses with side shields (or goggles).

Skin protection

Suitable chemical protective gloves should be worn when the potential exists for skin exposure. Hand protection

The choice of an appropriate glove does not only depend on its material but also on other quality features and is different from one producer to the other. Use protective gloves made of: Polyvinyl

chloride (PVC).

Wear appropriate chemical resistant clothing if applicable. Other

Respiratory protection If engineering controls do not maintain airborne concentrations to a level which is adequate to

protect worker health, an approved respirator must be worn. Respirator selection, use and maintenance should be in accordance with the requirements of OSHA Respiratory Protection

Standard 29 CFR 1910.134 and/or Canadian Standard CSA Z94.4.

Thermal hazards Wear appropriate thermal protective clothing, when necessary.

General hygiene considerations

When using do not smoke. Always observe good personal hygiene measures, such as washing after handling the material and before eating, drinking, and/or smoking. Routinely wash work clothing and protective equipment to remove contaminants. Contaminated work clothing should not be allowed out of the workplace.

9. Physical and chemical properties

Appearance

Liquid. Physical state **Form** Aerosol.

CLEAR, COLORLESS Color

Odor Odorless. **Odor threshold** Not available. Not available. Ηg Melting point/freezing point Not available. Initial boiling point and boiling Not available.

range

147.9 °F (64.4 °C) Flash point

Evaporation rate Not available. Flammability (solid, gas) Not applicable.

Upper/lower flammability or explosive limits

Not available. Explosive limit - lower (%) Explosive limit - upper (%) Not available.

Not available. Vapor pressure Vapor density Not available. 0.827 (Water=1) Relative density

Solubility(ies)

Solubility (water) **Immiscible** Partition coefficient Not available.

(n-octanol/water)

Issue Date: 02-21-2025

FIR No.: 197247 SDS US Version: 02