



## Ford Information Sheet for: TEROSON VR 500

## **Purpose:**

The purpose of this Information Sheet is to provide additional hazard communication information about the Henkel product, "TEROSON VR 500", which is contained in the grease packet in the Brake Lining Kit.

## **Additional Information:**

Hazard Category: Category 2 - Skin irritation

Category 2a - Eye irritation

Signal Word: WARNING

Hazard Statements: Causes skin irritation.

Causes serious eye irritation.



Pictogram:

## **Precautionary Statements:**

Prevention: Wash affected area thoroughly after handling. Wear protective gloves, eye protection, and face

protection. Wear protective gloves (Nitrile gloves).

Response: IF ON SKIN: Wash with plenty of water. IF IN EYES: Rinse cautiously with water for several minutes.

Remove contact lenses, if present and easy to do. Continue rinsing. If skin irritation occurs: Get medical

attention. If eye irritation persists: Get medical attention. Take off contaminated clothing.

Storage: Keep in a cool, well-ventilated place away from incompatible materials.

Dispose of contents/container in accordance with local/regional/national/international regulations.

Hazards not otherwise classified (HNOC): None

SDS Reference: For additional information, please see the Safety Data Sheet (SDS) for this product @ fordsds.com

Emergency Phone Number: For 24-hour MEDICAL EMERGENCY INFORMATION, Call: 1-800-959-3673 (FORD).