## 7. Handling and storage

**7.1 Precautions for safe**Avoid the formation of dust.

handling Provide appropriate exhaust ventilation at machinery and at

places, where dust can be generated.

- Do not use brushes, pressure air or other hazardous agents to clean the brake. The use of a vacuum cleaner is

recommended.

**7.2 Storage** Keep in a dry place.

Recommended storage temperature: room temperature.

7.3 Specific end use(s) No further relevant information available

## 8. Exposure controls/personal protection

### 8.1 Exposure limits

#### Ingredients with limit values that require monitoring at the workplace:

### 1344-28-1 aluminium oxide

PEL Long-term value: 15\*; 5\*\* mg/m³

\*Total dust; \*\* Respirable fraction

REL Long-term value: 10\*5\*\* mg/m³

as Al\*Total dust\*\*Respirable/pyro powd./welding f.

TLV Long-term value: 1\* mg/m³ as Al; \*as respirable fraction

#### 1344-95-2 Silicic acid, calcium salt

PEL Long-term value: 15\* 5\*\* mg/m³

\*total dust \*\*respirable fraction

REL Long-term value: 10\* 5\*\* mg/m³

 $*total\ dust\ **respirable\ fraction$ 

TLV synthetic nonfibrous: TLV withdrawn, see App. B

#### 8.2 Exposure controls / Personal protective equipment

Respiratory protection Suitable respiratory protective device recommended

Dust mask FFP2

Hand protectionProtective-gloves (dust-resistant)\*Eye protectionSafety goggles with side protection.\*Skin protectionDust resistant protective clothing.\*

Protective and hygiene measures Do not breathe dust.

Wash hands before breaks and at the end of workday.

When using, do not eat, drink or smoke.

Handle in accordance with the general hygienic rules.

# 9. Physical and chemical properties

#### Information on basic physical and chemical properties

Physical state solid Colour grey

Odour characteristic

<sup>\*</sup> recommended for mechanical processing