## 8. Exposure controls/personal protection

## **Occupational exposure limits**

US. OSHA Table Z-1 Limits for Air Contaminants (29 CFR 1910.1000)

Components	Туре	Value	Form
Barium sulphate (CAS 7727-43-7)	PEL	5 mg/m3	Respirable fraction.
		15 mg/m3	Total dust.
Calcium silicate (CAS 1344-95-2)	PEL	5 mg/m3	Respirable fraction.
		15 mg/m3	Total dust.
Copper (CAS 7440-50-8)	PEL	1 mg/m3	Dust and mist.
		0.1 mg/m3	Fume.
Graphite (CAS 7782-42-5)	PEL	5 mg/m3	Respirable fraction.
		15 mg/m3	Total dust.
Magnesium oxide (CAS 1309-48-4)	PEL	15 mg/m3	Total particulate.
Tin sulphide (CAS 1314-95-0)	PEL	2 mg/m3	
Zirconium dioxide (CAS 1314-23-4)	PEL	5 mg/m3	
US. OSHA Table Z-3 (29 CFR 1910	).1000)		
Components	Туре	Value	
Graphite (CAS 7782-42-5)	TWA	15 mppcf	
US. ACGIH Threshold Limit Value	s		
Components	Туре	Value	Form

Components	Туре	Value	Form
Barium sulphate (CAS 7727-43-7)	TWA	5 mg/m3	Inhalable fraction.
Calcium silicate (CAS 1344-95-2)	TWA	10 mg/m3	
Copper (CAS 7440-50-8)	TWA	1 mg/m3 0.2 mg/m3	Dust and mist. Fume.
Graphite (CAS 7782-42-5)	TWA	2 mg/m3	Respirable fraction.
Magnesium oxide (CAS 1309-48-4)	TWA	10 mg/m3	Inhalable fraction.
Tin sulphide (CAS 1314-95-0)	TWA	2 mg/m3	
Zirconium dioxide (CAS 1314-23-4)	STEL	10 mg/m3	
	TWA	5 mg/m3	

## **US. NIOSH: Pocket Guide to Chemical Hazards**

Components	Туре	Value	Form
Barium sulphate (CAS 7727-43-7)	TWA	5 mg/m3	Respirable.
·		10 mg/m3	Total
Calcium silicate (CAS 1344-95-2)	TWA	5 mg/m3	Respirable.
		10 mg/m3	Total
Copper (CAS 7440-50-8)	TWA	1 mg/m3	Dust and mist.
Graphite (CAS 7782-42-5)	TWA	2.5 mg/m3	Respirable.
Tin sulphide (CAS 1314-95-0)	TWA	2 mg/m3	·
Zirconium dioxide (CAS 1314-23-4)	STEL	10 mg/m3	
	TWA	5 mg/m3	

**Biological limit values** 

No biological exposure limits noted for the ingredient(s).

Appropriate engineering controls

Use explosion-proof electrical equipment if airborne dust levels are high. Provide adequate ventilation. Observe Occupational Exposure Limits and minimize the risk of inhalation of dust.