Graphite	7782-42-5	> 1
Iron	7439-89-6	> 1
Magnesium oxide	1309-48-4	> 1
Mullite	1302-93-8	> 1
Silicon dioxide	7631-86-9	> 1
Zinc powder	7440-66-6	> 1

Composition comments

The ingredients may be released as general dust from the product by operations such as overheating, burning, machining, abrading, or riveting. This product contains a variety of ingredients all of which have become part of a bound system both physically and chemically and do not necessarily exhibit the properties of the individual components.

All concentrations are in percent by weight unless ingredient is a gas. Gas concentrations are in percent by volume.

4. First-aid measures

Inhalation Move injured person into fresh air and keep person calm under observation. If necessary, seek

hospital and take along these instructions.

Remove contaminated clothing immediately and wash skin with soap and water. Get medical Skin contact

attention if irritation develops and persists.

Immediately flush with plenty of water for up to 15 minutes. Remove any contact lenses and open Eye contact

eyelids wide apart. Get medical attention promptly if symptoms persist or occur after washing.

If swallowed, rinse mouth with water (only if the person is conscious). Get medical attention if any Ingestion

Use fire-extinguishing media appropriate for surrounding materials.

By heating and fire, toxic vapors/gases may be formed.

Exposed individuals may experience eye tearing, redness, and discomfort.

discomfort continues.

Most important

symptoms/effects, acute and delayed

Treat symptomatically.

Indication of immediate medical attention and special

treatment needed

General information

Ensure that medical personnel are aware of the material(s) involved, and take precautions to protect themselves.

5. Fire-fighting measures

Suitable extinguishing media

Unsuitable extinguishing media

None.

Specific hazards arising from

the chemical

Special protective equipment

and precautions for firefighters

Fire fighting equipment/instructions

Use standard firefighting procedures and consider the hazards of other involved materials.

Self-contained breathing apparatus and full protective clothing must be worn in case of fire.

General fire hazards This product is not flammable.

6. Accidental release measures

Personal precautions, protective equipment and emergency procedures

Use explosion-proof electrical equipment if airborne dust levels are high. Avoid dust formation. Avoid inhalation of dust and contact with skin and eyes. Wear necessary protective equipment. See Section 8 of the SDS for Personal Protective Equipment.

Methods and materials for containment and cleaning up In the event of a spill or accidental release, notify relevant authorities in accordance with all applicable regulations. Collect powder using special dust vacuum cleaner with particle filter or carefully sweep into closed container. Do not vacuum clean unless vacuum cleaners are equipped with HEPA filter. For waste disposal, see Section 13 of the SDS.

Environmental precautions

Avoid discharge into drains, water courses or onto the ground. Collect and dispose of spillage as indicated in Section 13 of the SDS.

SDS #212 SDS US