### 7. Handling and storage

Precautions for safe handling

Avoid contact with eyes, skin, and clothing. Avoid breathing mist or vapor. Avoid prolonged exposure. Provide adequate ventilation. Avoid release to the environment. Observe good industrial hygiene practices. Wear appropriate personal protective equipment. For personal protection, see

Section 8 of the SDS.

Conditions for safe storage. including any incompatibilities Store in tightly closed container. Store away from incompatible materials (see Section 10 of the SDS).

### 8. Exposure controls/personal protection

### Occupational exposure limits

The following constituents are the only constituents of the product which have a PEL, TLV or other recommended exposure limit. At this time, the other constituents have no known exposure limits.

US. ACGIH	Threshold	Limit Values
-----------	-----------	--------------

Components	Туре	Value	Form
Glycol derivative	TWA	2 mg/m3	Inhalable fraction and
			vapor.

## US. NIOSH: Pocket Guide to Chemical Hazards

Components	Туре	Value
Glycol derivative	TWA	10 mg/m3

# US. Workplace Environmental Exposure Level (WEEL) Guides

Components	Type	Value	
Alkylamine	Ceiling	26.5 mg/m3	
		5 ppm	
Glycol derivative	TWA	10 mg/m3	

**Biological limit values** 

No biological exposure limits noted for the ingredient(s).

**Exposure guidelines** 

**US WEEL Guides: Skin designation** 

Alkylamine (CAS Trade Secret) Can be absorbed through the skin.

Appropriate engineering

controls

Provide eyewash station and safety shower. Use adequate ventilation to control airborne concentrations below the exposure limits/quidelines. If user operations generate a vapor, dust and/or mist, use process enclosure, appropriate local exhaust ventilation, or other engineering controls to control airborne levels below the recommended exposure limits/quidelines.

### Individual protection measures, such as personal protective equipment

Wear safety glasses with side shields (or goggles). Eye/face protection

Skin protection

Suitable chemical protective gloves should be worn when the potential exists for skin exposure. Hand protection

The choice of an appropriate glove does not only depend on its material but also on other quality features and is different from one producer to the other. Nitrile, butyl rubber or neoprene gloves

are recommended.

Other Wear appropriate chemical resistant clothing if applicable.

If engineering controls do not maintain airborne concentrations to a level which is adequate to Respiratory protection

protect worker health, an approved respirator must be worn. Respirator selection, use and maintenance should be in accordance with the requirements of OSHA Respiratory Protection

Standard 29 CFR 1910.134 and/or Canadian Standard CSA Z94.4.

Wear appropriate thermal protective clothing, when necessary. Thermal hazards

General hygiene considerations

Always observe good personal hygiene measures, such as washing after handling the material and before eating, drinking, and/or smoking. Routinely wash work clothing and protective

equipment to remove contaminants.

### 9. Physical and chemical properties

#### **Appearance**

Liquid. Physical state Liquid. Form Color Amber. Odor Mild.

Not available. Odor threshold

7.7 pН

Issue Date: 04-13-2022

FIR No.: 176038 SDS US Version: 01 3/7