Cellulose 9004-34-6 0.5 - 1.5

**Composition comments** 

All concentrations are in percent by weight unless ingredient is a gas. Gas concentrations are in percent by volume.

The ingredients may be released as general dust from the product by operations such as overheating, burning, machining, abrading, or riveting. This product contains a variety of ingredients all of which have become part of a bound system both physically and chemically and do not necessarily exhibit the properties of the individual components.

4. First-aid measures

Inhalation Move injured person into fresh air and keep person calm under observation. If necessary, seek

hospital and take along these instructions.

Remove contaminated clothing immediately and wash skin with soap and water. Get medical Skin contact

attention if irritation develops and persists.

Immediately ush with plenty of water for up to 15 minutes. Remove any contact lenses and open Eye contact

eyelids wide apart. Get medical attention promptly if symptoms persist or occur after washing.

If swallowed, rinse mouth with water (only if the person is conscious). Get medical attention if any Ingestion

Exposed individuals may experience eye tearing, redness, and discomfort.

discomfort continues.

Most important

**General information** 

symptoms/e ects, acute and delayed

Indication of immediate medical attention and special

treatment needed

Treat symptomatically.

Ensure that medical personnel are aware of the material(s) involved, and take precautions to

protect themselves.

5. Fire- ghting measures

Suitable extinguishing media

Unsuitable extinguishing

media

Speci c hazards arising from

the chemical

Special protective equipment and precautions for re ghters

Fire ghting equipment/instructions

General re hazards

Use re-extinguishing media appropriate for surrounding materials.

None.

By heating and re, toxic vapors/gases may be formed.

Self-contained breathing apparatus and full protective clothing must be worn in case of re.

Use standard regiling procedures and consider the hazards of other involved materials.

This product is not ammable.

6. Accidental release measures

Personal precautions, protective equipment and emergency procedures

Use explosion-proof electrical equipment if airborne dust levels are high. Avoid dust formation. Avoid inhalation of dust and contact with skin and eyes. Wear necessary protective equipment. See Section 8 of the SDS for Personal Protective Equipment.

Methods and materials for containment and cleaning up In the event of a spill or accidental release, notify relevant authorities in accordance with all applicable regulations. Collect powder using special dust vacuum cleaner with particle liter or carefully sweep into closed container. Do not vacuum clean unless vacuum cleaners are equipped with HEPA Iter. For waste disposal, see Section 13 of the SDS.

Avoid discharge into drains, water courses or onto the ground. Collect and dispose of spillage as **Environmental precautions** 

indicated in Section 13 of the SDS.

7. Handling and storage

Precautions for safe handling Provide adequate ventilation. Avoid dust formation. Avoid inhalation of dust and contact with skin

and eyes. Use work methods which minimize dust production. See Section 8 of the SDS for

Personal Protective Equipment. Observe good industrial hygiene practices.

Conditions for safe storage, including any incompatibilities Store in tightly closed original container. Avoid conditions which create dust. Protect against direct sunlight.

2/7

FA 603 SDS Canada