FIR No. 186381

Eye contact Immediately flush eyes with plenty of water for at least 15 minutes. Get medical attention if

Irritation of eyes and mucous membranes.

irritation develops or persists. Remove contact lenses, if present and easy to do. Continue rinsing.

If eye irritation persists: Get medical advice/attention. Get immediate medical attention.

Ingestion

If ingestion of a large amount does occur, seek medical attention. Do not induce vomiting without medical advice. If vomiting occurs naturally, have victim lean forward to reduce risk of aspiration.

Never give anything by mouth to a victim who is unconscious or is having convulsions.

Most important

symptoms/effects, acute and

delayed

Indication of immediate medical attention and special

treatment needed

**General information** 

Treat symptomatically.

If you feel unwell, seek medical advice (show the label where possible). Ensure that medical personnel are aware of the material(s) involved, and take precautions to protect themselves.

## 5. Fire-fighting measures

Suitable extinguishing media

Unsuitable extinguishing

media

Specific hazards arising from the chemical

Special protective equipment and precautions for firefighters

Fire-fighting

Specific methods

equipment/instructions

Water fog. Foam. Dry chemical. Dry chemical powder. Carbon dioxide (CO2).

Do not use water jet as an extinguisher, as this will spread the fire.

During fire, gases hazardous to health may be formed.

Wear suitable protective equipment. Self-contained breathing apparatus and full protective clothing must be worn in case of fire.

Move containers from fire area if you can do it without risk. Wear full protective clothing, including helmet, self-contained positive pressure or pressure demand breathing apparatus, protective clothing and face mask.

Move containers from fire area if you can do so without risk.

## 6. Accidental release measures

Personal precautions. protective equipment and emergency procedures

Keep unnecessary personnel away. Keep people away from and upwind of spill/leak. Keep out of low areas. Do not touch damaged containers or spilled material unless wearing appropriate protective clothing. Ensure adequate ventilation. Local authorities should be advised if significant spillages cannot be contained. For personal protection, see section 8 of the MSDS. Observe precautions from other sections.

Methods and materials for containment and cleaning up

Soak up with inert absorbent material.

Large Spills: Stop the flow of material, if this is without risk. Dike the spilled material, where this is possible. Cover with plastic sheet to prevent spreading. Clean contaminated surface thoroughly. Absorb in vermiculite, dry sand or earth and place into containers. Prevent entry into waterways, sewer, basements or confined areas. Following product recovery, flush area with water.

Small Spills: Wipe up with absorbent material (e.g. cloth, fleece). Clean surface thoroughly to remove residual contamination.

Never return spills in original containers for re-use. For waste disposal, see section 13 of the MSDS. Clean up spills immediately, observing precautions in Protective Equipment section. Sweep up and shovel into suitable containers for disposal.

**Environmental precautions** 

Prevent entry into waterways, sewers, basements or confined areas.

## 7. Handling and storage

Precautions for safe handling

Do NOT pressurize, cut, heat, or weld containers. Empty product containers may contain product residue. Avoid prolonged or repeated skin contact with this material. Do not handle or store near an open flame, heat or other sources of ignition. Avoid breathing gas/vapors/mist/fumes. Do not take internally. Do not taste or swallow. Avoid contact with eyes. Avoid prolonged exposure. Wash thoroughly after handling.

Conditions for safe storage, including any incompatibilities

Keep away from heat and sources of ignition. Store in a closed container away from incompatible materials. Store in cool place. Store away from incompatible materials (see Section 10 of the MSDS).

## 8. Exposure controls/personal protection

Occupational exposure limits

US. OSHA Table Z-3 (29 CFR 1910.1000)

Components	Туре	Value
SILICA, AMORPHOUS, FUMED, CRYSTAL-FREE (CAS 112945-52-5)	TWA	0.8 mg/m3

Material name: NYOGEL 774H