US. NIOSH: Pocket Guide to Chemical Hazards Recommended Exposure Limits (REL)

Form Components Type TWA 435 mg/m3

100 ppm

Biological limit values

ACGIH Biological Exposure Indices (BEI)

Components	Value	Determinant	Specimen	Sampling Time
XYLENE (CAS 1330-20-7) 1.5 g/g	Methylhippuric	Creatinine	*
		acids	in urine	

^{* -} For sampling details, please see the source document.

Exposure guidelines

US - California OELs: Skin designation

4-METHYLPENTAN-2-OL (CAS 108-11-2) Can be absorbed through the skin. **CUMENE (CAS 98-82-8)** Can be absorbed through the skin.

US - Minnesota Haz Subs: Skin designation applies

4-METHYLPENTAN-2-OL (CAS 108-11-2) Skin designation applies. Skin designation applies. **CUMENE (CAS 98-82-8)**

US - Tennessee OELs: Skin designation

4-METHYLPENTAN-2-OL (CAS 108-11-2) Can be absorbed through the skin. **CUMENE (CAS 98-82-8)** Can be absorbed through the skin.

US NIOSH Pocket Guide to Chemical Hazards: Skin designation

4-METHYLPENTAN-2-OL (CAS 108-11-2) Can be absorbed through the skin. **CUMENE (CAS 98-82-8)** Can be absorbed through the skin.

US. OSHA Table Z-1 Limits for Air Contaminants (29 CFR 1910.1000)

4-METHYLPENTAN-2-OL (CAS 108-11-2) Can be absorbed through the skin. Can be absorbed through the skin. **CUMENE (CAS 98-82-8)**

Appropriate engineering

controls

Provide eyewash station and safety shower. Use adequate ventilation to control airborne concentrations below the exposure limits/guidelines. If user operations generate a vapor, dust and/or mist, use process enclosure, appropriate local exhaust ventilation, or other engineering controls to control airborne levels below the recommended exposure limits/guidelines.

Individual protection measures, such as personal protective equipment

Wear safety glasses with side shields (or goggles). Eye/face protection

Skin protection

Hand protection Suitable chemical protective gloves should be worn when the potential exists for skin exposure.

The choice of an appropriate glove does not only depend on its material but also on other quality features and is different from one producer to the other. Use protective gloves made of: Polyvinyl

chloride (PVC). Neoprene.

Other Wear appropriate chemical resistant clothing if applicable.

Respiratory protection If engineering controls do not maintain airborne concentrations to a level which is adequate to

protect worker health, an approved respirator must be worn. Respirator selection, use and maintenance should be in accordance with the requirements of OSHA Respiratory Protection

Standard 29 CFR 1910.134 and/or Canadian Standard CSA Z94.4.

Thermal hazards Wear appropriate thermal protective clothing, when necessary.

General hygiene considerations

Issue Date: 04-17-2024

Observe any medical surveillance requirements. When using do not smoke. Always observe good personal hygiene measures, such as washing after handling the material and before eating, drinking, and/or smoking. Routinely wash work clothing and protective equipment to remove

contaminants.

9. Physical and chemical properties

Appearance

Liquid. Physical state Aerosol. **Form** Color Not available. Odor Not available. **Odor threshold** Not available.

Hq 8.6

FIR No.: 045361 SDS US Version: 01