

SAFETY DATA SHEET

590 S. Paddock Pontiac MI 48341

Ph: 248-333-1333 Fax: 248-333-1426

SECTION 4: FIRST AID MEASURES

EYES: Flush with copious amounts of water for several minutes. If irritation persists, continue with water application. If after 15 minutes, irritation continues, seek medical attention.

SKIN: Promptly wash skin with mild soap and water.

INGESTION: Induce vomiting under the direction of qualified medical personnel. Seek qualified medical attention. Small amounts, which may enter the mouth incidental to handling, may be rinsed out with water.

INHALATION: Remove to fresh air. In severe cases of overexposure, such as with a fire, administer oxygen and seek qualified medical attention.

NOTES TO PHYSICIANS OR FIRST AID PROVIDERS: Treat symptoms as required. Product contains petroleum oils.

SECTION 5: FIRE-FIGHTING MEASURES

FLASH POINT:

F: >425°F, Cleveland Open Cup

AUTOIGNITION TEMPERATURE:

F: Not Determined

NFPA HAZARD CLASSIFICATION

HEALTH: 1 FLAMMABILITY: 1 REACTIVITY: 0 OTHER: None

HMIS HAZARD CLASSIFICATION

HEALTH: 1 FLAMMABILITY: 1 REACTIVITY: 0

EXTINGUISHING MEDIA: Foam, Carbon Dioxide, Dry Chemical, Water Fog

SPECIAL FIRE FIGHTING PROCEDURES: Water may spread the fire as oil can float on it. Water spray may be used to cool exposed containers.

UNUSUAL FIRE AND EXPLOSION HAZARDS: Water may spread the fire. Heated containers may rupture.

HAZARDOUS DECOMPOSITION PRODUCTS: Oxides of Carbon, Sulfur, Phosphorous and Zinc. Smoke, odorous and toxic fumes may form during incomplete combustion. High heat may also generate low levels of hydrogen sulfide and alkyl mercaptans.

SECTION 5 NOTES: Use of water for fire fighting must be done with caution as water may actually spread the fire.

SECTION 6: ACCIDENTAL RELEASE MEASURES

ACCIDENTAL RELEASE MEASURES: If hot and molten, prevent spread of material by use of sand or other diking material. Scoop up and store in recovery containers until proper disposal. Prevent spill from reaching any type of running or standing water, such as streams, sewers, well water and ponds.

SECTION 7: HANDLING AND STORAGE

HANDLING AND STORAGE: Store in a sheltered area, away from temperature extremes in labeled containers. Keep away from heat, sparks, or flame. Avoid contact with eyes, skin, clothing, and shoes.

OTHER PRECAUTIONS: When handling, have appropriate safety equipment for the working conditions including eyewash. Do not pressurize, cut, weld, braze, solder, drill, or grind containers containing product residues. Wash thoroughly with soap and water after handling.

SECTION 8: EXPOSURE CONTROLS/PERSONAL PROTECTION