6 ACCIDENTAL RELEASE MEASURES

Personal Precautions:

Observe precautions from other sections.

Methods for Cleaning up:

Ventilate the area with fresh air. Remove all ignition sources such as flames, smoking materials, and electrical spark sources. Use only non-sparking tools. Collect as much of the spilled material as possible using non-sparking tools. Clean up residue with water. Place in a suitable metal container.

7 HANDLING AND STORAGE

Precautions for Safe Storage:

Keep container closed when not in use.

Fire Prevention:

Ground containers securely when transferring contents. Wear low static or properly grounded shoes.

Explosion Prevention:

Flammable liquid and vapour. Keep away from heat, sparks, open flame, pilot lights and other sources of ignition.

Precautions for Safe Handling:

Keep container tightly closed.