## **US. NIOSH: Pocket Guide to Chemical Hazards**

Туре	Value	Form
TWA	3 fibers/cm3	Fiber.
,	3 fibers/cm3	Dust.
	5 mg/m3	Fiber, total
	5 mg/m3	fibers, total dust
Barium sulphate (CAS TWA 7727-43-7)	5 mg/m3	Respirable.
	10 mg/m3	Total
Cellulose (CAS 9004-34-6) TWA	5 mg/m3	Respirable.
	10 mg/m3	Total
TWA	2.5 mg/m3	Respirable.
	TWA TWA	TWA 3 fibers/cm3  3 fibers/cm3  5 mg/m3  5 mg/m3  TWA 5 mg/m3  TWA 5 mg/m3  TWA 5 mg/m3  TWA 5 mg/m3

**Biological limit values** 

No biological exposure limits noted for the ingredient(s).

Appropriate engineering controls

Use explosion-proof electrical equipment if airborne dust levels are high. Provide adequate ventilation. Observe Occupational Exposure Limits and minimize the risk of inhalation of dust.

## Individual protection measures, such as personal protective equipment

Eye/face protection Wear approved safety goggles.

Skin protection

Wear protective gloves (i.e. latex, nitrile). Suitable gloves can be recommended by the glove Hand protection

supplier.

Wear suitable protective clothing. Other

If engineering controls do not maintain airborne concentrations below recommended exposure Respiratory protection

limits (where applicable) or to an acceptable level (in countries where exposure limits have not been established), an approved respirator must be worn. During dust-raising work: In the United States of America, if respirators are used, a program should be instituted to assure compliance with OSHA Standard 1910.134. Respirator type: Any powered, air-purifying respirator with a

high-efficiency particulate filter.

Thermal hazards Wear appropriate thermal protective clothing, when necessary.

General hygiene Always observe good personal hygiene measures, such as washing after handling the material considerations

and before eating, drinking, and/or smoking. Routinely wash work clothing and protective

equipment to remove contaminants.

## 9. Physical and chemical properties

**Appearance** Solid (article).

Solid. **Physical state** 

**Form** Solid (Disc pad). Color White to light grey.

Odor None.

**Odor threshold** Not applicable. Not applicable. Melting point/freezing point Not applicable. Initial boiling point and boiling Not applicable.

range

Flash point Not applicable. **Evaporation rate** Not applicable. Not applicable. Flammability (solid, gas)

Upper/lower flammability or explosive limits

Flammability limit - lower Not applicable.

Flammability limit - upper

(%)

Not applicable.

Vapor pressure Not applicable. Vapor density Not applicable.